

STATE OF UTAH MSE WALL INSPECTION FORM

Compiled As Part of Research By The Utah Department of Transportation

Instructions:

1-Fill out required sections for MSE Wall Inspector and Wall Characteristics.

2-Inspect the wall using the attached form. Questions that require a 'Yes' answer should be documented by noting the extent of the problem in the right most column and photo documentation. Photo documentation should consist of wall or bridge number, nature of problem, date, photo number for wall, and a size reference, which should be indicated in the photo (white board/paper). Photos taken should be placed on the Top View layout and indicated with the appropriate number. Note should be taken by the inspector that often anomalies are due to construction and should be distinguished from those that are a result of post-construction. If it is observable that they existed at the time of construction note should be taken in the space provided for drawings.

3- Shoot digital photos of the entire wall. This may require the use of a variety of shots and angles on each wall to cover the wall in its entirety.


4- Indicate Layout of MSE Wall in respect to major intersections, roadways, potential hazards, irrigation, vegetation, locations of conditions for which 'Yes' was marked, etc. in space provided below. Also Indicate approximate GPS Coordinates of Site of Interest in space provided below

			I-15, 660 N, SLC
Region	2	Identifying Road/Intersection	

MSE WALL CHARACTERISTICS

MSE Wall at Bridge	<input checked="" type="checkbox"/> N	Bridge Number if applicable:		Wall Number	R-337-D	
Surrounding Structures				Maximum Height of Wall (ft)	18 ft	
Distance to Each Structure				One Stage, Two Stage or Block Wall	2-Stage	
State Route Number				Estimated Max Length of Wall Abutment:	50 ft	
Approximate Mile Marker				Max Slope of Ground in front of wall:	0	
GPS Datum	WGS/84, NAD/83, or NAD/27			Max Height of wall burial line above surrounding level ground:	10 ft	


NE

MSE Wall GPS Coordinates (Location of Measurement shown on plan view) 40°46'58.07"N 111°54'37.56"W	Please draw rough layout of panel with approximate dimensions in space provided below: 
If known, Panel or System Manufacturer	


Summary of Key Observations:

Coping separating and settling

Plan View/Drainage:



Cross Sections:



A-A'



Cross Sections:

BASE WALL DRAINAGE

Required Topic	Yes	No	Measurements/Extent of Problem/Location/Photo Numbers
1-Is there an active water source near the toe of the wall (i.e. the wall near a body of water with seepage potential)?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
2-If applicable, are the catch basins at the base of the wall blocked?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
3-Are there evidence protruding through the wall?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
4-Are there vertical drains that extend through the backfill?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
5-Is there evidence at the base of the wall or leveling pad? (Photo 12)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
6-Is there evidence along the edge wall?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
7-Are there any signs of water flow along the base of the wall?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
8-Is there less than 14 feet between irrigation sprinklers and wall?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
9-Does the backfill on joint fabric appear to be saturated?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
10-Is there vegetation growing in joint fabric? (Photo 13)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
11-Are the deck drains and outlets at the top of the wall blocked? (Photo 14)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
12-Can water enter the wall between coping and slab (i.e. Drains appropriately)?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
13-Is there evidence at discharge point of fill washing through drain pipes?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /

BASE WALL JOINTS

Required Topic	Yes	No	Measurements/Extent of Problem/Location/Photo Numbers
14-Is backfill resting on joint or are there piles of backfill at the base of the wall? (Photos 2 & 3)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
15-Are the joints wide enough to see fabric or backfill behind panels when looking down joints? (Photo 5) If yes, record the approximate maximum joint width in inches.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
16-Is exposed backfill visible in the horizontal joints? (Photo 4)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
17-Are there visible tears in the fabric? Is there evidence of backfill or water leaking through joints? (Do not include additional damage to fabric)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
18-Do the joints have a nonuniform horizontal spacing? Are some horizontal joints larger/smaller than others? (Photo 6)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
19-Do the joints have a nonuniform vertical spacing? Are some vertical joints larger/smaller than others? (Photo 6)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
20-Are the panels offset at the joints either in or out of the wall? (Photo 7) If yes, record the approximate maximum offset.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
21-Does the fabric appear brittle, or appear as if it has undergone excessive UV exposure?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /

BASE WALL FACING

Required Topic	Yes	No	Measurements/Extent of Problem/Location/Photo Numbers
22-Are there cracks that continue vertically through adjacent panels? (Photos 9 & 10) If yes, record the approximate number of panels in the wall with cracks.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
23-Are the panels meeting contact with each other? If yes, record the approximate number in the wall.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
24-Are the panels separated, "popped-out" or displaced from contact with an adjacent panel? If yes, record the number in the wall.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
25-Does crack spacing suggest Differential Settlement?	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
26-Does the existing coping exhibit vertical offset? If yes, it may be appropriate to conduct LTOOT if detachment occurs.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
27-Are the panels in danger of falling off? (If potential exists contact appropriate LTOOT region).	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
28-Is there any open cracks in the concrete coping (see building)? If yes, record maximum degree of flaring from adhesion using vertical level and affected area.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /

BASE TOP OF WALL OBSERVATIONS

Required Topic	Yes	No	Measurements/Extent of Problem/Location/Photo Numbers
29-Is there evidence of settlement at the top of the wall? (pavement cracking, etc)	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
30-Is there any open cracks in the concrete coping (see building)? If yes, record the approximate maximum crack width.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /
31-Is there evidence of cracking in the concrete coping opened up? (Photo 6) If yes, record the maximum joint width.	Y	N	0-N6 1% 5% 10% 25% 50% 75% 90% 95% 100% /

