

STATE OF UTAH MSE WALL INSPECTION FORM

Compiled As Part of Research By The Utah Department of Transportation

Instructions:

1-Fill out required sections for MSE Wall Inspector and Wall Characteristics.

2-Inspect the wall using the attached form. Questions that require a 'Yes' answer should be documented by noting the extent of the problem in the right most column and photo documentation. Photo documentation should consist of wall or bridge number, nature of problem, date, photo number for wall, and a size reference, which should be indicated in the photo (white board/paper). Photos taken should be placed on the Top View layout and indicated with the appropriate number. Note should be taken by the inspector that often anomalies are due to construction and should be distinguished from those that are a result of post-construction. If it is observable that they existed at the time of construction note should be taken in the space provided for drawings.

3- Shoot digital photos of the entire wall. This may require the use of a variety of shots and angles on each wall to cover the wall in its entirety.

4- Indicate Layout of MSE Wall in respect to major intersections, roadways, potential hazards, irrigation, vegetation, locations of conditions for which 'Yes' was marked, etc. in space provided below. Also Indicate approximate GPS Coordinates of Site of Interest in space provided below

Region	2	Identifying Road/Intersection	H-201 & 900 W
---------------	---	--------------------------------------	---------------

MSE WALL CHARACTERISTICS

MSE Wall at Bridge	(X) N	Bridge Number if applicable:		Wall Number	R-379-14
Surrounding Structures				Maximum Height of Wall (ft)	25 ft
Distance to Each Structure				One Stage, Two Stage or Block Wall	2 stage
State Route Number				Estimated Max Length of Wall Abutment:	330 ft
Approximate Mile Marker				Max Slope of Ground in front of wall:	1
GPS Datum	WGS/84, NAD/83, or NAD/27			Max Height of wall burial line above surrounding level ground:	18 ft
MSE Wall GPS Coordinates (Location of Measurement shown on plan view)	40°43'28.48"N 111°54'50.21"W			Please draw rough layout of panel with approximate dimensions in space provided below:	
If known, Panel or System Manufacturer	<div style="border: 1px solid black; width: 200px; height: 100px; margin: auto; position: relative;"> 5' 10' </div>				

Summary of Key Observations:

compression fractures in coping along joints and uneven settlement near toe. (east end)

Plan View/Drainage:



GPS
X B' B



pic 103
↓ ↓

pic 101/10
↓ ↓





step

pic 1 + 2
toping

3, 4
mopped
corners

Cross Sections:



Cross Sections:

BASE WALL DRAINAGE

Required Topic		Yes	No	NA	UKS	Measurements/Extent of Problem/Location/Photo Numbers
Drainage						
Y	1-Is there an active water source near the toe of the wall (in the wall near a body of water with seepage potential)?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	2-If applicable, are the cracks located at the base of the wall blocked?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	3-Are there culverts protruding through the wall?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	4-Are there vertical drains that travel through the backfill?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	5-Are there cracks at the base of the wall or leveling pads? (Photos 12)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	6-Is there erosion along the wing wall?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	7-Are there any signs of water flow along the base of the wall?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	8-Is there less than 14 feet between infiltration spindlers and wall?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	9-Does the backfill or joint fabric appear to be saturated?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	10-Is there vegetation growing in panel joints? (Photo 8)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	11-Are the deck, drain and outlets at the top of the wall blocked? (Photos 14)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	12-Can water enter the wall between coping and slab (i.e., drain appropriately)?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	13-Is there evidence at discharge point of fill washing through drain pipes?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

cannot access

BASE WALL JOINTS

Required Topic		Yes	No	NA	UKS	Measurements/Extent of Problem/Location/Photo Numbers
Long Level Slab, Concrete Cracks						
Y	14-Is backfill coming out of joints or are there piles of backfill at the base of the wall? (Pictures 2 & 3)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	15-Are the joints wide enough to see fabric or backfill behind panels when looking into joints? (Photo 5) If yes, record the approximate maximum joint width in inches.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	16-Is exposed backfill visible in the horizontal joint? (Photo 3)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	17-Is there additional backfill in the joint? (Photo 4) Is there evidence of backfill or water leaking through here? (Do not include additional backfill in the joint.)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	18-Do the joints have a nonuniform horizontal spacing? Are some horizontal joints larger than others? (Photo 6)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	19-Do the joints have a nonuniform vertical spacing? Are some vertical joints larger than others? (Photo 6)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	20-Are the panels tilted at the joints either in or out of the wall? (Photo 7) If yes, record the approximate maximum tilt.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	21-Does the fabric appear brittle, or appear as if it has undergone excessive UV exposure?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

LH

BASE WALL FACING

Required Topic		Yes	No	NA	UKS	Measurements/Extent of Problem/Location/Photo Numbers
Long Level Slab, Concrete Cracks						
Y	22-Are the panels "tilty"? Is there excessive cracking in the panels?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	23-Are there cracks that continue vertically through adjacent panels (Photos 9 & 10)? If yes, record the approximate number of panels in the wall with cracking.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	24-Are there cracks that continue horizontally through adjacent panels (Photos 9 & 10)? If yes, record the approximate number of panels in the wall with cracking.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	25-Are the panel corners cracking contact with each other? If yes, record the approximate number in the wall.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	26-Are the panel corners "popped-off" or clipped from contact with an adjacent panel? If yes, record the number in the wall.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	27-Does crack spacing suggest Differential Settlement?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	28-Does the overlying coping exhibit Vertical Offset?					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	29-Are the coping and parapet loose or detaching? If yes, it may be appropriate to contact LDOT if detachment occurs en masse.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	30-Are the panels in danger of falling off (if potential exists contact appropriate LDOT region).					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	31-Are the panels bulging (bowing horizontally)? If so, record maximum deformation from accessible coping to leveling pad. (Photo 11)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	32-Is there tipping at the top or bottom of the wall? (Record maximum degree of tipping from vertical leveling pad. (Photo 11))					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

BASE TOP OF WALL OBSERVATIONS

Required Topic		Yes	No	NA	UKS	Measurements/Extent of Problem/Location/Photo Numbers
Top of Wall						
Y	33-Is there evidence of settlement at the top of the wall? (Government cracking, etc.)					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	34-Are there any open cracks in the concrete coping (not balling)? If yes, record the approximate maximum crack width.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	35-Does the construction joint in the concrete coping appear open? (Photo 6). If yes, record the maximum joint width.					0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

Y	N/A	UKN	36-Is there a large gap between the approach slab and the approach pavement? (Photo 15) Or thin slab	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N/A	UKN	37-Is the joint between the wall and the approach pavement? (Photo 16) Or thin slab	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N/A	UKN	38-Is the coping wall pulling away from pavement (loadway) section? Please record maximum displacement for wall.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/

NISE STABILITY

Required Tests:		SIS/UL/GEOPROBE		Measurement/Extent of Problem/Location/Photo Numbers												
Yes	No	N/A	UKN													
Y	N/A	UKN	39-What is the location depth of leveling pad? Found Geo-Probe into soil located 2 inches from wall to a maximum depth of 24 inches (24 inches is the minimum depth for NISE Wall)	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	40-Is leveling pad exposed?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	41-Is there cracking in the leveling pad? If so, record maximum crack size with gauge.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	42-Is there a four foot break (level slope) directly along the wall before the slope changes (Round Width)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	43-Is there a slope steeper than V:1.5 to H:1 in front of the wall? Please record slope and height of backfill above top of wall.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	44-Is there a slope greater than V:1.5 to H:1 below the wall? Please record slope and height of backfill below the wall.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	45-Is there excessive degradation of panel face?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	

NISE METAL CORROSION

Required Tests:		NISE/UL/GEOPROBE		Measurement/Extent of Problem/Location/Photo Numbers												
Yes	No	N/A	UKN													
Y	N/A	UKN	46-Is there excessive corrosion on groundnut or other exposed metal that might indicate corrosive conditions?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	47-Are there major rust stains on the face panel? Along joints? If so, record total number.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	48-Are any internal straps exposed? Does there appear to be corrosion on these straps? If applicable please record the total number of straps affected.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	49-Was a rebar survey taken of exposed wall? If so, please indicate depth in inches.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	50-Is there any indication of other corrosion (scaling bars, rust, exposed metal inside epoxy coating)? If so please record the total number of panels affected.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	

NISE IMPACT/COLLISION PROTECTION

Required Tests:		Concrete/GRS		Measurement/Extent of Problem/Location/Photo Numbers												
Yes	No	N/A	UKN													
Y	N/A	UKN	51-Are guardrails/wall protrusions in place at the base of the wall (to protect it from potential traffic loads)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	52-Does it appear that the wall has been involved in an incident (replaced panel, recent dips in the wall)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	53-Does it appear the wall's functionality and integrity has been compromised by a collision or accident?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	

NISE OBSTRUCTIONS IN REINFORCEMENT GEOMETRY

Required Tests:		Drawings		Measurement/Extent of Problem/Location/Photo Numbers												
Yes	No	N/A	UKN													
Y	N/A	UKN	54-Are there acute wall angles (<90)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	

NISE AS BUILT DIFFERENT FROM DESIGN

Required Tests:		Drawings/Concrete/GRS		Measurement/Extent of Problem/Location/Photo Numbers												
Yes	No	N/A	UKN													
Y	N/A	UKN	55-Are there available drawings for the wall? Please indicate type (Situation and Layout, Design, As Built, etc.)	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	56-Is the layout in general accordance with drawings?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	57-Are the panels CIP (Cast in Place) Does there appear to be excessive cracking in the panels?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	58-Was GEO/Fabric used in the construction of the wall?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	59-Are there any structures on or near wall that were not included in initial drawing?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	60-Are there any irrigation, utilities, or obstructions that are not part of the initial drawing?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	61-Have there been any excavations or evidence of excavation near the wall?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	62-Have local property owners changed the dynamics of the wall (additional structures, irrigation, vegetation, etc.)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	
Y	N/A	UKN	63-Are there piles located in the wall (bridge abutment)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/	