

STATE OF UTAH MSE WALL INSPECTION FORM

Compiled As Part of Research By The Utah Department of Transportation

Instructions:

- 1- Fill out required sections for MSE Wall Inspector and Wall Characteristics.
- 2- Inspect the wall using the attached form. Questions that require a 'Yes' answer should be documented by noting the extent of the problem in the right most column and photo documentation. Photo documentation should consist of wall or bridge number, nature of problem, date, photo number for wall, and a size reference, which should be indicated in the photo (white board/paper). Photos taken should be placed on the Top View layout and indicated with the appropriate number. Note should be taken by the inspector that often anomalies are due to construction and should be distinguished from those that are a result of post-construction. If it is observable that they existed at the time of construction note should be taken in the space provided for drawings.
- 3- Shoot digital photos of the entire wall. This may require the use of a variety of shots and angles on each wall to cover the wall in its entirety.
- 4- Indicate Layout of MSE Wall in respect to major intersections, roadways, potential hazards, irrigation, vegetation, locations of conditions for which 'Yes' was marked, etc. in space provided below. Also Indicate approximate GPS Coordinates of Site of Interest in space provided below


Region	3	Identifying Road/Intersection	I-15 & Mt. Park East
---------------	---	--------------------------------------	----------------------

MSE WALL CHARACTERISTICS

MSE Wall at Bridge	(Y) N	Bridge Number if applicable:		Wall Number	R-367B
Surrounding Structures				Maximum Height of Wall (ft)	20 FT
Distance to Each Structure				One Stage, Two Stage or Block Wall	One stage
State Route Number				Estimated Max Length of Wall Abutment:	465 FT
Approximate Mile Marker				Max Slope of Ground in front of wall:	2:1
GPS Datum	WGS/84, NAD/83, or NAD/27			Max Height of wall burial line above surrounding level ground:	
MSE Wall GPS Coordinates (Location of Measurement shown on plan view)	40° 16' 33.93" N 110° 43' 7.65" W			Please draw rough layout of panel with approximate dimensions in space provided below:	
If known, Panel or System Manufacturer					


Summary of Key Observations:

Plan View/Drainage:



499
245
441
465

Cross Sections:



Cross Sections:



MISE WALL DRAINAGE

Required tests:		System Under Test: Bitrite-CPS-Cases		Measurement/Extent of Problem/Location/Photo Numbers	
Yes	N/A	UKSN	Drainage	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	14-Is there an active water source near the toe of the wall (to the wall near a body of water with snow potential)?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	UKSN	24-If applicable, are the catch basins at the base of the wall blocked?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	3-Are there columns protruding through the wall?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	4-Are there vertical drains that travel through the backfill?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	5-Is there erosion at the base of the wall or leveling pad? (Photo 12)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	6-Is there erosion along the wing wall?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	7-Are there any signs of water flow along the base of the wall?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	8-Is there less than 14 feet between infiltration specklers and wall?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	9-Does the backfill or joint fabric appear to be saturated?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	10-Is there vegetation growing in panel joints (Photo 9)?	Blocked	Partial / 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	11-Are the deck drains and collars at the top of the wall blocked? (Photo 14)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	12-Can water enter the wall between coping and slab (i.e., drain appropriately)?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	13-Is there evidence at the base of the wall of water seeping through the drainage pipe?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

MISE WALL JOINTS

Required tests:		Long Level String GPS Current Crack Gauge		Measurement/Extent of Problem/Location/Photo Numbers	
Yes	N/A	UKSN	Joint	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	14-Is backfill coming out of joint or are there piles of backfill at the base of the wall? (Photos 2 & 3)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	15-Are the joints wide enough to see fabric or backfill behind panels when looking into joints? (Photo 5) If not, are there any signs of water seeping through joints?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	16-Is there backfill visible in the horizontal joints? (Photo 4)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	17-Are there visible signs of fabric? Is there evidence of backfill or water leaking through base? (Do not induce additional damage to fabric)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	18-Do the joints have a non-uniform horizontal spacing? Are some horizontal joints larger/smaller than others? (Photo 6)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	19-Do the joints have a non-uniform vertical spacing? Are some vertical joints larger/smaller than others? (Photo 6)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	20-Are the panels offset at the joints either in or out of the wall? (Photo 7) If yes, record the approximate maximum offset.	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	21-Does the fabric appear brittle, or appear as if it has undergone excessive UV exposure?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

MISE WALL FACING

Required tests:		Long Level String GPS Current Crack Gauge		Measurement/Extent of Problem/Location/Photo Numbers	
Yes	N/A	UKSN	Wall Facing	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	22-Are the panels "Tilt-Up"? Is there excessive cracking in the panel?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	23-Are there cracks that continue vertically through adjacent panels (Photos 8 & 10)? If yes, record the approximate number of panels in the wall with cracking.	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	24-Are there cracks that continue horizontally through adjacent panels (Photos 9 & 10)? If yes, record the approximate number of panels in the wall with cracking.	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	25-Are the panel corners cracking contact with each other? If yes, record the approximate number in the wall.	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	26-Are the panel corners "popped-off" or chipped from contact with an adjacent panel? If yes, record the number in the wall.	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	27-Does crack spacing suggest Differential Settlement?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	28-Does the overlying coping exhibit Vertical Offset?	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	29-Are the coping and parapets loose or detaching? If yes, it may be appropriate to contact LDOT if detachment were evident.	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	30-Are the panels in danger of falling off? (If potential exist contact appropriate LDOT region).	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	31-Are the panels bulging (bowing horizontally)? If so, record maximum deformation from accessible location to existing panel (Photo 11)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	32-Are the top corners of the wall (Record maximum degree of dipping from straight using vertical level not affected area)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

MISE TOP OF WALL OBSERVATIONS

Required tests:		Long Level Crack Gauge GPS Current		Measurement/Extent of Problem/Location/Photo Numbers	
Yes	N/A	UKSN	Top Of Wall	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	33-Is there evidence of settlement at the top of the wall? (ground cracking, etc)	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	34-Are there any open cracks in the concrete coping (not hairline)? If yes, record the approximate maximum crack width.	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UKSN	35-Is there the connection joints in the connecting coping opened up? (Photo 6). If yes, record the maximum joint width.	/	0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

Y	N/A	UNS	16-Is there a large gap between the approach slab and the approach pavement? (Photo 15) Often this produces a bumping sensation as the car enters the tunnel. Record the approximate maximum gap size.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UNS	17-At the abutments, has the joint between the wall coping and the abutment opened up significantly? If so record maximum distance.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UNS	18-Is the coping wall pulling away from pavement roadway section? Please record maximum displacement for wall.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

1/6

MISE STABILITY

Required Items: Special GED-Forms					
Yes	No	N/A	UNS	Measurement/Extent of Failure/Location/Photo Numbers	
Y	N	N/A	UNS	Structural Integrity	
Y	N	N/A	UNS	19-What is the location depth of leveling pad? Found One Probe hole wall located 2 inches from wall to a maximum depth of 24 inches (24 inches is the minimum depth for MSE Wall)	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	40-Is leveling pad exposed?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	41-Is there cracking in the leveling pad? If so, record maximum crack size with page.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	42-Is there a four foot 'bowl' (level slope) directly along the wall before the slope changes (Record backfill above top of wall.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	43-Is there a slope steeper than V:1.5 to H:1 in front of the wall? Please record slope and height of backfill above top of wall.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	44-Is there a slope greater than V:1.5 to H:1 below the wall? Please record slope and height of backfill below the wall.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	45-Is there excessive degradation of gravel fence?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

OTO Flat

MISE METAL CORROSION

Required Items: Nylon Nuts or Washers GFD-2 Zip Lock Bag Frowel					
Yes	No	N/A	UNS	Measurement/Extent of Failure/Location/Photo Numbers	
Y	N	N/A	UNS	Metal Corrosion	
Y	N	N/A	UNS	46-Is there excessive corrosion on guardrails or other exposed metal that might indicate corrosive conditions?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	47-Are there major rust stains on the face panels? Along joints? If so, record total number.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	48-Are any internal straps exposed? Does there appear to be corrosion on these straps? If applicable please record the total number of straps affected.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	49-Was a weldability sample taken if exposed wall? If so, please indicate depth in inches.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	50-Is there any indication of fiber corrosion (swelling, britt, rust, exposed metal inside epoxy coating)? If so please record the total number of panels affected.	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

MISE IMPACT/COLLISION PROTECTION

Required Items: Concrete					
Yes	No	N/A	UNS	Measurement/Extent of Failure/Location/Photo Numbers	
Y	N	N/A	UNS	Impact/Collision	
Y	N	N/A	UNS	51-Are guardrails wall protrusions in place at the base of the wall (to protect it from potential walls)?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	52-Does it appear that the wall has been involved in an accident (replaced panel, recent damage to the wall)?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	53-Does it appear that the wall's functionality and integrity has been compromised by a collision or accident?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

MISE OBSTRUCTIONS IN REINFORCEMENT GEOMETRY

Required Items: Drawings					
Yes	No	N/A	UNS	Measurement/Extent of Failure/Location/Photo Numbers	
Y	N	N/A	UNS	Obstructions in Reinforcement Geometry	
Y	N	N/A	UNS	54-Are there acute wall angles (<90°)?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /

MISE AS BUILT DIFFERENT FROM DESIGN

Required Items: Drawings + Concrete GFDs					
Yes	No	N/A	UNS	Measurement/Extent of Failure/Location/Photo Numbers	
Y	N	N/A	UNS	MISE as built different than design	
Y	N	N/A	UNS	55-Are there available drawings for the wall? Please indicate type (Situation and Layout, Design, As Built, etc.)	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	56-Is the layout in general accordance with drawings?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	57-Are the panels CIP (Cast in Place)? Does there appear to be excessive cracking in the panels?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	58-Was GFD Form used in the construction of the wall?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	59-Are there any structures on or near wall that were not included in initial drawings?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	60-Are there any irrigation, utilities, or foundation that are not part of the initial drawings?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	61-Have there been any excavations or evidence of excavation near the wall?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	62-Has local property owners changed the footprint of the wall (additional structures, irrigation, vegetation, etc.)?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N	N/A	UNS	63-Are there piles found in the wall (bridge abutment)?	/ 0-No 1% 5% 10% 25% 50% 75% 90% 95% 100% /