

STATE OF UTAH MSE WALL INSPECTION FORM

Compiled As Part of Research By The Utah Department of Transportation

Instructions:

- 1-Fill out required sections for MSE Wall Inspector and Wall Characteristics.
- 2-Inspect the wall using the attached form. Questions that require a 'Yes' answer should be documented by noting the extent of the problem in the right most column and photo documentation. Photo documentation should consist of wall or bridge number, nature of problem, date, photo number for wall, and a size reference, which should be indicated in the photo (white board/paper). Photos taken should be placed on the Top View layout and indicated with the appropriate number. Note should be taken by the inspector that often anomalies are due to construction and should be distinguished from those that are a result of post-construction. If it is observable that they existed at the time of construction note should be taken in the space provided for drawings.
- 3- Shoot digital photos of the entire wall. This may require the use of a variety of shots and angles on each wall to cover the wall in its entirety.
- 4- Indicate Layout of MSE Wall in respect to major intersections, roadways, potential hazards, irrigation, vegetation, locations of conditions for which 'Yes' was marked, etc. in space provided below. Also Indicate approximate GPS Coordinates of Site of Interest in space provided below

Region	4	Identifying Road/Intersection	Hwy 10 - North of Huntington
---------------	---	--------------------------------------	------------------------------

MSE WALL CHARACTERISTICS

MSE Wall at Bridge	Y <input checked="" type="checkbox"/> N <input type="checkbox"/>	Bridge Number if applicable:		Wall Number	R-407-A SE
Surrounding Structures				Maximum Height of Wall (ft)	13.5 ft
Distance to Each Structure				One Stage, Two Stage or Block Wall	Block
State Route Number				Estimated Max Length of Wall Abutment:	360 ft
Approximate Mile Marker				Max Slope of Ground in front of wall:	2:1
GPS Datum	WGS/84, NAD/83, or NAD/27			Max Height of wall burial line above surrounding level ground:	0
MSE Wall GPS Coordinates (Location of Measurement shown on plan view)	Please draw rough layout of panel with approximate dimensions in space provided below:				
If known, Panel or System Manufacturer	<div style="border: 1px solid black; width: 200px; height: 100px; margin: 0 auto; position: relative;"> 18" 8" </div>				

Summary of Key Observations:


Surface runoff may be a problem

4
 8
 120
 30
 12.5
 12150
 30




Plan View/Drainage:



↑
Hwy
10
↓



Cross Sections:



Cross Sections:

MISE WALL DRAINAGE

Required Tools: Nylon Angle-Wire Bead-Clips-Camera		Measurement/Extent of Problem/Location/Photo Numbers	
Yes	No	0-No	1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UNK	1-Is there any active water seepage near the toe of the wall (i.e. the wall water a body of water with scour potential)?
Y	N/A	UNK	2-If applicable, are the catch basins at the base of the wall blocked?
Y	N/A	UNK	3-Are there culverts protruding through the wall?
Y	N/A	UNK	4-Are there vertical drains that travel through the backfill?
Y	N/A	UNK	5-Is there erosion at the base of the wall or leveling post? (Photo 12)
Y	N/A	UNK	6-Is there erosion along the wing wall?
Y	N/A	UNK	7-Are there any signs of water flow along the base of the wall?
Y	N/A	UNK	8-Is there less than 14 feet between irrigation sprinklers and wall?
Y	N/A	UNK	9-Does the backfill or joint fabric appear to be saturated?
Y	N/A	UNK	10-Is there vegetation growing in panel joints (Photo 8)?
Y	N/A	UNK	11-Are the deck drains and outlets at the top of the wall blocked? (Photo 14)
Y	N/A	UNK	12-Can water enter the wall between coping and slab (i.e., Drain appropriately)?
Y	N/A	UNK	13-Is there evidence at discharge point of fill washing through drain pipe?

MISE WALL JOINTS

Required Tools: Long Level-String-Camera-GPS		Measurement/Extent of Problem/Location/Photo Numbers	
Yes	No	0-No	1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UNK	1-Is backfill coming out of joints or are there piles of backfill at the base of the wall? (Pictures 2 & 3)
Y	N/A	UNK	15-Are the joints wide enough to see fabric or backfill behind panels when looking into joints? (Photo 5) If yes, record the approximate maximum joint width in inches.
Y	N/A	UNK	16-Is exposed backfill visible in the horizontal joint? (Photo 4)
Y	N/A	UNK	17-Are there visible tears in the fabric? Is there evidence of backfill or water leaking through tear? (Do not induce additional damage to fabric)
Y	N/A	UNK	18-Do the joints have a non-uniform horizontal spacing/size? Are some horizontal joints larger/smaller than others? (Photo 6)
Y	N/A	UNK	19-Do the joints have a non-uniform vertical spacing/size? Are some vertical joints larger/smaller than others? (Photo 6)
Y	N/A	UNK	20-Are the panels offset at the joints either in or out of the wall? (Photo 7) If yes, record the approximate maximum offset.
Y	N/A	UNK	21-Does the fabric appear brittle, or appear as if it has undergone excessive UV exposure?

MISE WALL FACING

Required Tools: Long Level-String-GPS-Camera-CrACK Gauge		Measurement/Extent of Problem/Location/Photo Numbers	
Yes	No	0-No	1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UNK	1-Is there excessive cracking in the panels?
Y	N/A	UNK	2-Is there evidence of concrete delamination or spalling? (Photos 9 & 10) If yes, record the approximate number of panels in the wall with delamination or spalling.
Y	N/A	UNK	24-Are there cracks that continue horizontally through adjacent panels (Photos 9 & 10)? If yes, record the approximate number of panels in the wall with cracking.
Y	N/A	UNK	25-Are the panel corners meeting contact with each other? If yes, record the approximate number in the wall.
Y	N/A	UNK	26-Are the panel corners "jagged-off" or chipped from contact with an adjacent panel? If yes record the number in the wall.
Y	N/A	UNK	27-Does crack spacing suggest Differential Settlement?
Y	N/A	UNK	28-Does the overlying coping exhibit vertical offset?
Y	N/A	UNK	29-Are the coping and parapets loose or detaching? If yes, it may be appropriate to contact LUDOT if detachment seems eminent.
Y	N/A	UNK	30-Are the panels in danger of falling off? (If potential exist contact appropriate EDOT regions).
Y	N/A	UNK	31-Are the panels bulging (bowing horizontally)? If so, record maximum deformation from accessible area.
Y	N/A	UNK	32-Is there "bleeding" at the top or bottom of the wall? (Record maximum degree of bleeding from asphalt using vertical level and affected area).

MISE TOP OF WALL OBSERVATIONS

Required Tools: Long Level-CrACK Gauge-GPS-Camera		Measurement/Extent of Problem/Location/Photo Numbers	
Yes	No	0-No	1% 5% 10% 25% 50% 75% 90% 95% 100% /
Y	N/A	UNK	1-Is there evidence of settlement at the top of the wall? (prevent encasing, etc)
Y	N/A	UNK	14-Are there any open cracks in the concrete coping (see briefing)? If yes record the approximate maximum width.
Y	N/A	UNK	15-Are the construction joints in the concrete coping opened up? (Photo 6) If yes, record the maximum joint width.

Y	N	N/A	UNK	16-Is there a large gap between the approach slab and the approach pavement? (Photo 15) Or has the approach slab been damaged by the excavation or the excavation process? Record the distance and size of the damage.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	17-Are the abutments, but the joint between the wall coping and the abutment opened up significantly? If so record maximum distance.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	18-Is the coping wall pulling away from pavement/roadway section? Please record maximum displacement for wall.	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/

MISS STABILITY

Required Tests: None																	
Structural Integrity																	
Y	N	N/A	UNK	19-What is the location depth of leveling post? Found Concrete ties will located 2 inches from wall to a maximum depth of 24 inches (or inches to the maximum depth for MSE, Wall)	24"	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	40-Is leveling pad exposed?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	41-Is there cracking in the leveling pad? If so, record maximum crack size with gauge.		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	42-Is there a four foot bench (level slope) directly along the wall before the slope changes? (Record Width)	3'	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	43-Is there a slope steeper than V: 1.5 to H:1 in front of the wall? Please record slope and height of bench above top of wall.		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	44-Is there a slope greater than V: 1.5 to H:1 below the wall? Please record slope and height of backfill below the wall.		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	45-Is there excessive degradation of panel face?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/

MISS METAL CORROSION

Required Tests: None																	
Metal Corrosion																	
Y	N	N/A	UNK	46-Is there excessive corrosion on guardrails or other exposed metal that might indicate corrosive condition?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	47-Are there major rust stains on the face panels? Along joints? If so, record total number.		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	48-Are any internal straps exposed? Does there appear to be corrosion on these straps? If applicable please record the total number of straps affected.		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	49-Was a readily sample taken of exposed wall? If so, please indicate depth in inches.		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	50-Is there any indication of rebar corrosion (swelling bars, rust, exposed metal inside epoxy coating)? If so please record the total number of panels affected.		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/

MISS IMPACT/COLLISION PROTECTION

Required Tests: None																	
Impact/Collision																	
Y	N	N/A	UNK	51-Are guardrails wall protection in place at the base of the wall (to protect it from potential traffic barrels)?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	52-Does it appear that the wall has been involved in an accident (replaced panel, recent dips in the wall)?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	53-Does it appear the wall functionality and integrity has been compromised by a collision or accident?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/

MISS OBSTRUCTIONS IN REINFORCEMENT GEOMETRY

Required Tests: None																	
Obstructions in Reinforcement Geometry																	
Y	N	N/A	UNK	54-Are there cuts wall height (<90)?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/

MISS AS BUILT DIFFERENT FROM DESIGN

Required Tests: None																	
Drawing/Concrete/OPS																	
Y	N	N/A	UNK	55-Are there available drawings for the wall? Please indicate type (Situation and Layout, Design, As Built, etc.)		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	56-Is the layout in general accordance with drawings?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	57-Are the panels CIP (Cast in Place) Does there appear to be excessive cracking in the panels?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	58-Was GED foam used in the construction of the wall?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	59-Are there any structures on or near wall that were not included in initial drawing?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	60-Are there any irrigation, utilities, or intrusions that are not part of the initial drawing?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	61-Has there been any excavations or evidence of excavations near the wall?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	62-Have local property owners changed the dynamics of the wall (additional structures, irrigation, vegetation, etc.)?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/
Y	N	N/A	UNK	63-Are there piles located in the wall (bridge abutment)?		/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%	/