

SOUTH NAULS

STATE OF UTAH MSE WALL INSPECTION FORM

Compiled As Part of Research By The Utah Department of Transportation

Instructions:

- 1-Fill out required sections for MSE Wall Inspector and Wall Characteristics.
- 2-Inspect the wall using the attached form. Questions that require a 'Yes' answer should be documented by noting the extent of the problem in the right most column and photo documentation. Photo documentation should consist of wall or bridge number, nature of problem, date, photo number for wall, and a size reference, which should be indicated in the photo (white board/paper). Photos taken should be placed on the Top View layout and indicated with the appropriate number. Note should be taken by the inspector that often anomalies are due to construction and should be distinguished from those that are a result of post-construction. If it is observable that they existed at the time of construction note should be taken in the space provided for drawings.
- 3- Shoot digital photos of the entire wall. This may require the use of a variety of shots and angles on each wall to cover the wall in its entirety.
- 4- Indicate Layout of MSE Wall in respect to major intersections, roadways, potential hazards, irrigation, vegetation, locations of conditions for which 'Yes' was marked, etc. in space provided below. Also Indicate approximate GPS Coordinates of Site of Interest in space provided below

Inspector Information

Inspection Date	11/10/2007	Names Of Inspectors	RM & JL
Region	2	Identifying Road/Intersection	201 & BEAUMONT







MSE WALL CHARACTERISTICS

MSE Wall at Bridge	(Y) N	Bridge Number if applicable:	N/A	Wall Number	R-444
Surrounding Structures	NONE			Maximum Height of Wall (ft)	25'
Distance to Each Structure	N/A			One Stage, Two Stage or Block Wall	TWO
State Route Number	201			Estimated Max Length of Wall Abutment:	400'
Approximate Mile Marker	15.9			Max Slope of Ground in front of wall:	0 - TERRAISED LANDSCAPING
GPS Datum	WGS/84	NAD/83, or NAD/27		Max Height of wall burial line above surrounding level ground:	25'
MSE Wall GPS Coordinates (Location of Measurement shown on plan view)	N 40° 43.463		Please draw rough layout of panel with approximate dimensions in space provided below:		
	N 111° 56.304		<div style="border: 1px solid black; padding: 10px; text-align: center;"> </div>		
If known, Panel or System Manufacturer	VSL? HANSEN WORTH COMPANY				

Summary of Key Observations:

NEW WALL IN IMMACULATE CONDITION
 LANDSCAPING W/ TERRACES & VEGETATION

Plan View/Drainage:



TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH

SLOPE 1/2"

SLOPE 1/2"
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH OR ALL SLOPE BENCH

MAX HT 27'
LENGTH - 100'
MAX HT 25'
LENGTH 90'
BENCH OK
BENCH OK

TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH

Redwood Rd
SLOPE 1/2"
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH OR ALL SLOPE BENCH

SR-201
K
SLOPE 1/2"

MAX HT. 25'
LENGTH - 170'
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH OR ALL SLOPE BENCH

TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH

SLOPE 1/2"

SLOPE 1/2"
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH OR ALL SLOPE BENCH


MAX HT 27'
LENGTH - 100'
MAX HT 25'
LENGTH 90'
BENCH OK
BENCH OK

TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH

TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH
TERMINATED WITH SLOPE BENCH OR ALL SLOPE BENCH

Cross Sections:

A:A'



Cross Sections:

MSE METAL CORROSION

Required Tools:		Nylon Mallet-Camera-GPS-Zip Lock Bag-Trowel	Metal Corrosion	Measurement/Extent of Problem/Location/Photo Numbers										
Yes	No	N/A	UKN	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%
Y	N	N/A	UKN	46-Is there excessive corrosion on guardrails or other exposed metal that might indicate corrosive conditions?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	47-Are there major rust stains on the face panels? Along joints? If so, record total number.	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	48-Are any internal straps exposed? Does there appear to be corrosion on these straps? If applicable please record the total number of straps affected.	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	49- Was a resistivity sample taken of exposed soil? If so, please indicate depth in inches.	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	50-Is there any indication of rebar corrosion (swelling bars, rust, exposed metal inside epoxy coating)? If so please record the total number of panels affected.	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%

MSE IMPACT/COLLISION PROTECTION

Required Tools:		Camera-GPS	Impact/Collision	Measurement/Extent of Problem/Location/Photo Numbers										
Yes	No	N/A	UKN	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%	100%
Y	N	N/A	UKN	51-Are guardrail/wall protections in place at the base of the wall (to protect it from potential traffic hazards)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	95%
Y	N	N/A	UKN	52-Does it appear that the wall has been involved in an accident (replaced panel, recent dings in the wall)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	53-Does it appear the wall's functionality and integrity has been compromised by a collision or accident?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%

MSE OBSTRUCTIONS IN REINFORCEMENT GEOMETRY

Required Tools:		Drawings	Obstructions in Reinforcement Geometry	Measurement/Extent of Problem/Location/Photo Numbers										
Yes	No	N/A	UKN	/	0-No	1%	5%	10%	25%	50%	75%	90% <th>95% <th>100%</th> </th>	95% <th>100%</th>	100%
Y	N	N/A	UKN	54-Are there acute wall angles (<90)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%

MSE AS BUILT DIFFERENT FROM DESIGN

Required Tools:		Drawings-Camera-GPS	MSE as built different than design	Measurement/Extent of Problem/Location/Photo Numbers										
Yes	No	N/A	UKN	/	0-No	1%	5%	10%	25%	50%	75%	90% <th>95% <th>100%</th> </th>	95% <th>100%</th>	100%
Y	N	N/A	UKN	55-Are there available drawings for the wall? Please indicate type (Situation and Layout, Design, As Built, etc.)	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	56-Is the layout in general accordance with drawings?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	57-Are the panels CIP (Cast in Place) Does there appear to be excessive cracking in the panels?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	58-Was GEOFoam used in the construction of the wall?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	59-Are there any structures on or near wall that were not included in initial drawings?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	60-Are there any irrigation, utilities, or intrusions that are not part of the initial drawings?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	61-Have there been any excavations or evidence of excavations near the wall?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	62-Have local property owners changed the dynamics of the wall (additional structures, irrigation, vegetation, etc.)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%
Y	N	N/A	UKN	63-Are there piles located in the wall (bridge abutment)?	/	0-No	1%	5%	10%	25%	50%	75%	90%	100%

DAVIN SOBON
WE DON'T HAVE INITIAL AB