

STATE OF UTAH MSE WALL INSPECTION FORM

Compiled As Part of Research By The Utah Department of Transportation

Instructions:


- 1- Fill out required sections for MSE Wall Inspector and Wall Characteristics.
- 2- Inspect the wall using the attached form. Questions that require a 'Yes' answer should be documented by noting the extent of the problem in the right most column and photo documentation. Photo documentation should consist of wall or bridge number, nature of problem, date, photo number for wall, and a size reference, which should be indicated in the photo (white board/paper). Photos taken should be placed on the Top View layout and indicated with the appropriate number. Note should be taken by the inspector that often anomalies are due to construction and should be distinguished from those that are a result of post-construction. If it is observable that they existed at the time of construction note should be taken in the space provided for drawings.
- 3- Shoot digital photos of the entire wall. This may require the use of a variety of shots and angles on each wall to cover the wall in its entirety.
- 4- Indicate Layout of MSE Wall in respect to major intersections, roadways, potential hazards, irrigation, vegetation, locations of conditions for which 'Yes' was marked, etc. in space provided below. Also Indicate approximate GPS Coordinates of Site of Interest in space provided below

Inspector Information

Inspection Date	7/25/07	Names Of Inspectors	Ryan Maw, Holly Griffin
Region	1	Identifying Road/Intersection	SR-91

MSE WALL CHARACTERISTICS

MSE Wall at Bridge	Y <input checked="" type="radio"/> N	Bridge Number if applicable:	N/A	Wall Number	R-281
Surrounding Structures	N/A		Maximum Height of Wall (ft)	30'	
Distance to Each Structure	N/A		One Stage, Two Stage or Block Wall	one stage	
State Route Number	SR 91/89		Estimated Max Length of Wall Abutment:	110 paces x 2.17 ft	
Approximate Mile Marker	6		Max Slope of Ground in front of wall:	22" x 3'	
GPS Datum	WGS/84, NAD/83, or NAD/27		Max Height of wall burial line above surrounding level ground:	30'	
MSE Wall GPS Coordinates (Location of Measurement shown on plan view)	N 41° 29.827		Please draw rough layout of panel with approximate dimensions in space provided below:		
	W 111° 57.426				
If known, Panel or System Manufacturer	VSL		8x64		



Summary of Key Observations:

creek eroding wall
 creek in contact w/wall
 bowing present in center of wall
 leaking observed - likely due to blocked drain

Plan View/Drainage:





photo #6

photo #3

total wall : 63 + 47 paces
 @ 2.17 paces

Jersey Barrier

Cross Sections:



Cross Sections:

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

REQUIRED TESTS		TEST RESULTS							
Yes	No	N/A	UEN						
1	2	3	4	5	6	7	8	9	10

NEE WALL DRAINAGE

MEASUREMENTS LIST OF PROBABLY DEFECTIVE WALLS

Photo	Location	Area	Defect Type	Severity	Notes
PHOTO 6	Box EUBOR GREEN	10' x 10'	Crack	Medium	Crack in concrete
PHOTO 3	Box EUBOR GREEN	10' x 10'	Crack	Medium	Crack in concrete
PHOTO 6	Box EUBOR GREEN	10' x 10'	Crack	Medium	Crack in concrete

NEE WALL JOINTS

MEASUREMENTS LIST OF PROBABLY DEFECTIVE WALL JOINTS

Photo	Location	Area	Defect Type	Severity	Notes
PHOTO 1	Box EUBOR GREEN	10' x 10'	Joint	Medium	Joint between panels
PHOTO 2	Box EUBOR GREEN	10' x 10'	Joint	Medium	Joint between panels
PHOTO 3	Box EUBOR GREEN	10' x 10'	Joint	Medium	Joint between panels

NEE WALL FACING

MEASUREMENTS LIST OF PROBABLY DEFECTIVE WALL FACINGS

Photo	Location	Area	Defect Type	Severity	Notes
PHOTO 4	Box EUBOR GREEN	10' x 10'	Facing	Medium	Defective facing
PHOTO 5	Box EUBOR GREEN	10' x 10'	Facing	Medium	Defective facing
PHOTO 6	Box EUBOR GREEN	10' x 10'	Facing	Medium	Defective facing

TOP OF WALL

MEASUREMENTS LIST OF PROBABLY DEFECTIVE WALL TOPS

Photo	Location	Area	Defect Type	Severity	Notes
PHOTO 7	Box EUBOR GREEN	10' x 10'	Top	Medium	Defective top
PHOTO 8	Box EUBOR GREEN	10' x 10'	Top	Medium	Defective top
PHOTO 9	Box EUBOR GREEN	10' x 10'	Top	Medium	Defective top

TOP OF WALL OBSERVATIONS

Photo	Location	Area	Defect Type	Severity	Notes
PHOTO 10	Box EUBOR GREEN	10' x 10'	Top	Medium	Defective top
PHOTO 11	Box EUBOR GREEN	10' x 10'	Top	Medium	Defective top
PHOTO 12	Box EUBOR GREEN	10' x 10'	Top	Medium	Defective top

