

SafetyAnalyst

**Accident Summary for Route SR S0000101A_,
Milepost 9.24 (Intersection 1007)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary 1

 1.1 Accident Case Identifier 1

 1.2 Accident Month 1

 1.3 Accident Severity Level 1 2

 1.4 Accident Time of Day 3

 1.5 Accident Type and Manner of Collision 4

 1.6 Alcohol/Drug Involvement 5

 1.7 Bicycle Indicator 5

 1.8 Contributing Circumstances, Environment 6

 1.9 Contributing Circumstances, Road 6

 1.10 Day of Week 7

 1.11 Divided Highway Flag-Side of Road 8

 1.12 Driver Age 8

 1.13 Driveway Indicator 9

 1.14 First Harmful Event 10

 1.15 Initial Direction of Travel 10

 1.16 Light Condition 11

 1.17 Number of Vehicles Involved 12

 1.18 Pedestrian Indicator 12

 1.19 Relationship to Junction 13

 1.20 Roadway Surface Condition 14

 1.21 Run-Off Road Indicator 14

 1.22 School Bus Related 15

 1.23 Tow-Away Indicator 16

 1.24 Vehicle Configuration 16

 1.25 Vehicle Maneuver/Action 17

 1.26 Vehicle Turning Movement 18

 1.27 Weather Condition 19

 1.28 Work Zone Related 19

2. Route SR S0000101A_, Milepost 9.24 21

3. Accident Case Details 24

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	3
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	4
Table 8. Accident Type and Manner of Collision	4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	5
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	5
Table 12. Bicycle Indicator	5
Table 13. Bicycle Indicator (Accident Case Identifier)	6
Table 14. Contributing Circumstances, Environment	6
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	6
Table 16. Contributing Circumstances, Road	7
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	7
Table 18. Day of Week	7
Table 19. Day of Week (Accident Case Identifier)	8
Table 20. Divided Highway Flag-Side of Road	8
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	8
Table 22. Driver Age in Years	9
Table 23. Driver Age in Years (Accident Case Identifier)	9
Table 24. Driveway Indicator	9
Table 25. Driveway Indicator (Accident Case Identifier)	10
Table 26. First Harmful Event	10
Table 27. First Harmful Event (Accident Case Identifier)	10
Table 28. Initial Direction of Travel	11
Table 29. Initial Direction of Travel (Accident Case Identifier)	11
Table 30. Light Condition	11
Table 31. Light Condition (Accident Case Identifier)	12
Table 32. Number of Vehicles Involved	12
Table 33. Number of Vehicles Involved (Accident Case Identifier)	12
Table 34. Pedestrian Indicator	13
Table 35. Pedestrian Indicator (Accident Case Identifier)	13
Table 36. Relationship to Junction	13
Table 37. Relationship to Junction (Accident Case Identifier)	14
Table 38. Roadway Surface Condition	14

Table 39. Roadway Surface Condition (Accident Case Identifier)	14
Table 40. Run-Off Road Indicator	15
Table 41. Run-Off Road Indicator (Accident Case Identifier)	15
Table 42. School Bus Related	15
Table 43. School Bus Related (Accident Case Identifier)	15
Table 44. Tow-Away Indicator	16
Table 45. Tow-Away Indicator (Accident Case Identifier)	16
Table 46. Vehicle Configuration	16
Table 47. Vehicle Configuration (Accident Case Identifier)	17
Table 48. Vehicle Maneuver/Action	17
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	18
Table 50. Vehicle Turning Movement	18
Table 51. Vehicle Turning Movement (Accident Case Identifier)	19
Table 52. Weather Condition	19
Table 53. Weather Condition (Accident Case Identifier)	19
Table 54. Work Zone Related	20
Table 55. Work Zone Related (Accident Case Identifier)	20
Table 56. Route SR S0000101A_, Milepost 9.24 Major Road Annual Traffic	22
Table 57. Route SR S0000101A_, Milepost 9.24 Minor Road Annual Traffic	22
Table 58. Accident 05004134 Vehicle-Level Accident Data	25
Table 59. Accident 03007032 Vehicle-Level Accident Data	26
Table 60. Accident 08003947 Vehicle-Level Accident Data	27
Table 61. Accident 06014205 Vehicle-Level Accident Data	28
Table 62. Accident 09023363 Vehicle-Level Accident Data	29
Table 63. Accident 05007561 Vehicle-Level Accident Data	30
Table 64. Accident 07010977 Vehicle-Level Accident Data	31
Table 65. Accident 03033432 Vehicle-Level Accident Data	32
Table 66. Accident 09025398 Vehicle-Level Accident Data	33
Table 67. Accident 08018116 Vehicle-Level Accident Data	34
Table 68. Accident 06024666 Vehicle-Level Accident Data	35
Table 69. Accident 05026377 Vehicle-Level Accident Data	36
Table 70. Accident 08012349 Vehicle-Level Accident Data	38
Table 71. Accident 09005116 Vehicle-Level Accident Data	39
Table 72. Accident 04027518 Vehicle-Level Accident Data	40
Table 73. Accident 04015473 Vehicle-Level Accident Data	41
Table 74. Accident 07008598 Vehicle-Level Accident Data	42

1. Accident Summary

This is a summary of the accident data associated with the following Intersection from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 9.24 (Intersection 1007)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **17 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2003	03007032, 03033432
2004	04027518, 04015473
2005	05004134, 05007561, 05026377
2006	06014205, 06024666
2007	07010977, 07008598
2008	08003947, 08018116, 08012349
2009	09023363, 09025398, 09005116

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
January	0	0	0	1	0	0	1	0	2	12	8
February	0	1	0	0	0	0	0	1	2	12	7
March	0	0	0	1	0	1	0	0	2	12	7
April	0	0	0	0	0	1	0	0	1	6	8
May	0	0	0	0	0	0	1	0	1	6	8
June	0	0	1	0	1	0	0	0	2	12	9
July	0	0	0	0	0	0	1	0	1	6	9
September	0	0	1	1	0	0	0	1	3	18	8
October	0	1	0	0	1	0	0	1	3	18	9
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
January	05004134, 08003947
February	03007032, 09005116
March	05007561, 07008598
April	07010977
May	08012349
June	06014205, 04015473
July	08018116
September	09023363, 05026377, 04027518
October	03033432, 09025398, 06024666

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	0	1	0	2	1	0	0	2	6	35	N/A
Possible Injury	0	1	2	1	0	0	0	0	4	24	N/A
Property-Damage-Only	0	0	0	0	1	2	3	1	7	41	N/A
Total Accidents	0	2	2	3	2	2	3	3	17	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	06014205, 09023363, 05007561, 03033432, 09025398, 05026377
Possible Injury	05004134, 03007032, 04027518, 04015473
Property-Damage-Only	08003947, 07010977, 08018116, 06024666, 08012349, 09005116, 07008598

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
5:00 am to 5:59 am	0	0	0	0	0	1	0	0	1	6	N/A
6:00 am to 6:59 am	0	0	0	0	0	0	0	1	1	6	N/A
7:00 am to 7:59 am	0	0	0	1	0	0	0	0	1	6	N/A
9:00 am to 9:59 am	0	0	0	0	1	0	0	0	1	6	N/A
11:00 am to 11:59 am	0	0	1	0	0	0	0	0	1	6	N/A
12:00 pm to 12:59 pm	0	0	0	1	0	0	1	0	2	12	N/A
1:00 pm to 1:59 pm	0	0	0	0	0	0	1	0	1	6	N/A
2:00 pm to 2:59 pm	0	0	0	0	0	0	1	0	1	6	N/A
3:00 pm to 3:59 pm	0	0	0	1	0	0	0	1	2	12	N/A
4:00 pm to 4:59 pm	0	1	0	0	1	1	0	0	3	18	N/A
5:00 pm to 5:59 pm	0	1	0	0	0	0	0	0	1	6	N/A
6:00 pm to 6:59 pm	0	0	0	0	0	0	0	1	1	6	N/A
8:00 pm to 8:59 pm	0	0	1	0	0	0	0	0	1	6	N/A
Total Accidents	0	2	2	3	2	2	3	3	17	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
5:00 am to 5:59 am	07010977
6:00 am to 6:59 am	09005116
7:00 am to 7:59 am	05007561
9:00 am to 9:59 am	06014205
11:00 am to 11:59 am	04027518
12:00 pm to 12:59 pm	05004134, 08012349
1:00 pm to 1:59 pm	08018116
2:00 pm to 2:59 pm	08003947
3:00 pm to 3:59 pm	09023363,05026377
4:00 pm to 4:59 pm	03007032,06024666,07008598
5:00 pm to 5:59 pm	03033432
6:00 pm to 6:59 pm	09025398
8:00 pm to 8:59 pm	04015473

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Rear-end	0	0	2	0	0	0	0	0	2	12	16
Angle	0	1	0	0	0	0	0	0	1	6	11
Other multiple-vehicle collision	0	1	0	3	2	2	3	3	14	82	65
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Rear-end	04027518, 04015473
Angle	03033432
Other multiple-vehicle collision	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 07008598

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	0	2	2	3	2	2	3	3	17	100	98
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	2	2	3	2	2	3	3	17	100	99
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	0	2	2	2	1	2	3	3	15	88	73
Weather conditions	0	0	0	0	1	0	0	0	1	6	15
Glare	0	0	0	1	0	0	0	0	1	6	2
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	05004134, 03007032, 08003947, 06014205, 09023363, 07010977, 03033432, 09025398, 08018116, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598
Weather conditions	06024666
Glare	05007561

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	0	2	2	3	2	2	3	3	17	100	95
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Monday	0	0	0	0	0	0	1	0	1	6	15
Tuesday	0	1	0	0	1	0	1	1	4	24	15
Wednesday	0	0	1	0	1	0	1	1	4	24	14
Thursday	0	1	0	0	0	1	0	0	2	12	16
Friday	0	0	0	1	0	0	0	0	1	6	19
Saturday	0	0	1	2	0	1	0	1	5	29	13
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Monday	08018116
Tuesday	08003947, 03033432, 09025398, 06024666
Wednesday	06014205, 08012349, 09005116, 04027518
Thursday	03007032, 07010977
Friday	05007561
Saturday	05004134, 09023363, 05026377, 04015473, 07008598

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	2	2	3	2	2	3	3	17	100	100
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	0	1	2	0	2	0	0	0	5	15	N/A
25 to 34	0	1	0	2	2	0	1	0	6	18	N/A
35 to 44	0	1	0	1	0	3	2	3	10	29	N/A
45 to 54	0	0	0	0	0	0	0	1	1	3	N/A
55 to 64	0	1	1	2	0	1	1	0	6	18	N/A
65 to 74	0	0	1	1	0	0	1	1	4	12	N/A
75 to 84	0	0	0	0	0	0	1	1	2	6	N/A
Total Vehicles	0	4	4	6	4	4	6	6	34	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	03007032, 06014205, 06024666, 04015473, 04015473
25 to 34	06014205, 05007561, 03033432, 06024666, 05026377, 08012349
35 to 44	05004134, 03007032, 08003947, 09023363, 07010977, 07010977, 08018116, 09005116, 09005116, 07008598
45 to 54	09023363
55 to 64	05007561, 03033432, 05026377, 08012349, 04027518, 07008598
65 to 74	05004134, 08003947, 09025398, 04027518
75 to 84	09025398, 08018116

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	2	2	3	2	2	3	3	17	100	100
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Motor vehicle in transport	0	4	4	6	4	4	6	6	34	100	N/A
Total Vehicles	0	4	4	6	4	4	6	6	34	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Motor vehicle in transport	05004134, 05004134, 03007032, 03007032, 08003947, 08003947, 06014205, 06014205, 09023363, 09023363, 05007561, 05007561, 07010977, 07010977, 03033432, 03033432, 09025398, 09025398, 08018116, 08018116, 06024666, 06024666, 05026377, 05026377, 08012349, 08012349, 09005116, 09005116, 04027518, 04027518, 04015473, 04015473, 07008598, 07008598

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Northbound	0	0	0	1	1	0	2	0	4	12	N/A
Southbound	0	2	0	1	0	0	0	0	3	9	N/A
Eastbound	0	0	2	3	1	4	1	2	13	38	N/A
Westbound	0	2	2	1	2	0	3	4	14	41	N/A
Total Vehicles	0	4	4	6	4	4	6	6	34	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Northbound	08003947, 06014205, 08018116, 05026377
Southbound	03007032, 05007561, 03033432
Eastbound	05004134, 05004134, 08003947, 06014205, 09023363, 09023363, 05007561, 07010977, 07010977, 04015473, 04015473, 07008598, 07008598
Westbound	03007032, 03033432, 09025398, 09025398, 08018116, 06024666, 06024666, 05026377, 08012349, 08012349, 09005116, 09005116, 04027518, 04027518

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	0	1	1	3	2	0	3	1	11	65	73
Dawn	0	0	0	0	0	1	0	1	2	12	1
Dusk	0	0	0	0	0	1	0	0	1	6	3
Dark-lighted	0	1	1	0	0	0	0	1	3	18	18
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 08018116, 06024666, 05026377, 08012349, 04027518
Dawn	07010977, 09005116
Dusk	07008598
Dark-lighted	03033432, 09025398, 04015473

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident. (Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
2 Vehicles	0	2	0	2	2	2	2	3	13	76	N/A
More than 2 Vehicles	0	0	2	1	0	0	1	0	4	24	N/A
Total Accidents	0	2	2	3	2	2	3	3	17	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
2 Vehicles	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 06024666, 08012349, 09005116, 07008598
More than 2 Vehicles	08018116, 05026377, 04027518, 04015473

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	2	2	3	2	2	3	3	17	100	99
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
At intersection	0	2	1	3	2	1	2	2	13	76	74
Intersection-related	0	0	1	0	0	1	1	1	4	24	26
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
At intersection	05004134, 03007032, 08003947, 06014205, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 09005116, 04015473
Intersection-related	09023363, 08012349, 04027518, 07008598

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	0	2	2	3	1	2	3	2	15	88	76
Wet	0	0	0	0	1	0	0	0	1	6	18
Snow	0	0	0	0	0	0	0	1	1	6	5
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 05026377, 08012349, 04027518, 04015473, 07008598
Wet	06024666
Snow	09005116

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	2	2	3	2	2	3	3	17	100	98
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	2	2	3	2	2	3	3	17	100	100
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	2	2	3	2	2	3	3	17	100	100
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	0	3	3	2	2	2	1	4	17	50	N/A
Light truck, only four tires	0	1	1	0	0	2	3	0	7	21	N/A
Sport utility vehicle	0	0	0	3	2	0	2	0	7	21	N/A
Motorcycle/Moped	0	0	0	0	0	0	0	2	2	6	N/A
Unknown vehicle configuration	0	0	0	1	0	0	0	0	1	3	N/A
Total Vehicles	0	4	4	6	4	4	6	6	34	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	03007032, 03007032, 06014205, 05007561, 07010977, 07010977, 03033432, 09025398, 09025398, 06024666, 05026377, 08012349, 09005116, 09005116, 04027518, 04015473, 04015473
Light truck, only four tires	08003947, 08003947, 03033432, 08018116, 04027518, 07008598, 07008598
Sport utility vehicle	05004134, 05004134, 06014205, 08018116, 06024666, 05026377, 08012349
Motorcycle/Moped	09023363, 09023363
Unknown vehicle configuration	05007561

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	0	1	1	3	1	3	4	2	15	44	N/A
Turning right	0	0	0	0	0	0	0	1	1	3	N/A
Turning left	0	2	0	1	1	0	0	1	5	15	N/A
Entering traffic lane	0	0	0	0	0	0	1	1	2	6	N/A
Stopped in traffic	0	0	3	1	2	0	1	1	8	24	N/A
Unknown	0	1	0	1	0	1	0	0	3	9	N/A
Total Vehicles	0	4	4	6	4	4	6	6	34	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 09025398, 08018116, 08018116, 05026377, 08012349, 04015473, 07008598, 07008598
Turning right	09023363
Turning left	03007032, 06014205, 05007561, 03033432, 09005116
Entering traffic lane	08003947, 09005116
Stopped in traffic	05004134, 09025398, 06024666, 06024666, 08012349, 04027518, 04027518, 04015473
Unknown	07010977, 03033432, 05026377

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	0	2	0	1	1	0	0	1	5	29	29
Right turn	0	0	0	0	0	0	0	1	1	6	7
No-turn	0	0	2	2	1	2	3	1	11	65	64
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	03007032, 06014205, 05007561, 03033432, 09005116
Right turn	09023363
No-turn	05004134, 08003947, 07010977, 09025398, 08018116, 06024666, 05026377, 08012349, 04027518, 04015473, 07008598

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	0	2	1	2	1	1	3	3	13	76	63
Cloudy	0	0	1	1	0	1	0	0	3	18	22
Rain	0	0	0	0	1	0	0	0	1	6	11
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 05026377, 08012349, 09005116, 04015473
Cloudy	05004134, 04027518, 07008598
Rain	06024666

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in

this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	2	2	3	2	2	3	3	17	100	98
Total Accidents	0	2	2	3	2	2	3	3	17	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	05004134, 03007032, 08003947, 06014205, 09023363, 05007561, 07010977, 03033432, 09025398, 08018116, 06024666, 05026377, 08012349, 09005116, 04027518, 04015473, 07008598

2. Route SR S0000101A_, Milepost 9.24

Intersection

Intersection ID: 1007

Internal Intersection ID: I5582

Route Number Display Value: SRS0000101A_

Site Subtype: Int/Urb; 3-leg signalized

Location: 9.24

GIS Identifier: 1007

Major Road Direction: East-West

Minor Road Name: Northwest Blvd

Minor Road Location: 0.0

Intersection Type Level 1: Tee intersection

Intersection Type Level 2: Three-legs

Traffic Control Type at Intersection: Signals semi-actuated (multi-phase)

Growth Factor: 1.0000

Growth Factor Source: Specified

Maximum AADT: 36,733 vehicles per day

Number of Accidents: 17

Geographic Description

Identifier: G2448

Route Type: State route

Route Name: S0000101A_

Major Road Name: NH Route 101A

County: HILLSBOROUGH

District: 5

City/Town: NASHUA

Jurisdiction: Local maintained

Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 9.24 Major Road Annual Traffic

Year	AADT	Volume Source	Comment
2002	36,733	Growth Factor Applied	
2003	36,733	Growth Factor Applied	
2004	36,733	Growth Factor Applied	
2005	36,733	Growth Factor Applied	
2006	36,733	Growth Factor Applied	
2007	36,733	Growth Factor Applied	
2008	36,733	Growth Factor Applied	
2009	36,733	Measured	

Table 57. Route SR S0000101A_, Milepost 9.24 Minor Road Annual Traffic

Year	AADT	Volume Source	Comment
2002	2,498	Growth Factor Applied	
2003	2,498	Growth Factor Applied	
2004	2,498	Growth Factor Applied	
2005	2,498	Growth Factor Applied	
2006	2,498	Growth Factor Applied	
2007	2,498	Growth Factor Applied	
2008	2,498	Growth Factor Applied	
2009	2,498	Measured	

Intersection Leg

Leg ID: 1

Type: Major road, increasing milepost direction

Leg Location: 9.24

Direction: EB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

Intersection Leg

Leg ID: 2

Type: Major road, decreasing milepost direction

Leg Location: 9.24

Direction: WB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

Intersection Leg

Leg ID: 3

Type: Minor road, increasing milepost direction

Leg Location: 0.0

Direction: NB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

3. Accident Case Details

Accident Details: Accident Case ID: 05004134

Accident

Accident ID: 05004134

Internal Accident ID: A34655

Inventory Element: I5582

Location: 9.23963

GIS Identifier: 05004134

Accident Date: 2005/01/22

Accident Month: January

Accident Time of Day: 1248

Accident Date Stamp: 01/22/05 12:48:00

Accident Year: 2005

Accident Severity Level 1: Possible Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Saturday

Agency Intersection Identifier: 1007

Table 58. Accident 05004134 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1964/02/16	40
Vehicle 2	Eastbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1932/11/30	72

Accident Details: Accident Case ID: 03007032

Accident

Accident ID: 03007032

Internal Accident ID: A5909

Inventory Element: I5582

Location: 9.23963

GIS Identifier: 03007032

Accident Date: 2003/02/20

Accident Month: February

Accident Time of Day: 1659

Accident Date Stamp: 02/20/03 16:59:00

Accident Year: 2003

Accident Severity Level 1: Possible Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 2

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Thursday

Agency Intersection Identifier: 1007

Table 59. Accident 03007032 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Turning left	Passenger car	Motor vehicle in transport	1958/05/28	44
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1986/01/23	17

Accident Details: Accident Case ID: 08003947**Accident**

Accident ID: 08003947

Internal Accident ID: A96883

Inventory Element: I5582

Location: 9.23963

GIS Identifier: 08003947

Accident Date: 2008/01/15

Accident Month: January

Accident Time of Day: 1420

Accident Date Stamp: 01/15/08 14:20:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Tuesday

Agency Intersection Identifier: 1007

Table 60. Accident 08003947 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1969/10/07	38
Vehicle 2	Northbound	Entering traffic lane	Light truck, only four tires	Motor vehicle in transport	1942/12/08	65

Accident Details: Accident Case ID: 06014205

Accident

Accident ID: 06014205

Internal Accident ID: A59610

Inventory Element: I5582

Location: 9.23963

GIS Identifier: 06014205

Accident Date: 2006/06/14

Accident Month: June

Accident Time of Day: 0930

Accident Date Stamp: 06/14/06 09:30:00

Accident Year: 2006

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Wednesday
 Agency Intersection Identifier: 1007

Table 61. Accident 06014205 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1986/12/09	19
Vehicle 2	Northbound	Turning left	Sport utility vehicle	Motor vehicle in transport	1976/03/09	30

Accident Details: Accident Case ID: 09023363

Accident

Accident ID: 09023363
 Internal Accident ID: A131760
 Inventory Element: I5582
 Location: 9.2358
 GIS Identifier: 09023363
 Accident Date: 2009/09/19
 Accident Month: September
 Accident Time of Day: 1514
 Accident Date Stamp: 09/19/09 15:14:00
 Accident Year: 2009
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No

Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Right turn
 Day of Week: Saturday
 Agency Intersection Identifier: 1007

Table 62. Accident 09023363 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning right	Motorcycle/Moped	Motor vehicle in transport	1958/04/29	51
Vehicle 2	Eastbound	Movements essentially straight ahead	Motorcycle/Moped	Motor vehicle in transport	1965/08/31	44

Accident Details: Accident Case ID: 05007561

Accident

Accident ID: 05007561
 Internal Accident ID: A30588
 Inventory Element: I5582
 Location: 9.23963
 GIS Identifier: 05007561
 Accident Date: 2005/03/04
 Accident Month: March
 Accident Time of Day: 0709
 Accident Date Stamp: 03/04/05 07:09:00
 Accident Year: 2005
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Glare

Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Friday
 Agency Intersection Identifier: 1007

Table 63. Accident 05007561 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1944/05/17	60
Vehicle 2	Southbound	Turning left	Unknown vehicle configuration	Motor vehicle in transport	1977/10/29	27

Accident Details: Accident Case ID: 07010977

Accident

Accident ID: 07010977
 Internal Accident ID: A75823
 Inventory Element: I5582
 Location: 9.2358
 GIS Identifier: 07010977
 Accident Date: 2007/04/05
 Accident Month: April
 Accident Time of Day: 0532
 Accident Date Stamp: 04/05/07 05:32:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Dawn
 Weather Condition: Clear

Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday
 Agency Intersection Identifier: 1007

Table 64. Accident 07010977 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1962/12/04	44
Vehicle 2	Eastbound	Unknown	Passenger car	Motor vehicle in transport	1967/09/25	39

Accident Details: Accident Case ID: 03033432

Accident

Accident ID: 03033432
 Internal Accident ID: A10151
 Inventory Element: I5582
 Location: 9.23963
 GIS Identifier: 03033432
 Accident Date: 2003/10/28
 Accident Month: October
 Accident Time of Day: 1745
 Accident Date Stamp: 10/28/03 17:45:00
 Accident Year: 2003
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: At intersection

Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Angle
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Tuesday
 Agency Intersection Identifier: 1007

Table 65. Accident 03033432 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Unknown	Passenger car	Motor vehicle in transport	1973/03/02	30
Vehicle 2	Southbound	Turning left	Light truck, only four tires	Motor vehicle in transport	1943/06/27	60

Accident Details: Accident Case ID: 09025398

Accident

Accident ID: 09025398
 Internal Accident ID: A138596
 Inventory Element: I5582
 Location: 9.23963
 GIS Identifier: 09025398
 Accident Date: 2009/10/20
 Accident Month: October
 Accident Time of Day: 1825
 Accident Date Stamp: 10/20/09 18:25:00
 Accident Year: 2009
 Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday
 Agency Intersection Identifier: 1007

Table 66. Accident 09025398 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1931/05/02	78
Vehicle 2	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1942/06/25	67

Accident Details: Accident Case ID: 08018116

Accident

Accident ID: 08018116
 Internal Accident ID: A107794
 Inventory Element: I5582
 Location: 9.23963
 GIS Identifier: 08018116
 Accident Date: 2008/07/07
 Accident Month: July
 Accident Time of Day: 1325

Accident Date Stamp: 07/07/08 13:25:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday
 Agency Intersection Identifier: 1007

Table 67. Accident 08018116 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1926/10/28	81
Vehicle 2	Northbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1967/01/16	41

Accident Details: Accident Case ID: 06024666

Accident

Accident ID: 06024666
 Internal Accident ID: A68977
 Inventory Element: I5582
 Location: 9.23963
 GIS Identifier: 06024666

Accident Date: 2006/10/17
 Accident Month: October
 Accident Time of Day: 1612
 Accident Date Stamp: 10/17/06 16:12:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Rain
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday
 Agency Intersection Identifier: 1007

Table 68. Accident 06024666 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1979/05/28	27
Vehicle 2	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1987/12/28	18

Accident Details: Accident Case ID: 05026377

Accident

Accident ID: 05026377

Internal Accident ID: A43224

Inventory Element: I5582
 Location: 9.23963
 GIS Identifier: 05026377
 Accident Date: 2005/09/03
 Accident Month: September
 Accident Time of Day: 1549
 Accident Date Stamp: 09/03/05 15:49:00
 Accident Year: 2005
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 3
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday
 Agency Intersection Identifier: 1007

Table 69. Accident 05026377 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Unknown	Passenger car	Motor vehicle in transport	1979/11/27	25
Vehicle 2	Northbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1948/11/04	56

Accident Details: Accident Case ID: 08012349

Accident

Accident ID: 08012349

Internal Accident ID: A103856

Inventory Element: I5582

Location: 9.2586

GIS Identifier: 08012349

Accident Date: 2008/05/07

Accident Month: May

Accident Time of Day: 1248

Accident Date Stamp: 05/07/08 12:48:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Wednesday

Agency Intersection Identifier: 1007

Table 70. Accident 08012349 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1974/11/23	33
Vehicle 2	Westbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1952/01/06	56

Accident Details: Accident Case ID: 09005116

Accident

Accident ID: 09005116

Internal Accident ID: A123971

Inventory Element: I5582

Location: 9.23963

GIS Identifier: 09005116

Accident Date: 2009/02/04

Accident Month: February

Accident Time of Day: 0612

Accident Date Stamp: 02/04/09 06:12:00

Accident Year: 2009

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Dawn

Weather Condition: Clear

Roadway Surface Condition: Snow

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Wednesday

Agency Intersection Identifier: 1007

Table 71. Accident 09005116 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Turning left	Passenger car	Motor vehicle in transport	1969/01/05	40
Vehicle 2	Westbound	Entering traffic lane	Passenger car	Motor vehicle in transport	1973/01/23	36

Accident Details: Accident Case ID: 04027518

Accident

Accident ID: 04027518

Internal Accident ID: A27117

Inventory Element: I5582

Location: 9.23963

GIS Identifier: 04027518

Accident Date: 2004/09/29

Accident Month: September

Accident Time of Day: 1157

Accident Date Stamp: 09/29/04 11:57:00

Accident Year: 2004

Accident Severity Level 1: Possible Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 2

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Rear-end

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 5

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Wednesday

Agency Intersection Identifier: 1007

Table 72. Accident 04027518 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Light truck, only four tires	Motor vehicle in transport	1939/06/29	65
Vehicle 2	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1942/04/02	62

Accident Details: Accident Case ID: 04015473

Accident

Accident ID: 04015473

Internal Accident ID: A20762

Inventory Element: I5582

Location: 9.232

GIS Identifier: 04015473

Accident Date: 2004/06/05

Accident Month: June

Accident Time of Day: 2058

Accident Date Stamp: 06/05/04 20:58:00

Accident Year: 2004

Accident Severity Level 1: Possible Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 3

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Rear-end

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 4

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday
 Agency Intersection Identifier: 1007

Table 73. Accident 04015473 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1988/03/04	16
Vehicle 2	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1982/06/26	21

Accident Details: Accident Case ID: 07008598

Accident

Accident ID: 07008598
 Internal Accident ID: A79994
 Inventory Element: I5582
 Location: 9.2017
 GIS Identifier: 07008598
 Accident Date: 2007/03/24
 Accident Month: March
 Accident Time of Day: 1641
 Accident Date Stamp: 03/24/07 16:41:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Dusk
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No

Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday

Table 74. Accident 07008598 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1947/11/23	59
Vehicle 2	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1968/04/04	38