

SafetyAnalyst

**Accident Summary for Route SR S0000101A_,
Milepost 11.494 (Intersection 62897)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary 1

 1.1 Accident Case Identifier 1

 1.2 Accident Month 1

 1.3 Accident Severity Level 1 2

 1.4 Accident Time of Day 3

 1.5 Accident Type and Manner of Collision 4

 1.6 Alcohol/Drug Involvement 5

 1.7 Bicycle Indicator 5

 1.8 Contributing Circumstances, Environment 6

 1.9 Contributing Circumstances, Road 7

 1.10 Day of Week 7

 1.11 Divided Highway Flag-Side of Road 8

 1.12 Driver Age 9

 1.13 Driveway Indicator 10

 1.14 First Harmful Event 11

 1.15 Initial Direction of Travel 12

 1.16 Light Condition 13

 1.17 Number of Vehicles Involved 13

 1.18 Pedestrian Indicator 14

 1.19 Relationship to Junction 14

 1.20 Roadway Surface Condition 15

 1.21 Run-Off Road Indicator 16

 1.22 School Bus Related 16

 1.23 Tow-Away Indicator 17

 1.24 Vehicle Configuration 18

 1.25 Vehicle Maneuver/Action 18

 1.26 Vehicle Turning Movement 19

 1.27 Weather Condition 20

 1.28 Work Zone Related 21

2. Route SR S0000101A_, Milepost 11.494 22

3. Accident Case Details 25

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	3
Table 5. Accident Severity Level 1 (Accident Case Identifier)	3
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	4
Table 8. Accident Type and Manner of Collision	4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	5
Table 10. Alcohol/Drug Involvement	5
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	5
Table 12. Bicycle Indicator	6
Table 13. Bicycle Indicator (Accident Case Identifier)	6
Table 14. Contributing Circumstances, Environment	6
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	7
Table 16. Contributing Circumstances, Road	7
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	7
Table 18. Day of Week	8
Table 19. Day of Week (Accident Case Identifier)	8
Table 20. Divided Highway Flag-Side of Road	8
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	9
Table 22. Driver Age in Years	9
Table 23. Driver Age in Years (Accident Case Identifier)	10
Table 24. Driveway Indicator	10
Table 25. Driveway Indicator (Accident Case Identifier)	11
Table 26. First Harmful Event	11
Table 27. First Harmful Event (Accident Case Identifier)	11
Table 28. Initial Direction of Travel	12
Table 29. Initial Direction of Travel (Accident Case Identifier)	12
Table 30. Light Condition	13
Table 31. Light Condition (Accident Case Identifier)	13
Table 32. Number of Vehicles Involved	13
Table 33. Number of Vehicles Involved (Accident Case Identifier)	14
Table 34. Pedestrian Indicator	14
Table 35. Pedestrian Indicator (Accident Case Identifier)	14
Table 36. Relationship to Junction	15
Table 37. Relationship to Junction (Accident Case Identifier)	15
Table 38. Roadway Surface Condition	15

Table 39. Roadway Surface Condition (Accident Case Identifier)	16
Table 40. Run-Off Road Indicator	16
Table 41. Run-Off Road Indicator (Accident Case Identifier)	16
Table 42. School Bus Related	17
Table 43. School Bus Related (Accident Case Identifier)	17
Table 44. Tow-Away Indicator	17
Table 45. Tow-Away Indicator (Accident Case Identifier)	17
Table 46. Vehicle Configuration	18
Table 47. Vehicle Configuration (Accident Case Identifier)	18
Table 48. Vehicle Maneuver/Action	19
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	19
Table 50. Vehicle Turning Movement	20
Table 51. Vehicle Turning Movement (Accident Case Identifier)	20
Table 52. Weather Condition	20
Table 53. Weather Condition (Accident Case Identifier)	21
Table 54. Work Zone Related	21
Table 55. Work Zone Related (Accident Case Identifier)	21
Table 56. Route SR S0000101A_, Milepost 11.494 Major Road Annual Traffic	23
Table 57. Route SR S0000101A_, Milepost 11.494 Minor Road Annual Traffic	23
Table 58. Accident 08031377 Vehicle-Level Accident Data	26
Table 59. Accident 08027284 Vehicle-Level Accident Data	27
Table 60. Accident 03023123 Vehicle-Level Accident Data	28
Table 61. Accident 09019142 Vehicle-Level Accident Data	29
Table 62. Accident 06024495 Vehicle-Level Accident Data	30
Table 63. Accident 09002356 Vehicle-Level Accident Data	31
Table 64. Accident 07003509 Vehicle-Level Accident Data	32
Table 65. Accident 08024134 Vehicle-Level Accident Data	33
Table 66. Accident 02025369 Vehicle-Level Accident Data	34
Table 67. Accident 03027729 Vehicle-Level Accident Data	35
Table 68. Accident 06011394 Vehicle-Level Accident Data	36
Table 69. Accident 08023586 Vehicle-Level Accident Data	37
Table 70. Accident 06009481 Vehicle-Level Accident Data	38
Table 71. Accident 06001631 Vehicle-Level Accident Data	39
Table 72. Accident 06022056 Vehicle-Level Accident Data	40
Table 73. Accident 09008009 Vehicle-Level Accident Data	41
Table 74. Accident 02034934 Vehicle-Level Accident Data	42
Table 75. Accident 03021877 Vehicle-Level Accident Data	43
Table 76. Accident 06024491 Vehicle-Level Accident Data	45
Table 77. Accident 06017676 Vehicle-Level Accident Data	46
Table 78. Accident 08027272 Vehicle-Level Accident Data	47

Table 79. Accident 09004326 Vehicle-Level Accident Data	48
Table 80. Accident 06005424 Vehicle-Level Accident Data	49
Table 81. Accident 08027959 Vehicle-Level Accident Data	50
Table 82. Accident 03028716 Vehicle-Level Accident Data	51
Table 83. Accident 08025527 Vehicle-Level Accident Data	52
Table 84. Accident 06023243 Vehicle-Level Accident Data	53

1. Accident Summary

This is a summary of the accident data associated with the following Intersection from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 11.494 (Intersection 62897)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **27 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2002	02025369, 02034934
2003	03023123, 03027729, 03021877, 03028716
2006	06024495, 06011394, 06009481, 06001631, 06022056, 06024491, 06017676, 06005424, 06023243
2007	07003509
2008	08031377, 08027284, 08024134, 08023586, 08027272, 08027959, 08025527
2009	09019142, 09002356, 09008009, 09004326

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
January	0	0	0	0	1	0	0	1	2	7	9
February	0	0	0	0	1	0	0	0	1	4	7
March	0	0	0	0	0	0	0	2	2	7	7
April	0	0	0	0	1	1	0	0	2	7	7
May	0	0	0	0	1	0	0	0	1	4	9
July	0	1	0	0	1	0	0	0	2	7	9
August	0	1	0	0	0	0	0	0	1	4	9
September	1	2	0	0	1	0	1	1	6	22	8
October	0	0	0	0	3	0	2	0	5	19	9
November	0	0	0	0	0	0	3	0	3	11	8
December	1	0	0	0	0	0	1	0	2	7	9
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
January	09002356, 06001631
February	06005424
March	09008009, 09004326
April	07003509, 06009481
May	06011394
July	03021877, 06017676
August	03023123
September	09019142, 02025369, 03027729, 08023586, 03028716, 06023243
October	06024495, 08024134, 06022056, 06024491, 08025527
November	08027284, 08027272, 08027959
December	08031377, 02034934

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	1	1	0	0	0	0	0	0	2	7	N/A
Possible Injury	1	1	0	0	1	0	0	0	3	11	N/A
Property-Damage-Only	0	2	0	0	8	1	7	4	22	81	N/A
Total Accidents	2	4	0	0	9	1	7	4	27	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	02025369, 03021877
Possible Injury	02034934, 06005424, 03028716
Property-Damage-Only	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 06024491, 06017676, 08027272, 09004326, 08027959, 08025527, 06023243

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
6:00 am to 6:59 am	0	1	0	0	0	1	0	0	2	7	N/A
7:00 am to 7:59 am	0	0	0	0	2	0	0	0	2	7	N/A
11:00 am to 11:59 am	0	0	0	0	1	0	0	0	1	4	N/A
12:00 pm to 12:59 pm	0	0	0	0	0	0	1	1	2	7	N/A
1:00 pm to 1:59 pm	1	0	0	0	1	0	0	1	3	11	N/A
2:00 pm to 2:59 pm	0	0	0	0	1	0	1	2	4	15	N/A
3:00 pm to 3:59 pm	0	1	0	0	1	0	1	0	3	11	N/A
4:00 pm to 4:59 pm	1	1	0	0	0	0	0	0	2	7	N/A
5:00 pm to 5:59 pm	0	1	0	0	0	0	3	0	4	15	N/A
6:00 pm to 6:59 pm	0	0	0	0	1	0	0	0	1	4	N/A
7:00 pm to 7:59 pm	0	0	0	0	1	0	0	0	1	4	N/A
8:00 pm to 8:59 pm	0	0	0	0	1	0	0	0	1	4	N/A
10:00 pm to 10:59 pm	0	0	0	0	0	0	1	0	1	4	N/A
Total Accidents	2	4	0	0	9	1	7	4	27	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
6:00 am to 6:59 am	07003509,03021877
7:00 am to 7:59 am	06017676,06005424
11:00 am to 11:59 am	06001631
12:00 pm to 12:59 pm	09004326, 08027959
1:00 pm to 1:59 pm	09008009,02034934, 06024491
2:00 pm to 2:59 pm	09019142,09002356, 08024134, 06023243
3:00 pm to 3:59 pm	03027729,06011394, 08023586
4:00 pm to 4:59 pm	02025369,03028716
5:00 pm to 5:59 pm	08031377,03023123, 08027272, 08025527
6:00 pm to 6:59 pm	06009481
7:00 pm to 7:59 pm	06022056
8:00 pm to 8:59 pm	06024495
10:00 pm to 10:59 pm	08027284

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with fixed object	0	0	0	0	0	0	1	0	1	4	5
Rear-end	1	2	0	0	0	0	1	0	4	15	11
Angle	0	1	0	0	0	1	0	0	2	7	10
Sideswipe, opposite direction	0	1	0	0	0	0	0	0	1	4	0
Other multiple-vehicle collision	1	0	0	0	9	0	5	4	19	70	67
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with fixed object	08027272
Rear-end	02025369, 03027729, 03028716, 08025527
Angle	07003509, 03021877
Sideswipe, opposite direction	03023123
Other multiple-vehicle collision	08031377, 08027284, 09019142, 06024495, 09002356, 08024134, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 06024491, 06017676, 09004326, 06005424, 08027959, 06023243

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	2	4	0	0	9	1	7	4	27	100	98
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	2	4	0	0	9	1	7	4	27	100	98
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	2	3	0	0	8	0	4	4	21	78	70
Weather conditions	0	0	0	0	1	0	1	0	2	7	15
Physical obstruction(s)	0	0	0	0	0	0	1	0	1	4	7
Unknown	0	1	0	0	0	1	1	0	3	11	6
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	08027284, 03023123, 09019142, 06024495, 09002356, 02025369, 06011394, 08023586, 06009481, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 06023243
Weather conditions	08031377, 06001631
Physical obstruction(s)	08024134
Unknown	07003509, 03027729, 08025527

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	2	3	0	0	9	0	6	4	24	89	95
Unknown	0	1	0	0	0	1	1	0	3	11	3
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 08024134, 02025369, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 06023243
Unknown	07003509, 03027729, 08025527

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Monday	0	2	0	0	0	0	0	0	2	7	14
Tuesday	0	1	0	0	2	0	3	1	7	26	16
Wednesday	2	0	0	0	5	0	1	1	9	33	15
Thursday	0	1	0	0	0	0	2	0	3	11	16
Friday	0	0	0	0	1	1	1	1	4	15	18
Saturday	0	0	0	0	1	0	0	1	2	7	12
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Monday	03021877, 03028716
Tuesday	08027284, 03023123, 09019142, 06017676, 06005424, 08027959, 08025527
Wednesday	06024495, 02025369, 06009481, 06022056, 09008009, 02034934, 06024491, 08027272, 06023243
Thursday	08031377, 03027729, 08023586
Friday	07003509, 08024134, 06011394, 09004326
Saturday	09002356, 06001631

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	2	4	0	0	9	1	7	4	27	100	100
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	1	2	0	0	2	0	3	2	10	19	N/A
25 to 34	3	1	0	0	2	0	3	0	9	17	N/A
35 to 44	0	0	0	0	7	0	4	2	13	25	N/A
45 to 54	0	5	0	0	2	1	2	1	11	21	N/A
55 to 64	0	0	0	0	2	1	0	3	6	11	N/A
65 to 74	0	0	0	0	2	0	0	0	2	4	N/A
75 to 84	0	0	0	0	1	0	0	0	1	2	N/A
85 and over	0	0	0	0	0	0	1	0	1	2	N/A
Total Vehicles	4	8	0	0	18	2	13	8	53	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	08027284, 03023123, 06024495, 03027729, 08023586, 09008009, 02034934, 06024491, 08027272, 09004326
25 to 34	08031377, 08027284, 02025369, 02025369, 03027729, 06011394, 06011394, 02034934, 08027959
35 to 44	09002356, 09002356, 08024134, 06009481, 06009481, 06001631, 06022056, 06017676, 06005424, 06005424, 08027959, 08025527, 08025527
45 to 54	08031377, 03023123, 09019142, 07003509, 08024134, 06001631, 03021877, 03021877, 06017676, 03028716, 03028716
55 to 64	09019142, 06024495, 07003509, 09008009, 06024491, 09004326
65 to 74	06023243, 06023243
75 to 84	06022056
85 and over	08023586

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	2	4	0	0	9	1	7	4	27	100	100
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Motor vehicle in transport	4	8	0	0	18	2	12	8	52	98	N/A
Utility pole/Light support	0	0	0	0	0	0	1	0	1	2	N/A
Total Vehicles	4	8	0	0	18	2	13	8	53	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Motor vehicle in transport	08031377, 08031377, 08027284, 08027284, 03023123, 03023123, 09019142, 09019142, 06024495, 06024495, 09002356, 09002356, 07003509, 07003509, 08024134, 08024134, 02025369, 02025369, 03027729, 03027729, 06011394, 06011394, 08023586, 08023586, 06009481, 06009481, 06001631, 06001631, 06022056, 06022056, 09008009, 09008009, 02034934, 02034934, 03021877, 03021877, 06024491, 06024491, 06017676, 06017676, 09004326, 09004326, 06005424, 06005424, 08027959, 08027959, 03028716, 03028716, 08025527, 08025527, 06023243, 06023243
Utility pole/Light support	08027272

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Southbound	0	0	0	0	5	1	3	0	9	17	N/A
Eastbound	0	5	0	0	8	1	7	2	23	43	N/A
Westbound	4	2	0	0	5	0	3	5	19	36	N/A
Unknown	0	1	0	0	0	0	0	1	2	4	N/A
Total Vehicles	4	8	0	0	18	2	13	8	53	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Southbound	08031377, 08031377, 07003509, 06017676, 06017676, 08027272, 06005424, 06005424, 06023243
Eastbound	08027284, 03023123, 03023123, 06024495, 06024495, 09002356, 07003509, 06011394, 06011394, 08023586, 08023586, 06009481, 06009481, 03021877, 06024491, 09004326, 08027959, 08027959, 03028716, 03028716, 08025527, 08025527, 06023243
Westbound	08027284, 09019142, 09019142, 08024134, 08024134, 02025369, 02025369, 03027729, 03027729, 06001631, 06001631, 06022056, 06022056, 09008009, 09008009, 02034934, 02034934, 06024491, 09004326
Unknown	09002356, 03021877

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	2	3	0	0	6	0	3	4	18	67	76
Dusk	0	0	0	0	1	0	0	0	1	4	3
Dark-lighted	0	0	0	0	2	0	3	0	5	19	14
Unknown	0	1	0	0	0	1	1	0	3	11	3
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	03023123, 09019142, 09002356, 08024134, 02025369, 06011394, 08023586, 06001631, 09008009, 02034934, 03021877, 06024491, 06017676, 09004326, 06005424, 08027959, 03028716, 06023243
Dusk	06009481
Dark-lighted	08031377, 08027284, 06024495, 06022056, 08027272
Unknown	07003509, 03027729, 08025527

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1 Vehicle	0	0	0	0	0	0	1	0	1	4	N/A
2 Vehicles	2	4	0	0	7	1	4	4	22	81	N/A
More than 2 Vehicles	0	0	0	0	2	0	2	0	4	15	N/A
Total Accidents	2	4	0	0	9	1	7	4	27	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
1 Vehicle	08027272
2 Vehicles	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 06009481, 06001631, 09008009, 02034934, 03021877, 06024491, 09004326, 06005424, 03028716, 08025527, 06023243
More than 2 Vehicles	08023586, 06022056, 06017676, 08027959

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	2	4	0	0	9	1	7	4	27	100	98
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some

distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
At intersection	1	1	0	0	6	1	1	1	11	41	76
Intersection-related	1	3	0	0	3	0	6	3	16	59	24
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
At intersection	07003509, 06011394, 06009481, 06001631, 02034934, 03021877, 06024491, 09004326, 06005424, 08025527, 06023243
Intersection-related	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 08024134, 02025369, 03027729, 08023586, 06022056, 09008009, 06017676, 08027272, 08027959, 03028716

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	2	4	0	0	7	1	6	4	24	89	75
Wet	0	0	0	0	2	0	1	0	3	11	17
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 08023586, 06009481, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243
Wet	08031377, 06011394, 06001631

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	0	0	0	0	1	0	1	4	5
No	2	4	0	0	9	1	6	4	26	96	95
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	08027272
No	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	2	4	0	0	9	1	7	4	27	100	100
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	2	4	0	0	9	1	7	4	27	100	100
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06024491, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	1	5	0	0	12	1	7	4	30	57	N/A
Light truck, only four tires	1	1	0	0	4	1	2	1	10	19	N/A
Sport utility vehicle	0	1	0	0	2	0	4	2	9	17	N/A
Motorcycle/Moped	2	0	0	0	0	0	0	0	2	4	N/A
Unknown vehicle configuration	0	1	0	0	0	0	0	1	2	4	N/A
Total Vehicles	4	8	0	0	18	2	13	8	53	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	08031377, 08027284, 08027284, 03023123, 09019142, 06024495, 07003509, 03027729, 03027729, 06011394, 08023586, 08023586, 06009481, 06001631, 09008009, 09008009, 02034934, 03021877, 06024491, 06024491, 06017676, 06017676, 09004326, 06005424, 06005424, 08027959, 03028716, 08025527, 06023243, 06023243
Light truck, only four tires	07003509, 08024134, 06011394, 06009481, 06022056, 06022056, 02034934, 03021877, 09004326, 08027959
Sport utility vehicle	08031377, 09019142, 06024495, 09002356, 08024134, 06001631, 08027272, 03028716, 08025527
Motorcycle/Moped	02025369, 02025369
Unknown vehicle configuration	03023123, 09002356

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	1	3	0	0	5	1	3	2	15	28	N/A
Backing	0	0	0	0	1	0	0	0	1	2	N/A
Changing lanes	0	0	0	0	0	0	1	1	2	4	N/A
Turning right	1	1	0	0	2	0	0	0	4	8	N/A
Turning left	0	0	0	0	4	1	1	1	7	13	N/A
Making U-turn	0	1	0	0	0	0	0	0	1	2	N/A
Entering traffic lane	0	0	0	0	0	0	2	0	2	4	N/A
Slowing	2	1	0	0	1	0	0	0	4	8	N/A
Stopped in traffic	0	2	0	0	3	0	6	3	14	26	N/A
Unknown	0	0	0	0	2	0	0	1	3	6	N/A
Total Vehicles	4	8	0	0	18	2	13	8	53	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	08027284, 08027284, 03023123, 06024495, 07003509, 03027729, 08023586, 06009481, 06022056, 06022056, 09008009, 02034934, 03021877, 06024491, 09004326
Backing	06023243
Changing lanes	09019142, 08024134
Turning right	03023123, 02034934, 06005424, 06005424
Turning left	06024495, 07003509, 06011394, 06011394, 06024491, 08027272, 09004326
Making U-turn	03021877
Entering traffic lane	08031377, 08024134
Slowing	02025369, 02025369, 06001631, 03028716
Stopped in traffic	08031377, 09019142, 09002356, 03027729, 08023586, 06009481, 06001631, 09008009, 08027959, 08027959, 03028716, 08025527, 08025527, 06023243
Unknown	09002356, 06017676, 06017676

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then

this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	0	1	0	0	3	1	0	1	6	22	35
Right turn	1	1	0	0	1	0	0	0	3	11	7
No-turn	1	2	0	0	4	0	7	3	17	63	58
Unknown	0	0	0	0	1	0	0	0	1	4	1
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	06024495, 07003509, 06011394, 03021877, 06024491, 09004326
Right turn	03023123, 02034934, 06005424
No-turn	08031377, 08027284, 09019142, 09002356, 08024134, 02025369, 03027729, 08023586, 06009481, 06001631, 06022056, 09008009, 08027272, 08027959, 03028716, 08025527, 06023243
Unknown	06017676

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	2	3	0	0	7	1	4	3	20	74	63
Cloudy	0	1	0	0	1	0	2	1	5	19	21
Rain	0	0	0	0	1	0	1	0	2	7	10
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 02025369, 03027729, 06009481, 06022056, 09008009, 02034934, 06024491, 06017676, 08027272, 06005424, 08027959, 03028716, 08025527, 06023243
Cloudy	08024134, 06011394, 08023586, 03021877, 09004326
Rain	08031377, 06001631

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	0	0	1	0	0	0	1	4	1
No	2	4	0	0	8	1	7	4	26	96	99
Total Accidents	2	4	0	0	9	1	7	4	27	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
Yes	06024491
No	08031377, 08027284, 03023123, 09019142, 06024495, 09002356, 07003509, 08024134, 02025369, 03027729, 06011394, 08023586, 06009481, 06001631, 06022056, 09008009, 02034934, 03021877, 06017676, 08027272, 09004326, 06005424, 08027959, 03028716, 08025527, 06023243

2. Route SR S0000101A_, Milepost 11.494

Intersection

Intersection ID: 62897

Internal Intersection ID: I8245

Route Number Display Value: SRS0000101A_

Site Subtype: Int/Urb; 3-leg minor-rd STOP

Location: 11.494

GIS Identifier: 62897

Major Road Direction: East-West

Minor Road Name: Arvard St

Minor Road Location: 0.0

Intersection Type Level 1: Tee intersection

Intersection Type Level 2: Three-legs

Traffic Control Type at Intersection: Stop signs on cross street only

Growth Factor: 1.0000

Growth Factor Source: Specified

Maximum AADT: 37,823 vehicles per day

Number of Accidents: 27

Geographic Description

Identifier: G344

Route Type: State route

Route Name: S0000101A_

Major Road Name: Amherst St

County: HILLSBOROUGH

District: 5

City/Town: NASHUA

Jurisdiction: Local maintained

Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 11.494 Major Road Annual Traffic

Year	AADT	Volume Source	Comment
2002	37,823	Growth Factor Applied	
2003	37,823	Growth Factor Applied	
2004	37,823	Growth Factor Applied	
2005	37,823	Growth Factor Applied	
2006	37,823	Growth Factor Applied	
2007	37,823	Growth Factor Applied	
2008	37,823	Growth Factor Applied	
2009	37,823	Measured	

Table 57. Route SR S0000101A_, Milepost 11.494 Minor Road Annual Traffic

Year	AADT	Volume Source	Comment
2002	2,498	Growth Factor Applied	
2003	2,498	Growth Factor Applied	
2004	2,498	Growth Factor Applied	
2005	2,498	Growth Factor Applied	
2006	2,498	Growth Factor Applied	
2007	2,498	Growth Factor Applied	
2008	2,498	Growth Factor Applied	
2009	2,498	Measured	

Intersection Leg

Leg ID: 1

Type: Major road, increasing milepost direction

Leg Location: 11.494

Direction: EB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

Intersection Leg

Leg ID: 2

Type: Major road, decreasing milepost direction

Leg Location: 11.494

Direction: WB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

Intersection Leg

Leg ID: 3

Type: Minor road, increasing milepost direction

Leg Location: 0.0

Direction: NB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

3. Accident Case Details

Accident Details: Accident Case ID: 08031377

Accident

Accident ID: 08031377

Internal Accident ID: A118905

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 08031377

Accident Date: 2008/12/11

Accident Month: December

Accident Time of Day: 1700

Accident Date Stamp: 12/11/08 17:00:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Rain

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Weather conditions

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Thursday

Table 58. Accident 08031377 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1980/10/02	28
Vehicle 2	Southbound	Entering traffic lane	Sport utility vehicle	Motor vehicle in transport	1955/04/24	53

Accident Details: Accident Case ID: 08027284

Accident

Accident ID: 08027284

Internal Accident ID: A110522

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 08027284

Accident Date: 2008/11/04

Accident Month: November

Accident Time of Day: 2214

Accident Date Stamp: 11/04/08 22:14:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Tuesday

Table 59. Accident 08027284 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1978/06/09	30
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1991/05/23	17

Accident Details: Accident Case ID: 03023123

Accident

Accident ID: 03023123

Internal Accident ID: A10015

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 03023123

Accident Date: 2003/08/19

Accident Month: August

Accident Time of Day: 1730

Accident Date Stamp: 08/19/03 17:30:00

Accident Year: 2003

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Sideswipe, opposite direction

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Right turn

Day of Week: Tuesday

Table 60. Accident 03023123 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning right	Passenger car	Motor vehicle in transport	1983/03/30	20
Vehicle 2	Eastbound	Movements essentially straight ahead	Unknown vehicle configuration	Motor vehicle in transport	1951/12/06	51

Accident Details: Accident Case ID: 09019142

Accident

Accident ID: 09019142

Internal Accident ID: A132008

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 09019142

Accident Date: 2009/09/01

Accident Month: September

Accident Time of Day: 1448

Accident Date Stamp: 09/01/09 14:48:00

Accident Year: 2009

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 61. Accident 09019142 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1945/08/16	64
Vehicle 2	Westbound	Changing lanes	Passenger car	Motor vehicle in transport	1962/07/31	47

Accident Details: Accident Case ID: 06024495

Accident

Accident ID: 06024495
 Internal Accident ID: A68780
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 06024495
 Accident Date: 2006/10/04
 Accident Month: October
 Accident Time of Day: 2057
 Accident Date Stamp: 10/04/06 20:57:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Wednesday

Table 62. Accident 06024495 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1988/08/03	18
Vehicle 2	Eastbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1942/09/04	64

Accident Details: Accident Case ID: 09002356

Accident

Accident ID: 09002356
 Internal Accident ID: A122558
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 09002356
 Accident Date: 2009/01/03
 Accident Month: January
 Accident Time of Day: 1414
 Accident Date Stamp: 01/03/09 14:14:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday

Table 63. Accident 09002356 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1967/04/28	41
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Motor vehicle in transport	1967/04/28	41

Accident Details: Accident Case ID: 07003509

Accident

Accident ID: 07003509
 Internal Accident ID: A71631
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 07003509
 Accident Date: 2007/04/06
 Accident Month: April
 Accident Time of Day: 0650
 Accident Date Stamp: 04/06/07 06:50:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Unknown
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Angle
 Contributing Circumstances, Environment: Unknown
 Contributing Circumstances, Road: Unknown
 School Bus Related: Unknown

Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Friday

Table 64. Accident 07003509 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1956/04/09	50
Vehicle 2	Southbound	Turning left	Light truck, only four tires	Motor vehicle in transport	1943/01/08	64

Accident Details: Accident Case ID: 08024134

Accident

Accident ID: 08024134
 Internal Accident ID: A112206
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 08024134
 Accident Date: 2008/10/03
 Accident Month: October
 Accident Time of Day: 1445
 Accident Date Stamp: 10/03/08 14:45:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Physical obstruction(s)

Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 65. Accident 08024134 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Entering traffic lane	Light truck, only four tires	Motor vehicle in transport	1965/07/16	43
Vehicle 2	Westbound	Changing lanes	Sport utility vehicle	Motor vehicle in transport	1961/12/25	46

Accident Details: Accident Case ID: 02025369

Accident

Accident ID: 02025369
 Internal Accident ID: A95
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 02025369
 Accident Date: 2002/09/11
 Accident Month: September
 Accident Time of Day: 1643
 Accident Date Stamp: 09/11/02 16:43:00
 Accident Year: 2002
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 66. Accident 02025369 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Slowing	Motorcycle/Moped	Motor vehicle in transport	1972/06/05	30
Vehicle 2	Westbound	Slowing	Motorcycle/Moped	Motor vehicle in transport	1974/02/17	28

Accident Details: Accident Case ID: 03027729

Accident

Accident ID: 03027729
 Internal Accident ID: A12837
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 03027729
 Accident Date: 2003/09/11
 Accident Month: September
 Accident Time of Day: 1510
 Accident Date Stamp: 09/11/03 15:10:00
 Accident Year: 2003
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Unknown

Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: Unknown
 Contributing Circumstances, Road: Unknown
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 67. Accident 03027729 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1986/03/12	17
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1977/01/30	26

Accident Details: Accident Case ID: 06011394

Accident

Accident ID: 06011394
 Internal Accident ID: A55232
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 06011394
 Accident Date: 2006/05/12
 Accident Month: May
 Accident Time of Day: 1534
 Accident Date Stamp: 05/12/06 15:34:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection

Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Friday

Table 68. Accident 06011394 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1971/05/13	34
Vehicle 2	Eastbound	Turning left	Light truck, only four tires	Motor vehicle in transport	1971/05/13	34

Accident Details: Accident Case ID: 08023586

Accident

Accident ID: 08023586
 Internal Accident ID: A112207
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 08023586
 Accident Date: 2008/09/25
 Accident Month: September
 Accident Time of Day: 1523
 Accident Date Stamp: 09/25/08 15:23:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0

Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 69. Accident 08023586 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1922/11/10	85
Vehicle 2	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1991/10/16	16

Accident Details: Accident Case ID: 06009481

Accident

Accident ID: 06009481
 Internal Accident ID: A57361
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 06009481
 Accident Date: 2006/04/12
 Accident Month: April
 Accident Time of Day: 1800
 Accident Date Stamp: 04/12/06 18:00:00
 Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Dusk
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 70. Accident 06009481 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1969/04/20	36
Vehicle 2	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1969/04/20	36

Accident Details: Accident Case ID: 06001631

Accident

Accident ID: 06001631
 Internal Accident ID: A45121
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 06001631
 Accident Date: 2006/01/14
 Accident Month: January
 Accident Time of Day: 1159

Accident Date Stamp: 01/14/06 11:59:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Rain
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday

Table 71. Accident 06001631 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1951/12/25	54
Vehicle 2	Westbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1968/05/20	37

Accident Details: Accident Case ID: 06022056

Accident

Accident ID: 06022056
 Internal Accident ID: A60705
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 06022056
 Accident Date: 2006/10/04

Accident Month: October
 Accident Time of Day: 1917
 Accident Date Stamp: 10/04/06 19:17:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 72. Accident 06022056 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1969/06/18	37
Vehicle 2	Westbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1931/04/29	75

Accident Details: Accident Case ID: 09008009

Accident

Accident ID: 09008009
 Internal Accident ID: A122241
 Inventory Element: I8245
 Location: 11.4652

GIS Identifier: 09008009
 Accident Date: 2009/03/18
 Accident Month: March
 Accident Time of Day: 1318
 Accident Date Stamp: 03/18/09 13:18:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 73. Accident 09008009 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1946/09/01	62
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1991/05/09	17

Accident Details: Accident Case ID: 02034934

Accident

Accident ID: 02034934

Internal Accident ID: A6284

Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 02034934
 Accident Date: 2002/12/04
 Accident Month: December
 Accident Time of Day: 1348
 Accident Date Stamp: 12/04/02 13:48:00
 Accident Year: 2002
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Right turn
 Day of Week: Wednesday

Table 74. Accident 02034934 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1980/07/08	22
Vehicle 2	Westbound	Turning right	Light truck, only four tires	Motor vehicle in transport	1974/11/12	28

Accident Details: Accident Case ID: 03021877

Accident

Accident ID: 03021877
 Internal Accident ID: A12929
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 03021877
 Accident Date: 2003/07/14
 Accident Month: July
 Accident Time of Day: 0613
 Accident Date Stamp: 07/14/03 06:13:00
 Accident Year: 2003
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Angle
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Monday

Table 75. Accident 03021877 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Unknown	Making U-turn	Passenger car	Motor vehicle in transport	1958/01/28	45
Vehicle 2	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1950/05/16	53

Accident Details: Accident Case ID: 06024491

Accident

Accident ID: 06024491

Internal Accident ID: A68688

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 06024491

Accident Date: 2006/10/04

Accident Month: October

Accident Time of Day: 1316

Accident Date Stamp: 10/04/06 13:16:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: Yes

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Wednesday

Table 76. Accident 06024491 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1982/11/14	23
Vehicle 2	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1947/02/02	59

Accident Details: Accident Case ID: 06017676

Accident

Accident ID: 06017676

Internal Accident ID: A60589

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 06017676

Accident Date: 2006/07/18

Accident Month: July

Accident Time of Day: 0738

Accident Date Stamp: 07/18/06 07:38:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Unknown

Day of Week: Tuesday

Table 77. Accident 06017676 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Unknown	Passenger car	Motor vehicle in transport	1956/01/13	50
Vehicle 2	Southbound	Unknown	Passenger car	Motor vehicle in transport	1966/08/23	39

Accident Details: Accident Case ID: 08027272

Accident

Accident ID: 08027272

Internal Accident ID: A114810

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 08027272

Accident Date: 2008/11/05

Accident Month: November

Accident Time of Day: 1759

Accident Date Stamp: 11/05/08 17:59:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Collision with fixed object

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 1

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: Yes

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Wednesday

Table 78. Accident 08027272 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Turning left	Sport utility vehicle	Utility pole/Light support	1986/07/04	22
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Utility pole/Light support		

Accident Details: Accident Case ID: 09004326

Accident

Accident ID: 09004326

Internal Accident ID: A124357

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 09004326

Accident Date: 2009/03/06

Accident Month: March

Accident Time of Day: 1213

Accident Date Stamp: 03/06/09 12:13:00

Accident Year: 2009

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Friday

Table 79. Accident 09004326 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1989/01/19	20
Vehicle 2	Westbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1952/08/26	56

Accident Details: Accident Case ID: 06005424

Accident

Accident ID: 06005424

Internal Accident ID: A50861

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 06005424

Accident Date: 2006/02/28

Accident Month: February

Accident Time of Day: 0752

Accident Date Stamp: 02/28/06 07:52:00

Accident Year: 2006

Accident Severity Level 1: Possible Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Right turn
 Day of Week: Tuesday

Table 80. Accident 06005424 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Turning right	Passenger car	Motor vehicle in transport	1967/12/18	38
Vehicle 2	Southbound	Turning right	Passenger car	Motor vehicle in transport	1961/09/29	44

Accident Details: Accident Case ID: 08027959

Accident

Accident ID: 08027959
 Internal Accident ID: A114860
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 08027959
 Accident Date: 2008/11/11
 Accident Month: November
 Accident Time of Day: 1233
 Accident Date Stamp: 11/11/08 12:33:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Tuesday

Table 81. Accident 08027959 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Light truck, only four tires	Motor vehicle in transport	1968/10/30	40
Vehicle 2	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1983/05/04	25

Accident Details: Accident Case ID: 03028716

Accident

Accident ID: 03028716

Internal Accident ID: A13867

Inventory Element: I8245

Location: 11.4652

GIS Identifier: 03028716

Accident Date: 2003/09/22

Accident Month: September

Accident Time of Day: 1625

Accident Date Stamp: 09/22/03 16:25:00

Accident Year: 2003

Accident Severity Level 1: Possible Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Rear-end

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 82. Accident 03028716 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1957/03/25	46
Vehicle 2	Eastbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1958/09/04	45

Accident Details: Accident Case ID: 08025527

Accident

Accident ID: 08025527
 Internal Accident ID: A110309
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 08025527
 Accident Date: 2008/10/14
 Accident Month: October
 Accident Time of Day: 1730
 Accident Date Stamp: 10/14/08 17:30:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Unknown
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: Unknown

Contributing Circumstances, Road: Unknown
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 83. Accident 08025527 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1969/01/31	39
Vehicle 2	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1969/01/31	39

Accident Details: Accident Case ID: 06023243

Accident

Accident ID: 06023243
 Internal Accident ID: A61990
 Inventory Element: I8245
 Location: 11.4652
 GIS Identifier: 06023243
 Accident Date: 2006/09/27
 Accident Month: September
 Accident Time of Day: 1423
 Accident Date Stamp: 09/27/06 14:23:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 84. Accident 06023243 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Backing	Passenger car	Motor vehicle in transport	1935/12/29	70
Vehicle 2	Southbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1939/10/10	66