

SafetyAnalyst

**Accident Summary for Route SR S0000101A ,
Milepost 12.819 to 12.875 (Segment 32983...37628)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary	1
1.1 Accident Case Identifier	1
1.2 Accident Month	1
1.3 Accident Severity Level 1	2
1.4 Accident Time of Day	3
1.5 Accident Type and Manner of Collision	3
1.6 Alcohol/Drug Involvement	4
1.7 Bicycle Indicator	4
1.8 Contributing Circumstances, Environment	5
1.9 Contributing Circumstances, Road	5
1.10 Day of Week	6
1.11 Divided Highway Flag-Side of Road	6
1.12 Driver Age	7
1.13 Driveway Indicator	8
1.14 First Harmful Event	8
1.15 Initial Direction of Travel	9
1.16 Light Condition	9
1.17 Number of Vehicles Involved	10
1.18 Pedestrian Indicator	10
1.19 Relationship to Junction	11
1.20 Roadway Surface Condition	11
1.21 Run-Off Road Indicator	12
1.22 School Bus Related	12
1.23 Tow-Away Indicator	13
1.24 Vehicle Configuration	13
1.25 Vehicle Maneuver/Action	14
1.26 Vehicle Turning Movement	15
1.27 Weather Condition	15
1.28 Work Zone Related	16
2. Route SR S0000101A_, Milepost 12.819 to 12.875	17
3. Accident Case Details	19

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	2
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	3
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	4
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	4
Table 12. Bicycle Indicator	4
Table 13. Bicycle Indicator (Accident Case Identifier)	5
Table 14. Contributing Circumstances, Environment	5
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	5
Table 16. Contributing Circumstances, Road	5
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	6
Table 18. Day of Week	6
Table 19. Day of Week (Accident Case Identifier)	6
Table 20. Divided Highway Flag-Side of Road	7
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	7
Table 22. Driver Age in Years	7
Table 23. Driver Age in Years (Accident Case Identifier)	7
Table 24. Driveway Indicator	8
Table 25. Driveway Indicator (Accident Case Identifier)	8
Table 26. First Harmful Event	8
Table 27. First Harmful Event (Accident Case Identifier)	8
Table 28. Initial Direction of Travel	9
Table 29. Initial Direction of Travel (Accident Case Identifier)	9
Table 30. Light Condition	10
Table 31. Light Condition (Accident Case Identifier)	10
Table 32. Number of Vehicles Involved	10
Table 33. Number of Vehicles Involved (Accident Case Identifier)	10
Table 34. Pedestrian Indicator	11
Table 35. Pedestrian Indicator (Accident Case Identifier)	11
Table 36. Relationship to Junction	11
Table 37. Relationship to Junction (Accident Case Identifier)	11
Table 38. Roadway Surface Condition	12

Table 39. Roadway Surface Condition (Accident Case Identifier)	12
Table 40. Run-Off Road Indicator	12
Table 41. Run-Off Road Indicator (Accident Case Identifier)	12
Table 42. School Bus Related	13
Table 43. School Bus Related (Accident Case Identifier)	13
Table 44. Tow-Away Indicator	13
Table 45. Tow-Away Indicator (Accident Case Identifier)	13
Table 46. Vehicle Configuration	14
Table 47. Vehicle Configuration (Accident Case Identifier)	14
Table 48. Vehicle Maneuver/Action	14
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	15
Table 50. Vehicle Turning Movement	15
Table 51. Vehicle Turning Movement (Accident Case Identifier)	15
Table 52. Weather Condition	16
Table 53. Weather Condition (Accident Case Identifier)	16
Table 54. Work Zone Related	16
Table 55. Work Zone Related (Accident Case Identifier)	16
Table 56. Route SR S0000101A_, Milepost 12.819 to 12.875 Directional Attributes	18
Table 57. Route SR S0000101A_, Milepost 12.819 to 12.875 Annual Traffic	18
Table 58. Accident 06017134 Vehicle-Level Accident Data	20
Table 59. Accident 04018776 Vehicle-Level Accident Data	21
Table 60. Accident 08013386 Vehicle-Level Accident Data	22
Table 61. Accident 07003266 Vehicle-Level Accident Data	23
Table 62. Accident 03035323 Vehicle-Level Accident Data	24
Table 63. Accident 06030017 Vehicle-Level Accident Data	25
Table 64. Accident 02003748 Vehicle-Level Accident Data	26

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 12.819 to 12.875 (Segment 32983...37628)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **7 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **12.819** to **12.875** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2002	02003748
2003	03035323
2004	04018776
2006	06017134, 06030017
2007	07003266
2008	08013386

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
February	1	0	0	0	0	1	0	0	2	29	8
May	0	0	0	0	0	0	1	0	1	14	9
June	0	0	1	0	1	0	0	0	2	29	9
November	0	1	0	0	1	0	0	0	2	29	8
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
February	07003266, 02003748
May	08013386
June	06017134, 04018776
November	03035323, 06030017

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	0	1	1	0	1	0	0	0	3	43	N/A
Possible Injury	1	0	0	0	0	0	0	0	1	14	N/A
Property-Damage-Only	0	0	0	0	1	1	1	0	3	43	N/A
Total Accidents	1	1	1	0	2	1	1	0	7	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	04018776, 03035323, 06030017
Possible Injury	02003748
Property-Damage-Only	06017134, 08013386, 07003266

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1:00 am to 1:59 am	0	1	0	0	0	0	0	0	1	14	N/A
1:00 pm to 1:59 pm	0	0	0	0	1	0	0	0	1	14	N/A
2:00 pm to 2:59 pm	0	0	1	0	0	0	0	0	1	14	N/A
4:00 pm to 4:59 pm	0	0	0	0	1	0	0	0	1	14	N/A
5:00 pm to 5:59 pm	1	0	0	0	0	0	1	0	2	29	N/A
6:00 pm to 6:59 pm	0	0	0	0	0	1	0	0	1	14	N/A
Total Accidents	1	1	1	0	2	1	1	0	7	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
1:00 am to 1:59 am	03035323
1:00 pm to 1:59 pm	06030017
2:00 pm to 2:59 pm	04018776
4:00 pm to 4:59 pm	06017134
5:00 pm to 5:59 pm	08013386,02003748
6:00 pm to 6:59 pm	07003266

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with fixed object	0	1	0	0	0	0	0	0	1	14	21
Other multiple-vehicle collision	1	0	1	0	2	1	1	0	6	86	49
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with fixed object	03035323
Other multiple-vehicle collision	06017134, 04018776, 08013386, 07003266, 06030017, 02003748

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	1	1	1	0	2	1	1	0	7	100	95
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	1	1	0	2	1	1	0	7	100	99
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	1	1	0	1	1	1	0	6	86	65
Weather conditions	0	0	0	0	1	0	0	0	1	14	20
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	06017134, 04018776, 08013386, 07003266, 03035323, 02003748
Weather conditions	06030017

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	1	1	0	2	1	1	0	7	100	94
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Sunday	0	1	0	0	0	0	0	0	1	14	10
Monday	1	0	0	0	0	1	0	0	2	29	14
Tuesday	0	0	0	0	1	0	0	0	1	14	14
Thursday	0	0	0	0	1	0	1	0	2	29	16
Saturday	0	0	1	0	0	0	0	0	1	14	13
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Sunday	03035323
Monday	07003266, 02003748
Tuesday	06030017
Thursday	06017134, 08013386
Saturday	04018776

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	1	1	0	2	1	1	0	7	100	100
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	1	2	0	0	1	1	1	0	6	43	N/A
25 to 34	1	0	0	0	2	0	0	0	3	21	N/A
35 to 44	0	0	2	0	0	0	1	0	3	21	N/A
55 to 64	0	0	0	0	1	1	0	0	2	14	N/A
Total Vehicles	2	2	2	0	4	2	2	0	14	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	08013386, 07003266, 03035323, 03035323, 06030017, 02003748
25 to 34	06017134, 06017134, 02003748
35 to 44	04018776, 04018776, 08013386
55 to 64	07003266, 06030017

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	1	1	0	2	1	1	0	7	100	86
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Motor vehicle in transport	2	0	2	0	4	2	2	0	12	86	N/A
Utility pole/Light support	0	2	0	0	0	0	0	0	2	14	N/A
Total Vehicles	2	2	2	0	4	2	2	0	14	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Motor vehicle in transport	06017134, 06017134, 04018776, 04018776, 08013386, 08013386, 07003266, 07003266, 06030017, 06030017, 02003748, 02003748
Utility pole/Light support	03035323, 03035323

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Northbound	0	1	0	0	0	0	0	0	1	7	N/A
Southbound	0	1	0	0	0	0	0	0	1	7	N/A
Eastbound	2	0	0	0	2	1	2	0	7	50	N/A
Westbound	0	0	2	0	2	1	0	0	5	36	N/A
Total Vehicles	2	2	2	0	4	2	2	0	14	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Northbound	03035323
Southbound	03035323
Eastbound	06017134, 06017134, 08013386, 08013386, 07003266, 02003748, 02003748
Westbound	04018776, 04018776, 07003266, 06030017, 06030017

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	0	0	1	0	2	0	1	0	4	57	70
Dark-lighted	1	1	0	0	0	1	0	0	3	43	14
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	06017134, 04018776, 08013386, 06030017
Dark-lighted	07003266, 03035323, 02003748

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
2 Vehicles	1	1	1	0	1	1	1	0	6	86	N/A
More than 2 Vehicles	0	0	0	0	1	0	0	0	1	14	N/A
Total Accidents	1	1	1	0	2	1	1	0	7	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
2 Vehicles	04018776, 08013386, 07003266, 03035323, 06030017, 02003748
More than 2 Vehicles	06017134

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	1	1	0	2	1	1	0	7	100	98
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	1	1	1	0	2	1	1	0	7	100	83
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	1	1	0	0	1	1	0	0	4	57	69
Wet	0	0	1	0	1	0	1	0	3	43	15
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	06017134, 07003266, 03035323, 02003748
Wet	04018776, 08013386, 06030017

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	1	0	0	0	0	0	0	1	14	23
No	1	0	1	0	2	1	1	0	6	86	77
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	03035323
No	06017134, 04018776, 08013386, 07003266, 06030017, 02003748

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	1	1	0	2	1	1	0	7	100	100
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	1	1	0	2	1	1	0	7	100	100
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	1	1	2	0	4	0	2	0	10	71	N/A
Light truck, only four tires	1	0	0	0	0	0	0	0	1	7	N/A
Sport utility vehicle	0	1	0	0	0	2	0	0	3	21	N/A
Total Vehicles	2	2	2	0	4	2	2	0	14	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	06017134, 06017134, 04018776, 04018776, 08013386, 08013386, 03035323, 06030017, 06030017, 02003748
Light truck, only four tires	02003748
Sport utility vehicle	07003266, 07003266, 03035323

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	1	1	1	0	2	1	0	0	6	43	N/A
Overtaking/passing	0	0	1	0	0	0	0	0	1	7	N/A
Slowing	1	0	0	0	1	0	1	0	3	21	N/A
Stopped in traffic	0	0	0	0	1	1	1	0	3	21	N/A
Unknown	0	1	0	0	0	0	0	0	1	7	N/A
Total Vehicles	2	2	2	0	4	2	2	0	14	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	06017134, 04018776, 07003266, 03035323, 06030017, 02003748
Overtaking/passing	04018776
Slowing	08013386, 06030017, 02003748
Stopped in traffic	06017134, 08013386, 07003266
Unknown	03035323

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No-turn	1	1	1	0	2	1	1	0	7	100	83
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
No-turn	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	1	1	0	0	1	0	0	0	3	43	60
Cloudy	0	0	1	0	0	1	1	0	3	43	19
Rain	0	0	0	0	1	0	0	0	1	14	9
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	06017134, 03035323, 02003748
Cloudy	04018776, 08013386, 07003266
Rain	06030017

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	1	1	0	2	1	1	0	7	100	98
Total Accidents	1	1	1	0	2	1	1	0	7	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	06017134, 04018776, 08013386, 07003266, 03035323, 06030017, 02003748

2. Route SR S0000101A_, Milepost 12.819 to 12.875

Roadway Segment

Segment ID: 32983...37628
Internal Segment ID: S3738a
Route Number Display Value: SRS0000101A_
Site Subtype: Seg/Urb; 2-lane arterial
Start Location: 12.819
End Location: 12.875
GIS Identifier: 32983
Next Roadway Segment ID: S13192
Previous Roadway Segment ID: S9262
Next Intersection ID: I7596
Previous Intersection ID: I5150
Segment Length: 0.0560 miles
Roadway Class Level 1: Principal arterial-other
Roadway Class Level 2: Principal arterial-other urban
Roadway Class Level 3: Urban two-lane
Number of Through Lanes - Combined: 2
Median Type Level 1: Undivided
Median Type Level 2: Divided
Median Width: 12.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 22,011 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Eastbound
Interchange Influence Area on Mainline Freeway: No
Aggregated Segment IDs: S3738...S10965
Number of Accidents: 7

Geographic Description

Identifier: G344
Route Type: State route
Route Name: S0000101A_
Major Road Name: Amherst St
County: HILLSBOROUGH
District: 5
City/Town: NASHUA
Jurisdiction: Local maintained
Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 12.819 to 12.875 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	1	12.00	Paved	Paved	0.00	0.00		
Direction 2	1	12.00	Paved	Paved	0.00	0.00		

Table 57. Route SR S0000101A_, Milepost 12.819 to 12.875 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	22,011			Growth Factor Applied	
2003	22,011			Growth Factor Applied	
2004	22,011			Growth Factor Applied	
2005	22,011			Growth Factor Applied	
2006	22,011			Growth Factor Applied	
2007	22,011			Growth Factor Applied	
2008	22,011			Growth Factor Applied	
2009	22,011			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 06017134

Accident

Accident ID: 06017134

Internal Accident ID: A61718

Inventory Element: S3738a

Pre-Post Process Inventory Element: S10965

Location: 12.86825

GIS Identifier: 06017134

Accident Date: 2006/06/29

Accident Month: June

Accident Time of Day: 1652

Accident Date Stamp: 06/29/06 16:52:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 4

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Thursday

Table 58. Accident 06017134 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1974/01/20	32
Vehicle 2	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1975/10/29	30

Accident Details: Accident Case ID: 04018776

Accident

Accident ID: 04018776

Internal Accident ID: A20055

Inventory Element: S3738a

Pre-Post Process Inventory Element: S3738

Location: 12.8626

GIS Identifier: 04018776

Accident Date: 2004/06/26

Accident Month: June

Accident Time of Day: 1456

Accident Date Stamp: 06/26/04 14:56:00

Accident Year: 2004

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 2

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Saturday

Table 59. Accident 04018776 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1961/02/27	43
Vehicle 2	Westbound	Overtaking/passing	Passenger car	Motor vehicle in transport	1962/05/04	42

Accident Details: Accident Case ID: 08013386

Accident

Accident ID: 08013386

Internal Accident ID: A101010

Inventory Element: S3738a

Pre-Post Process Inventory Element: S10965

Location: 12.86825

GIS Identifier: 08013386

Accident Date: 2008/05/22

Accident Month: May

Accident Time of Day: 1730

Accident Date Stamp: 05/22/08 17:30:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 60. Accident 08013386 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1987/10/09	20
Vehicle 2	Eastbound	Slowing	Passenger car	Motor vehicle in transport	1964/10/16	43

Accident Details: Accident Case ID: 07003266

Accident

Accident ID: 07003266
 Internal Accident ID: A71747
 Inventory Element: S3738a
 Pre-Post Process Inventory Element: S3738
 Location: 12.8616
 GIS Identifier: 07003266
 Accident Date: 2007/02/26
 Accident Month: February
 Accident Time of Day: 1806
 Accident Date Stamp: 02/26/07 18:06:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 61. Accident 07003266 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1949/09/29	57
Vehicle 2	Eastbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1987/08/09	19

Accident Details: Accident Case ID: 03035323

Accident

Accident ID: 03035323
 Internal Accident ID: A18320
 Inventory Element: S3738a
 Pre-Post Process Inventory Element: S3738
 Location: 12.8588
 GIS Identifier: 03035323
 Accident Date: 2003/11/09
 Accident Month: November
 Accident Time of Day: 0144
 Accident Date Stamp: 11/09/03 01:44:00
 Accident Year: 2003
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with fixed object
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown

Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: Yes
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Sunday

Table 62. Accident 03035323 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Sport utility vehicle	Utility pole/Light support	1980/01/31	23
Vehicle 2	Northbound	Unknown	Passenger car	Utility pole/Light support	1979/03/03	24

Accident Details: Accident Case ID: 06030017

Accident

Accident ID: 06030017
 Internal Accident ID: A66244
 Inventory Element: S3738a
 Pre-Post Process Inventory Element: S10965
 Location: 12.87463
 GIS Identifier: 06030017
 Accident Date: 2006/11/28
 Accident Month: November
 Accident Time of Day: 1319
 Accident Date Stamp: 11/28/06 13:19:00
 Accident Year: 2006
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Rain
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 63. Accident 06030017 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Slowing	Passenger car	Motor vehicle in transport	1943/07/22	63
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1988/06/10	18

Accident Details: Accident Case ID: 02003748

Accident

Accident ID: 02003748
 Internal Accident ID: A1261
 Inventory Element: S3738a
 Pre-Post Process Inventory Element: S3738
 Location: 12.8581
 GIS Identifier: 02003748
 Accident Date: 2002/02/04
 Accident Month: February
 Accident Time of Day: 1700
 Accident Date Stamp: 02/04/02 17:00:00
 Accident Year: 2002
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted

Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 64. Accident 02003748 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1971/02/28	30
Vehicle 2	Eastbound	Slowing	Passenger car	Motor vehicle in transport	1981/03/06	20