

SafetyAnalyst

**Accident Summary for Route SR S0000101A_,
Milepost 9.898 (Intersection 41284)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary 1

 1.1 Accident Case Identifier 1

 1.2 Accident Month 1

 1.3 Accident Severity Level 1 2

 1.4 Accident Time of Day 3

 1.5 Accident Type and Manner of Collision 3

 1.6 Alcohol/Drug Involvement 4

 1.7 Bicycle Indicator 4

 1.8 Contributing Circumstances, Environment 5

 1.9 Contributing Circumstances, Road 5

 1.10 Day of Week 6

 1.11 Divided Highway Flag-Side of Road 7

 1.12 Driver Age 7

 1.13 Driveway Indicator 8

 1.14 First Harmful Event 8

 1.15 Initial Direction of Travel 9

 1.16 Light Condition 10

 1.17 Number of Vehicles Involved 10

 1.18 Pedestrian Indicator 11

 1.19 Relationship to Junction 11

 1.20 Roadway Surface Condition 12

 1.21 Run-Off Road Indicator 12

 1.22 School Bus Related 13

 1.23 Tow-Away Indicator 13

 1.24 Vehicle Configuration 14

 1.25 Vehicle Maneuver/Action 14

 1.26 Vehicle Turning Movement 15

 1.27 Weather Condition 16

 1.28 Work Zone Related 16

2. Route SR S0000101A_, Milepost 9.898 18

3. Accident Case Details 21

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	3
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	4
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	4
Table 12. Bicycle Indicator	5
Table 13. Bicycle Indicator (Accident Case Identifier)	5
Table 14. Contributing Circumstances, Environment	5
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	5
Table 16. Contributing Circumstances, Road	6
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	6
Table 18. Day of Week	6
Table 19. Day of Week (Accident Case Identifier)	6
Table 20. Divided Highway Flag-Side of Road	7
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	7
Table 22. Driver Age in Years	7
Table 23. Driver Age in Years (Accident Case Identifier)	8
Table 24. Driveway Indicator	8
Table 25. Driveway Indicator (Accident Case Identifier)	8
Table 26. First Harmful Event	8
Table 27. First Harmful Event (Accident Case Identifier)	9
Table 28. Initial Direction of Travel	9
Table 29. Initial Direction of Travel (Accident Case Identifier)	9
Table 30. Light Condition	10
Table 31. Light Condition (Accident Case Identifier)	10
Table 32. Number of Vehicles Involved	10
Table 33. Number of Vehicles Involved (Accident Case Identifier)	11
Table 34. Pedestrian Indicator	11
Table 35. Pedestrian Indicator (Accident Case Identifier)	11
Table 36. Relationship to Junction	11
Table 37. Relationship to Junction (Accident Case Identifier)	12
Table 38. Roadway Surface Condition	12

Table 39. Roadway Surface Condition (Accident Case Identifier)	12
Table 40. Run-Off Road Indicator	12
Table 41. Run-Off Road Indicator (Accident Case Identifier)	13
Table 42. School Bus Related	13
Table 43. School Bus Related (Accident Case Identifier)	13
Table 44. Tow-Away Indicator	13
Table 45. Tow-Away Indicator (Accident Case Identifier)	14
Table 46. Vehicle Configuration	14
Table 47. Vehicle Configuration (Accident Case Identifier)	14
Table 48. Vehicle Maneuver/Action	15
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	15
Table 50. Vehicle Turning Movement	15
Table 51. Vehicle Turning Movement (Accident Case Identifier)	16
Table 52. Weather Condition	16
Table 53. Weather Condition (Accident Case Identifier)	16
Table 54. Work Zone Related	17
Table 55. Work Zone Related (Accident Case Identifier)	17
Table 56. Route SR S0000101A_, Milepost 9.898 Major Road Annual Traffic	19
Table 57. Route SR S0000101A_, Milepost 9.898 Minor Road Annual Traffic	19
Table 58. Accident 09027162 Vehicle-Level Accident Data	22
Table 59. Accident 06012512 Vehicle-Level Accident Data	23
Table 60. Accident 09021591 Vehicle-Level Accident Data	24
Table 61. Accident 04034030 Vehicle-Level Accident Data	25
Table 62. Accident 09015969 Vehicle-Level Accident Data	26
Table 63. Accident 07027050 Vehicle-Level Accident Data	27
Table 64. Accident 08028384 Vehicle-Level Accident Data	28
Table 65. Accident 04022982 Vehicle-Level Accident Data	29
Table 66. Accident 05019646 Vehicle-Level Accident Data	30
Table 67. Accident 02027513 Vehicle-Level Accident Data	31

1. Accident Summary

This is a summary of the accident data associated with the following Intersection from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 9.898 (Intersection 41284)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **10 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2002	02027513
2004	04034030, 04022982
2005	05019646
2006	06012512
2007	07027050
2008	08028384
2009	09027162, 09021591, 09015969

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
May	0	0	0	0	1	0	0	0	1	10	8
June	0	0	0	0	0	0	0	1	1	10	9
July	0	0	0	1	0	0	0	0	1	10	9
August	0	0	1	0	0	0	0	1	2	20	9
October	1	0	0	0	0	1	0	0	2	20	9
November	0	0	0	0	0	0	1	1	2	20	8
December	0	0	1	0	0	0	0	0	1	10	9
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
May	06012512
June	09015969
July	05019646
August	09021591, 04022982
October	07027050, 02027513
November	09027162, 08028384
December	04034030

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	0	0	0	0	0	0	1	1	2	20	N/A
Possible Injury	1	0	2	1	0	0	0	0	4	40	N/A
Property-Damage-Only	0	0	0	0	1	1	0	2	4	40	N/A
Total Accidents	1	0	2	1	1	1	1	3	10	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	09021591, 08028384
Possible Injury	04034030, 04022982, 05019646, 02027513
Property-Damage-Only	09027162, 06012512, 09015969, 07027050

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
10:00 am to 10:59 am	0	0	1	0	0	1	0	0	2	20	N/A
11:00 am to 11:59 am	1	0	0	0	0	0	0	0	1	10	N/A
3:00 pm to 3:59 pm	0	0	1	0	0	0	0	0	1	10	N/A
6:00 pm to 6:59 pm	0	0	0	0	0	0	0	1	1	10	N/A
8:00 pm to 8:59 pm	0	0	0	0	0	0	1	2	3	30	N/A
9:00 pm to 9:59 pm	0	0	0	1	1	0	0	0	2	20	N/A
Total Accidents	1	0	2	1	1	1	1	3	10	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
10:00 am to 10:59 am	07027050, 04022982
11:00 am to 11:59 am	02027513
3:00 pm to 3:59 pm	04034030
6:00 pm to 6:59 pm	09027162
8:00 pm to 8:59 pm	09021591, 09015969, 08028384
9:00 pm to 9:59 pm	06012512, 05019646

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Rear-end	0	0	1	0	0	0	0	0	1	10	16
Other multiple-vehicle collision	1	0	1	1	1	1	1	3	9	90	65
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Rear-end	04022982
Other multiple-vehicle collision	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 05019646, 02027513

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	1	0	2	1	1	1	1	3	10	100	98
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	0	2	1	1	1	1	3	10	100	99
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	0	2	1	1	1	1	2	9	90	73
Weather conditions	0	0	0	0	0	0	0	1	1	10	15
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513
Weather conditions	09027162

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	0	2	1	1	1	1	3	10	100	95
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Sunday	0	0	1	1	0	0	0	1	3	30	8
Monday	0	0	0	0	0	0	1	0	1	10	15
Tuesday	0	0	0	0	1	0	0	0	1	10	15
Wednesday	1	0	1	0	0	0	0	1	3	30	14
Friday	0	0	0	0	0	1	0	0	1	10	19
Saturday	0	0	0	0	0	0	0	1	1	10	13
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Sunday	04034030, 09015969, 05019646
Monday	08028384
Tuesday	06012512
Wednesday	09021591, 04022982, 02027513
Friday	07027050
Saturday	09027162

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	0	2	1	1	1	1	3	10	100	100
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	0	0	2	2	2	1	1	2	10	50	N/A
25 to 34	0	0	0	0	0	0	0	1	1	5	N/A
35 to 44	1	0	0	0	0	0	0	1	2	10	N/A
45 to 54	1	0	2	0	0	1	1	0	5	25	N/A
55 to 64	0	0	0	0	0	0	0	2	2	10	N/A
Total Vehicles	2	0	4	2	2	2	2	6	20	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	06012512, 06012512, 09021591, 04034030, 04034030, 09015969, 07027050, 08028384, 05019646, 05019646
25 to 34	09015969
35 to 44	09021591, 02027513
45 to 54	07027050, 08028384, 04022982, 04022982, 02027513
55 to 64	09027162, 09027162

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	0	2	1	1	1	1	3	10	100	100
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Motor vehicle in transport	2	0	4	2	2	2	2	6	20	100	N/A
Total Vehicles	2	0	4	2	2	2	2	6	20	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Motor vehicle in transport	09027162, 09027162, 06012512, 06012512, 09021591, 09021591, 04034030, 04034030, 09015969, 09015969, 07027050, 07027050, 08028384, 08028384, 04022982, 04022982, 05019646, 05019646, 02027513, 02027513

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Southbound	0	0	0	0	0	0	1	2	3	15	N/A
Eastbound	0	0	2	2	2	0	0	0	6	30	N/A
Westbound	2	0	2	0	0	2	1	4	11	55	N/A
Total Vehicles	2	0	4	2	2	2	2	6	20	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Southbound	09027162, 09021591, 08028384
Eastbound	06012512, 06012512, 04022982, 04022982, 05019646, 05019646
Westbound	09027162, 09021591, 04034030, 04034030, 09015969, 09015969, 07027050, 07027050, 08028384, 02027513, 02027513

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	1	0	2	0	0	1	0	0	4	40	73
Dark-lighted	0	0	0	1	1	0	1	3	6	60	18
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	04034030, 07027050, 04022982, 02027513
Dark-lighted	09027162, 06012512, 09021591, 09015969, 08028384, 05019646

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
2 Vehicles	1	0	2	1	0	0	1	3	8	80	N/A
More than 2 Vehicles	0	0	0	0	1	1	0	0	2	20	N/A
Total Accidents	1	0	2	1	1	1	1	3	10	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
2 Vehicles	09027162, 09021591, 04034030, 09015969, 08028384, 04022982, 05019646, 02027513
More than 2 Vehicles	06012512, 07027050

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	0	2	1	1	1	1	3	10	100	99
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
At intersection	0	0	1	1	0	1	1	2	6	60	74
Intersection-related	1	0	1	0	1	0	0	1	4	40	26
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
At intersection	09021591, 09015969, 07027050, 08028384, 04022982, 05019646
Intersection-related	09027162, 06012512, 04034030, 02027513

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	1	0	2	1	1	1	1	2	9	90	76
Wet	0	0	0	0	0	0	0	1	1	10	18
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513
Wet	09027162

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	0	2	1	1	1	1	3	10	100	98
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	0	2	1	1	1	1	3	10	100	100
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	0	2	1	1	1	1	3	10	100	100
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	09027162, 06012512, 09021591, 04034030, 09015969, 07027050, 08028384, 04022982, 05019646, 02027513

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	1	0	2	2	1	1	1	6	14	70	N/A
Light truck, only four tires	0	0	2	0	0	0	1	0	3	15	N/A
Sport utility vehicle	1	0	0	0	1	0	0	0	2	10	N/A
Motor home/recreational vehicle	0	0	0	0	0	1	0	0	1	5	N/A
Total Vehicles	2	0	4	2	2	2	2	6	20	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	09027162, 09027162, 06012512, 09021591, 09021591, 04034030, 04034030, 09015969, 09015969, 07027050, 08028384, 05019646, 05019646, 02027513
Light truck, only four tires	08028384, 04022982, 04022982
Sport utility vehicle	06012512, 02027513
Motor home/recreational vehicle	07027050

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	1	0	2	2	1	0	1	3	10	50	N/A
Turning left	0	0	0	0	0	0	1	2	3	15	N/A
Slowing	1	0	0	0	0	0	0	0	1	5	N/A
Stopped in traffic	0	0	2	0	1	2	0	0	5	25	N/A
Unknown	0	0	0	0	0	0	0	1	1	5	N/A
Total Vehicles	2	0	4	2	2	2	2	6	20	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	09027162, 06012512, 09021591, 04034030, 09015969, 08028384, 04022982, 05019646, 05019646, 02027513
Turning left	09027162, 09021591, 08028384
Slowing	02027513
Stopped in traffic	06012512, 04034030, 07027050, 07027050, 04022982
Unknown	09015969

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	0	0	0	0	0	0	1	2	3	30	29
No-turn	1	0	2	1	1	1	0	1	7	70	64
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	09027162, 09021591, 08028384
No-turn	06012512, 04034030, 09015969, 07027050, 04022982, 05019646, 02027513

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	0	0	2	1	0	0	1	1	5	50	63
Cloudy	1	0	0	0	1	1	0	1	4	40	22
Rain	0	0	0	0	0	0	0	1	1	10	11
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	09021591, 04034030, 08028384, 04022982, 05019646
Cloudy	06012512, 09015969, 07027050, 02027513
Rain	09027162

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	0	0	0	1	0	0	1	10	2
No	1	0	2	1	1	0	1	3	9	90	98
Total Accidents	1	0	2	1	1	1	1	3	10	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
Yes	07027050
No	09027162, 06012512, 09021591, 04034030, 09015969, 08028384, 04022982, 05019646, 02027513

2. Route SR S0000101A_, Milepost 9.898

Intersection

Intersection ID: 41284

Internal Intersection ID: I2994

Route Number Display Value: SRS0000101A_

Site Subtype: Int/Urb; 3-leg signalized

Location: 9.898

GIS Identifier: 41284

Major Road Direction: East-West

Minor Road Name: Blackstone Dr.

Minor Road Location: 0.0

Intersection Type Level 1: Tee intersection

Intersection Type Level 2: Three-legs

Traffic Control Type at Intersection: Signals semi-actuated (multi-phase)

Growth Factor: 1.0000

Growth Factor Source: Specified

Maximum AADT: 40,194 vehicles per day

Number of Accidents: 10

Geographic Description

Identifier: G344

Route Type: State route

Route Name: S0000101A_

Major Road Name: Amherst St

County: HILLSBOROUGH

District: 5

City/Town: NASHUA

Jurisdiction: Local maintained

Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 9.898 Major Road Annual Traffic

Year	AADT	Volume Source	Comment
2002	40,194	Growth Factor Applied	
2003	40,194	Growth Factor Applied	
2004	40,194	Growth Factor Applied	
2005	40,194	Growth Factor Applied	
2006	40,194	Growth Factor Applied	
2007	40,194	Growth Factor Applied	
2008	40,194	Growth Factor Applied	
2009	40,194	Measured	

Table 57. Route SR S0000101A_, Milepost 9.898 Minor Road Annual Traffic

Year	AADT	Volume Source	Comment
2002	2,498	Growth Factor Applied	
2003	2,498	Growth Factor Applied	
2004	2,498	Growth Factor Applied	
2005	2,498	Growth Factor Applied	
2006	2,498	Growth Factor Applied	
2007	2,498	Growth Factor Applied	
2008	2,498	Growth Factor Applied	
2009	2,498	Measured	

Intersection Leg

Leg ID: 1

Type: Major road, increasing milepost direction

Leg Location: 9.898

Direction: EB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

Intersection Leg

Leg ID: 2

Type: Major road, decreasing milepost direction

Leg Location: 9.898

Direction: WB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

Intersection Leg

Leg ID: 3

Type: Minor road, increasing milepost direction

Leg Location: 0.0

Direction: NB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

3. Accident Case Details

Accident Details: Accident Case ID: 09027162

Accident

Accident ID: 09027162

Internal Accident ID: A139622

Inventory Element: I2994

Location: 0.0189

GIS Identifier: 09027162

Accident Date: 2009/11/14

Accident Month: November

Accident Time of Day: 1855

Accident Date Stamp: 11/14/09 18:55:00

Accident Year: 2009

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Rain

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Weather conditions

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Saturday

Agency Intersection Identifier: 41284

Table 58. Accident 09027162 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Turning left	Passenger car	Motor vehicle in transport	1951/06/15	58
Vehicle 2	Southbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1952/09/23	57

Accident Details: Accident Case ID: 06012512

Accident

Accident ID: 06012512

Internal Accident ID: A56970

Inventory Element: I2994

Location: 9.898

GIS Identifier: 06012512

Accident Date: 2006/05/16

Accident Month: May

Accident Time of Day: 2114

Accident Date Stamp: 05/16/06 21:14:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Cloudy

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Tuesday

Agency Intersection Identifier: 41284

Table 59. Accident 06012512 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1988/09/13	17
Vehicle 2	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1982/12/07	23

Accident Details: Accident Case ID: 09021591

Accident

Accident ID: 09021591

Internal Accident ID: A134489

Inventory Element: I2994

Location: 9.898

GIS Identifier: 09021591

Accident Date: 2009/08/26

Accident Month: August

Accident Time of Day: 2028

Accident Date Stamp: 08/26/09 20:28:00

Accident Year: 2009

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 2

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Wednesday

Agency Intersection Identifier: 41284

Table 60. Accident 09021591 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1991/08/29	17
Vehicle 2	Southbound	Turning left	Passenger car	Motor vehicle in transport	1971/09/13	37

Accident Details: Accident Case ID: 04034030

Accident

Accident ID: 04034030

Internal Accident ID: A25122

Inventory Element: I2994

Location: 9.9264

GIS Identifier: 04034030

Accident Date: 2004/12/05

Accident Month: December

Accident Time of Day: 1523

Accident Date Stamp: 12/05/04 15:23:00

Accident Year: 2004

Accident Severity Level 1: Possible Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 2

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Sunday

Table 61. Accident 04034030 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1984/12/26	19
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1982/04/03	22

Accident Details: Accident Case ID: 09015969

Accident

Accident ID: 09015969
 Internal Accident ID: A128196
 Inventory Element: I2994
 Location: 9.898
 GIS Identifier: 09015969
 Accident Date: 2009/06/28
 Accident Month: June
 Accident Time of Day: 2042
 Accident Date Stamp: 06/28/09 20:42:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Sunday
 Agency Intersection Identifier: 41284

Table 62. Accident 09015969 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Unknown	Passenger car	Motor vehicle in transport	1989/02/16	20
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1974/09/02	34

Accident Details: Accident Case ID: 07027050

Accident

Accident ID: 07027050
 Internal Accident ID: A88693
 Inventory Element: I2994
 Location: 9.898
 GIS Identifier: 07027050
 Accident Date: 2007/10/12
 Accident Month: October
 Accident Time of Day: 1032
 Accident Date Stamp: 10/12/07 10:32:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None

School Bus Related: Unknown
 Work Zone Related: Yes
 Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday
 Agency Intersection Identifier: 41284

Table 63. Accident 07027050 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1988/07/02	19
Vehicle 2	Westbound	Stopped in traffic	Motor home/recreational vehicle	Motor vehicle in transport	1953/08/05	54

Accident Details: Accident Case ID: 08028384

Accident

Accident ID: 08028384
 Internal Accident ID: A113366
 Inventory Element: I2994
 Location: 9.898
 GIS Identifier: 08028384
 Accident Date: 2008/11/10
 Accident Month: November
 Accident Time of Day: 2017
 Accident Date Stamp: 11/10/08 20:17:00
 Accident Year: 2008
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Monday
 Agency Intersection Identifier: 41284

Table 64. Accident 08028384 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1960/12/14	47
Vehicle 2	Southbound	Turning left	Passenger car	Motor vehicle in transport	1989/10/18	19

Accident Details: Accident Case ID: 04022982

Accident

Accident ID: 04022982
 Internal Accident ID: A24927
 Inventory Element: I2994
 Location: 9.898
 GIS Identifier: 04022982
 Accident Date: 2004/08/18
 Accident Month: August
 Accident Time of Day: 1044
 Accident Date Stamp: 08/18/04 10:44:00
 Accident Year: 2004
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: At intersection
 Driveway Indicator: No

Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday
 Agency Intersection Identifier: 41284

Table 65. Accident 04022982 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Light truck, only four tires	Motor vehicle in transport	1957/06/21	47
Vehicle 2	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1951/05/14	53

Accident Details: Accident Case ID: 05019646

Accident

Accident ID: 05019646
 Internal Accident ID: A38718
 Inventory Element: I2994
 Location: 9.898
 GIS Identifier: 05019646
 Accident Date: 2005/07/03
 Accident Month: July
 Accident Time of Day: 2136
 Accident Date Stamp: 07/03/05 21:36:00
 Accident Year: 2005
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0

Number of Non-Fatal Injuries: 1
 Relationship to Junction: At intersection
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Sunday
 Agency Intersection Identifier: 41284

Table 66. Accident 05019646 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1987/08/28	17
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1987/10/06	17

Accident Details: Accident Case ID: 02027513

Accident

Accident ID: 02027513
 Internal Accident ID: A7509
 Inventory Element: I2994
 Location: 9.9122
 GIS Identifier: 02027513
 Accident Date: 2002/10/09
 Accident Month: October
 Accident Time of Day: 1140
 Accident Date Stamp: 10/09/02 11:40:00

Accident Year: 2002
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday
 Agency Intersection Identifier: 41284

Table 67. Accident 02027513 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1965/04/14	37
Vehicle 2	Westbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1955/03/04	47