

SafetyAnalyst

**Accident Summary for Route SR S0000101A_,
Milepost 10.285 to 10.384 (Segment 11120)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary	1
1.1 Accident Case Identifier	1
1.2 Accident Month	1
1.3 Accident Severity Level 1	2
1.4 Accident Time of Day	3
1.5 Accident Type and Manner of Collision	4
1.6 Alcohol/Drug Involvement	4
1.7 Bicycle Indicator	5
1.8 Contributing Circumstances, Environment	5
1.9 Contributing Circumstances, Road	6
1.10 Day of Week	7
1.11 Divided Highway Flag-Side of Road	7
1.12 Driver Age	8
1.13 Driveway Indicator	9
1.14 First Harmful Event	9
1.15 Initial Direction of Travel	10
1.16 Light Condition	11
1.17 Number of Vehicles Involved	12
1.18 Pedestrian Indicator	12
1.19 Relationship to Junction	13
1.20 Roadway Surface Condition	13
1.21 Run-Off Road Indicator	14
1.22 School Bus Related	14
1.23 Tow-Away Indicator	15
1.24 Vehicle Configuration	16
1.25 Vehicle Maneuver/Action	16
1.26 Vehicle Turning Movement	17
1.27 Weather Condition	18
1.28 Work Zone Related	19
2. Route SR S0000101A_, Milepost 10.285 to 10.384	20
3. Accident Case Details	22

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	3
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	4
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	5
Table 12. Bicycle Indicator	5
Table 13. Bicycle Indicator (Accident Case Identifier)	5
Table 14. Contributing Circumstances, Environment	6
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	6
Table 16. Contributing Circumstances, Road	6
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	7
Table 18. Day of Week	7
Table 19. Day of Week (Accident Case Identifier)	7
Table 20. Divided Highway Flag-Side of Road	8
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	8
Table 22. Driver Age in Years	8
Table 23. Driver Age in Years (Accident Case Identifier)	9
Table 24. Driveway Indicator	9
Table 25. Driveway Indicator (Accident Case Identifier)	9
Table 26. First Harmful Event	10
Table 27. First Harmful Event (Accident Case Identifier)	10
Table 28. Initial Direction of Travel	10
Table 29. Initial Direction of Travel (Accident Case Identifier)	11
Table 30. Light Condition	11
Table 31. Light Condition (Accident Case Identifier)	11
Table 32. Number of Vehicles Involved	12
Table 33. Number of Vehicles Involved (Accident Case Identifier)	12
Table 34. Pedestrian Indicator	12
Table 35. Pedestrian Indicator (Accident Case Identifier)	13
Table 36. Relationship to Junction	13
Table 37. Relationship to Junction (Accident Case Identifier)	13
Table 38. Roadway Surface Condition	14

Table 39. Roadway Surface Condition (Accident Case Identifier)	14
Table 40. Run-Off Road Indicator	14
Table 41. Run-Off Road Indicator (Accident Case Identifier)	14
Table 42. School Bus Related	15
Table 43. School Bus Related (Accident Case Identifier)	15
Table 44. Tow-Away Indicator	15
Table 45. Tow-Away Indicator (Accident Case Identifier)	15
Table 46. Vehicle Configuration	16
Table 47. Vehicle Configuration (Accident Case Identifier)	16
Table 48. Vehicle Maneuver/Action	17
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	17
Table 50. Vehicle Turning Movement	18
Table 51. Vehicle Turning Movement (Accident Case Identifier)	18
Table 52. Weather Condition	18
Table 53. Weather Condition (Accident Case Identifier)	18
Table 54. Work Zone Related	19
Table 55. Work Zone Related (Accident Case Identifier)	19
Table 56. Route SR S0000101A_, Milepost 10.285 to 10.384 Directional Attributes	21
Table 57. Route SR S0000101A_, Milepost 10.285 to 10.384 Annual Traffic	21
Table 58. Accident 06028395 Vehicle-Level Accident Data	23
Table 59. Accident 09026231 Vehicle-Level Accident Data	24
Table 60. Accident 07023491 Vehicle-Level Accident Data	25
Table 61. Accident 08003481 Vehicle-Level Accident Data	26
Table 62. Accident 06032057 Vehicle-Level Accident Data	27
Table 63. Accident 09031092 Vehicle-Level Accident Data	28
Table 64. Accident 08018041 Vehicle-Level Accident Data	29
Table 65. Accident 08002126 Vehicle-Level Accident Data	30
Table 66. Accident 02015955 Vehicle-Level Accident Data	31
Table 67. Accident 02028922 Vehicle-Level Accident Data	32
Table 68. Accident 03007549 Vehicle-Level Accident Data	33
Table 69. Accident 03007170 Vehicle-Level Accident Data	34
Table 70. Accident 02018547 Vehicle-Level Accident Data	35
Table 71. Accident 02011438 Vehicle-Level Accident Data	36
Table 72. Accident 08018315 Vehicle-Level Accident Data	37
Table 73. Accident 02024352 Vehicle-Level Accident Data	38
Table 74. Accident 07026193 Vehicle-Level Accident Data	39
Table 75. Accident 03026318 Vehicle-Level Accident Data	40

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 10.285 to 10.384 (Segment 11120)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **18 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **10.285** to **10.384** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2002	02015955, 02028922, 02018547, 02011438, 02024352
2003	03007549, 03007170, 03026318
2006	06028395, 06032057
2007	07023491, 07026193
2008	08003481, 08018041, 08002126, 08018315
2009	09026231, 09031092

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
January	0	0	0	0	0	0	2	0	2	11	9
February	0	2	0	0	0	0	0	0	2	11	8
May	1	0	0	0	0	0	0	0	1	6	8
June	1	0	0	0	0	0	0	0	1	6	8
July	1	0	0	0	0	0	2	0	3	17	8
August	0	1	0	0	0	0	0	0	1	6	9
September	1	0	0	0	0	2	0	0	3	17	9
October	1	0	0	0	0	0	0	0	1	6	8
November	0	0	0	0	1	0	0	1	2	11	8
December	0	0	0	0	1	0	0	1	2	11	11
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
January	08003481, 08002126
February	03007549, 03007170
May	02011438
June	02015955
July	08018041, 02018547, 08018315
August	03026318
September	07023491, 02024352, 07026193
October	02028922
November	06028395, 09026231
December	06032057, 09031092

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	4	2	0	0	0	0	0	0	6	33	N/A
Possible Injury	1	0	0	0	0	0	1	0	2	11	N/A
Property-Damage-Only	0	1	0	0	2	2	3	2	10	56	N/A
Total Accidents	5	3	0	0	2	2	4	2	18	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	02015955, 03007549, 03007170, 02018547, 02011438, 02024352
Possible Injury	08003481, 02028922
Property-Damage-Only	06028395, 09026231, 07023491, 06032057, 09031092, 08018041, 08002126, 08018315, 07026193, 03026318

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1:00 am to 1:59 am	1	0	0	0	0	0	0	0	1	6	N/A
7:00 am to 7:59 am	0	0	0	0	0	0	1	1	2	11	N/A
12:00 pm to 12:59 pm	1	0	0	0	0	0	0	0	1	6	N/A
1:00 pm to 1:59 pm	1	2	0	0	0	1	2	0	6	33	N/A
2:00 pm to 2:59 pm	0	0	0	0	1	0	0	1	2	11	N/A
3:00 pm to 3:59 pm	2	1	0	0	0	0	0	0	3	17	N/A
5:00 pm to 5:59 pm	0	0	0	0	1	1	1	0	3	17	N/A
Total Accidents	5	3	0	0	2	2	4	2	18	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
1:00 am to 1:59 am	02028922
7:00 am to 7:59 am	09026231,08003481
12:00 pm to 12:59 pm	02011438
1:00 pm to 1:59 pm	08018041,08002126, 02015955, 03007549, 03007170, 07026193
2:00 pm to 2:59 pm	06028395,09031092
3:00 pm to 3:59 pm	02018547,02024352, 03026318
5:00 pm to 5:59 pm	07023491,06032057, 08018315

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with bicyclist	1	0	0	0	0	0	0	0	1	6	1
Rear-end	1	3	0	0	0	0	0	0	4	22	16
Angle	0	0	0	0	0	1	0	0	1	6	5
Other multiple-vehicle collision	3	0	0	0	2	1	4	2	12	67	64
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with bicyclist	02024352
Rear-end	03007549, 03007170, 02011438, 03026318
Angle	07023491
Other multiple-vehicle collision	06028395, 09026231, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 02018547, 08018315, 07026193

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	5	3	0	0	2	2	4	2	18	100	97
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	1	0	0	0	0	0	0	0	1	6	1
No	4	3	0	0	2	2	4	2	17	94	99
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	02024352
No	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 07026193, 03026318

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	3	3	0	0	1	2	3	2	14	78	74
Physical obstruction(s)	0	0	0	0	1	0	0	0	1	6	6
Glare	0	0	0	0	0	0	1	0	1	6	1
Unknown	2	0	0	0	0	0	0	0	2	11	5
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	06028395, 09026231, 07023491, 09031092, 08018041, 08002126, 02015955, 03007549, 03007170, 02018547, 02011438, 08018315, 07026193, 03026318
Physical obstruction(s)	06032057
Glare	08003481
Unknown	02028922, 02024352

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	4	3	0	0	2	2	4	2	17	94	94
Unknown	1	0	0	0	0	0	0	0	1	6	3
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318
Unknown	02028922

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Sunday	0	0	0	0	0	1	0	0	1	6	9
Monday	1	1	0	0	0	0	0	1	3	17	13
Tuesday	1	0	0	0	0	0	0	0	1	6	13
Wednesday	2	2	0	0	2	0	1	0	7	39	13
Thursday	1	0	0	0	0	0	2	1	4	22	15
Friday	0	0	0	0	0	1	1	0	2	11	19
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Sunday	07026193
Monday	09026231, 02024352, 03026318
Tuesday	02015955
Wednesday	06028395, 06032057, 02028922, 03007549, 03007170, 02011438, 08018315
Thursday	08003481, 09031092, 08002126, 02018547
Friday	07023491, 08018041

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records

for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	5	3	0	0	2	2	4	2	18	100	100
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	2	3	0	0	0	1	1	0	7	21	N/A
25 to 34	0	3	0	0	1	0	1	1	6	18	N/A
35 to 44	1	0	0	0	1	0	3	1	6	18	N/A
45 to 54	2	0	0	0	1	2	1	0	6	18	N/A
55 to 64	1	0	0	0	1	0	2	2	6	18	N/A
65 to 74	2	0	0	0	0	1	0	0	3	9	N/A
Total Vehicles	8	6	0	0	4	4	8	4	34	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	07023491, 08003481, 03007549, 03007170, 02018547, 02011438, 03026318
25 to 34	06028395, 09026231, 08003481, 03007549, 03007170, 03026318
35 to 44	09026231, 06032057, 08002126, 02028922, 08018315, 08018315
45 to 54	07023491, 06032057, 08002126, 02028922, 02011438, 07026193
55 to 64	06028395, 09031092, 09031092, 08018041, 08018041, 02015955
65 to 74	02015955, 02018547, 07026193

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	4	3	0	0	1	2	4	1	15	83	83
Yes, at driveway	1	0	0	0	1	0	0	1	3	17	17
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	09026231, 07023491, 08003481, 06032057, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02011438, 08018315, 02024352, 07026193, 03026318
Yes, at driveway	06028395, 09031092, 02018547

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Bicyclist	1	0	0	0	0	0	0	0	1	3	N/A
Motor vehicle in transport	8	6	0	0	4	4	8	4	34	97	N/A
Total Vehicles	9	6	0	0	4	4	8	4	35	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Bicyclist	02024352
Motor vehicle in transport	06028395, 06028395, 09026231, 09026231, 07023491, 07023491, 08003481, 08003481, 06032057, 06032057, 09031092, 09031092, 08018041, 08018041, 08002126, 08002126, 02015955, 02015955, 02028922, 02028922, 03007549, 03007549, 03007170, 03007170, 02018547, 02018547, 02011438, 02011438, 08018315, 08018315, 07026193, 07026193, 03026318, 03026318

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Northbound	0	0	0	0	1	0	0	0	1	3	N/A
Southbound	2	0	0	0	1	0	0	1	4	11	N/A
Eastbound	5	4	0	0	1	2	7	3	22	63	N/A
Westbound	0	2	0	0	1	2	0	0	5	14	N/A
Unknown	2	0	0	0	0	0	1	0	3	9	N/A
Total Vehicles	9	6	0	0	4	4	8	4	35	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Northbound	06032057
Southbound	06032057, 09031092, 02018547, 02018547
Eastbound	06028395, 09026231, 09026231, 08003481, 08003481, 09031092, 08018041, 08002126, 08002126, 02015955, 02028922, 02028922, 03007549, 03007549, 03007170, 03007170, 02011438, 02011438, 08018315, 08018315, 07026193, 07026193
Westbound	06028395, 07023491, 07023491, 03026318, 03026318
Unknown	08018041, 02015955, 02024352

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	4	3	0	0	1	2	4	2	16	89	71
Dark-lighted	0	0	0	0	1	0	0	0	1	6	20
Unknown	1	0	0	0	0	0	0	0	1	6	4
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	06028395, 09026231, 07023491, 08003481, 09031092, 08018041, 08002126, 02015955, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318
Dark-lighted	06032057
Unknown	02028922

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1 Vehicle	1	0	0	0	0	0	0	0	1	6	N/A
2 Vehicles	4	1	0	0	2	1	3	2	13	72	N/A
More than 2 Vehicles	0	2	0	0	0	1	1	0	4	22	N/A
Total Accidents	5	3	0	0	2	2	4	2	18	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
1 Vehicle	02024352
2 Vehicles	06028395, 09026231, 08003481, 06032057, 09031092, 08018041, 02015955, 02028922, 02018547, 02011438, 08018315, 07026193, 03026318
More than 2 Vehicles	07023491, 08002126, 03007549, 03007170

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	5	3	0	0	2	2	4	2	18	100	99
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	3	3	0	0	1	2	4	1	14	78	79
At driveway or driveway-related	1	0	0	0	1	0	0	1	3	17	17
Other	1	0	0	0	0	0	0	0	1	6	4
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	09026231, 07023491, 08003481, 06032057, 08018041, 08002126, 02015955, 03007549, 03007170, 02011438, 08018315, 02024352, 07026193, 03026318
At driveway or driveway-related	06028395, 09031092, 02018547
Other	02028922

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	5	1	0	0	2	2	4	2	16	89	76
Wet	0	2	0	0	0	0	0	0	2	11	18
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318
Wet	03007549, 03007170

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	5	3	0	0	2	2	4	2	18	100	94
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a

school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	5	3	0	0	2	2	4	2	18	100	100
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	5	3	0	0	2	2	4	2	18	100	100
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	5	1	0	0	2	3	6	3	20	57	N/A
Light truck, only four tires	1	0	0	0	0	1	1	1	4	11	N/A
Sport utility vehicle	1	5	0	0	2	0	0	0	8	23	N/A
Unknown vehicle configuration	2	0	0	0	0	0	1	0	3	9	N/A
Total Vehicles	9	6	0	0	4	4	8	4	35	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	06028395, 09026231, 07023491, 07023491, 08003481, 08003481, 06032057, 09031092, 09031092, 08018041, 08002126, 02015955, 02028922, 02018547, 02018547, 02011438, 08018315, 08018315, 07026193, 03026318
Light truck, only four tires	09026231, 08002126, 02011438, 07026193
Sport utility vehicle	06028395, 06032057, 02028922, 03007549, 03007549, 03007170, 03007170, 03026318
Unknown vehicle configuration	08018041, 02015955, 02024352

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	2	3	0	0	0	2	4	3	14	40	N/A
Backing	0	0	0	0	1	0	0	0	1	3	N/A
Turning right	1	0	0	0	0	1	0	1	3	9	N/A
Turning left	1	0	0	0	2	0	0	0	3	9	N/A
Slowing	2	1	0	0	0	1	0	0	4	11	N/A
Stopped in traffic	0	2	0	0	1	0	3	0	6	17	N/A
Unknown	3	0	0	0	0	0	1	0	4	11	N/A
Total Vehicles	9	6	0	0	4	4	8	4	35	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	09026231, 09026231, 07023491, 08003481, 09031092, 08018041, 08002126, 02015955, 03007549, 03007170, 02018547, 08018315, 07026193, 03026318
Backing	06032057
Turning right	07023491, 09031092, 02028922
Turning left	06028395, 06028395, 02018547
Slowing	02011438, 02011438, 07026193, 03026318
Stopped in traffic	08003481, 06032057, 08002126, 03007549, 03007170, 08018315
Unknown	08018041, 02015955, 02028922, 02024352

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	1	0	0	0	1	0	0	0	2	11	13
Right turn	1	0	0	0	0	1	0	1	3	17	5
No-turn	3	3	0	0	1	1	4	1	13	72	81
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	06028395, 02018547
Right turn	07023491, 09031092, 02028922
No-turn	09026231, 08003481, 06032057, 08018041, 08002126, 02015955, 03007549, 03007170, 02011438, 08018315, 02024352, 07026193, 03026318

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	5	3	0	0	2	2	4	2	18	100	62
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	5	3	0	0	2	2	4	2	18	100	98
Total Accidents	5	3	0	0	2	2	4	2	18	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	06028395, 09026231, 07023491, 08003481, 06032057, 09031092, 08018041, 08002126, 02015955, 02028922, 03007549, 03007170, 02018547, 02011438, 08018315, 02024352, 07026193, 03026318

2. Route SR S0000101A_, Milepost 10.285 to 10.384

Roadway Segment

Segment ID: 11120
Internal Segment ID: S4672
Route Number Display Value: SRS0000101A_
Site Subtype: Seg/Urb; Multilane divided
Start Location: 10.285
End Location: 10.384
GIS Identifier: 11120
Next Roadway Segment ID: S16023
Previous Roadway Segment ID: S12005
Next Intersection ID: I3653
Previous Intersection ID: I4679
Segment Length: 0.0990 miles
Roadway Class Level 1: Principal arterial-other
Roadway Class Level 2: Principal arterial-other urban
Roadway Class Level 3: Urban multi-lane divided
Number of Through Lanes - Combined: 4
Median Type Level 1: Rigid barrier system
Median Type Level 2: Divided
Median Width: 2.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 40,194 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Eastbound
Interchange Influence Area on Mainline Freeway: No
Number of Accidents: 18

Geographic Description

Identifier: G344
Route Type: State route
Route Name: S0000101A_
Major Road Name: Amherst St
County: HILLSBOROUGH
District: 5
City/Town: NASHUA
Jurisdiction: Local maintained
Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 10.285 to 10.384 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	2	12.00	Paved	Paved	10.00	0.00		
Direction 2	2	12.00	Paved	Paved	10.00	0.00		

Table 57. Route SR S0000101A_, Milepost 10.285 to 10.384 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	40,194			Growth Factor Applied	
2003	40,194			Growth Factor Applied	
2004	40,194			Growth Factor Applied	
2005	40,194			Growth Factor Applied	
2006	40,194			Growth Factor Applied	
2007	40,194			Growth Factor Applied	
2008	40,194			Growth Factor Applied	
2009	40,194			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 06028395

Accident

Accident ID: 06028395

Internal Accident ID: A68979

Inventory Element: S4672

Location: 10.384

GIS Identifier: 06028395

Accident Date: 2006/11/01

Accident Month: November

Accident Time of Day: 1432

Accident Date Stamp: 11/01/06 14:32:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: At driveway or driveway-related

Driveway Indicator: Yes, at driveway

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Wednesday

Table 58. Accident 06028395 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1980/05/09	26
Vehicle 2	Westbound	Turning left	Sport utility vehicle	Motor vehicle in transport	1948/10/27	58

Accident Details: Accident Case ID: 09026231

Accident

Accident ID: 09026231

Internal Accident ID: A135686

Inventory Element: S4672

Location: 10.3231

GIS Identifier: 09026231

Accident Date: 2009/11/02

Accident Month: November

Accident Time of Day: 0751

Accident Date Stamp: 11/02/09 07:51:00

Accident Year: 2009

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Monday

Table 59. Accident 09026231 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1977/06/16	32
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1965/10/19	44

Accident Details: Accident Case ID: 07023491

Accident

Accident ID: 07023491

Internal Accident ID: A89286

Inventory Element: S4672

Location: 10.384

GIS Identifier: 07023491

Accident Date: 2007/09/14

Accident Month: September

Accident Time of Day: 1757

Accident Date Stamp: 09/14/07 17:57:00

Accident Year: 2007

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Angle

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Right turn
 Day of Week: Friday

Table 60. Accident 07023491 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Turning right	Passenger car	Motor vehicle in transport	1960/08/05	47
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1984/05/14	23

Accident Details: Accident Case ID: 08003481

Accident

Accident ID: 08003481
 Internal Accident ID: A95761
 Inventory Element: S4672
 Location: 10.384
 GIS Identifier: 08003481
 Accident Date: 2008/01/10
 Accident Month: January
 Accident Time of Day: 0759
 Accident Date Stamp: 01/10/08 07:59:00
 Accident Year: 2008
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Glare
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No

Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Thursday

Table 61. Accident 08003481 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1983/11/04	24
Vehicle 2	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1978/03/14	29

Accident Details: Accident Case ID: 06032057

Accident

Accident ID: 06032057
Internal Accident ID: A68113
Inventory Element: S4672
Location: 10.384
GIS Identifier: 06032057
Accident Date: 2006/12/20
Accident Month: December
Accident Time of Day: 1718
Accident Date Stamp: 12/20/06 17:18:00
Accident Year: 2006
Accident Severity Level 1: Property-Damage-Only
Number of Fatalities: 0
Number of Non-Fatal Injuries: 0
Relationship to Junction: Non-junction
Driveway Indicator: No
Light Condition: Dark-lighted
Weather Condition: Clear
Roadway Surface Condition: Dry
Accident Type and Manner of Collision: Other multiple-vehicle collision
Contributing Circumstances, Environment: Physical obstruction(s)
Contributing Circumstances, Road: None
School Bus Related: Unknown
Work Zone Related: No
Number of Vehicles Involved: 2
Alcohol/Drug Involvement: Neither alcohol nor other drugs
Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 62. Accident 06032057 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Backing	Sport utility vehicle	Motor vehicle in transport	1952/08/07	54
Vehicle 2	Northbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1965/07/05	41

Accident Details: Accident Case ID: 09031092

Accident

Accident ID: 09031092
 Internal Accident ID: A140119
 Inventory Element: S4672
 Location: 10.384
 GIS Identifier: 09031092
 Accident Date: 2009/12/17
 Accident Month: December
 Accident Time of Day: 1434
 Accident Date Stamp: 12/17/09 14:34:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At driveway or driveway-related
 Driveway Indicator: Yes, at driveway
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs
Tow-Away Indicator: Unknown
Run-Off Road Indicator: No
Pedestrian Indicator: No
Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: Right turn
Day of Week: Thursday

Table 63. Accident 09031092 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1953/10/20	56
Vehicle 2	Eastbound	Turning right	Passenger car	Motor vehicle in transport	1950/04/11	59

Accident Details: Accident Case ID: 08018041

Accident

Accident ID: 08018041
Internal Accident ID: A107750
Inventory Element: S4672
Location: 10.384
GIS Identifier: 08018041
Accident Date: 2008/07/11
Accident Month: July
Accident Time of Day: 1300
Accident Date Stamp: 07/11/08 13:00:00
Accident Year: 2008
Accident Severity Level 1: Property-Damage-Only
Number of Fatalities: 0
Number of Non-Fatal Injuries: 0
Relationship to Junction: Non-junction
Driveway Indicator: No
Light Condition: Daylight
Weather Condition: Clear
Roadway Surface Condition: Dry
Accident Type and Manner of Collision: Other multiple-vehicle collision
Contributing Circumstances, Environment: None
Contributing Circumstances, Road: None
School Bus Related: Unknown

Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 64. Accident 08018041 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1953/04/01	55
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Motor vehicle in transport	1953/04/01	55

Accident Details: Accident Case ID: 08002126

Accident

Accident ID: 08002126
 Internal Accident ID: A99141
 Inventory Element: S4672
 Location: 10.3367
 GIS Identifier: 08002126
 Accident Date: 2008/01/31
 Accident Month: January
 Accident Time of Day: 1321
 Accident Date Stamp: 01/31/08 13:21:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 65. Accident 08002126 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1966/06/24	41
Vehicle 2	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1962/11/02	45

Accident Details: Accident Case ID: 02015955

Accident

Accident ID: 02015955
 Internal Accident ID: A648
 Inventory Element: S4672
 Location: 10.3367
 GIS Identifier: 02015955
 Accident Date: 2002/06/04
 Accident Month: June
 Accident Time of Day: 1342
 Accident Date Stamp: 06/04/02 13:42:00
 Accident Year: 2002
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 66. Accident 02015955 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1934/11/14	67
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Motor vehicle in transport	1944/09/21	57

Accident Details: Accident Case ID: 02028922

Accident

Accident ID: 02028922
 Internal Accident ID: A8880
 Inventory Element: S4672
 Location: 10.384
 GIS Identifier: 02028922
 Accident Date: 2002/10/09
 Accident Month: October
 Accident Time of Day: 0130
 Accident Date Stamp: 10/09/02 01:30:00
 Accident Year: 2002
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Other
 Driveway Indicator: No
 Light Condition: Unknown

Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Unknown
 Contributing Circumstances, Road: Unknown
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Right turn
 Day of Week: Wednesday

Table 67. Accident 02028922 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning right	Passenger car	Motor vehicle in transport	1949/05/28	53
Vehicle 2	Eastbound	Unknown	Sport utility vehicle	Motor vehicle in transport	1961/02/26	41

Accident Details: Accident Case ID: 03007549

Accident

Accident ID: 03007549
 Internal Accident ID: A5500
 Inventory Element: S4672
 Location: 10.2995
 GIS Identifier: 03007549
 Accident Date: 2003/02/19
 Accident Month: February
 Accident Time of Day: 1300
 Accident Date Stamp: 02/19/03 13:00:00
 Accident Year: 2003
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: Non-junction

Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 4
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 68. Accident 03007549 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1970/07/13	32
Vehicle 2	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1979/09/24	23

Accident Details: Accident Case ID: 03007170

Accident

Accident ID: 03007170
 Internal Accident ID: A6448
 Inventory Element: S4672
 Location: 10.2995
 GIS Identifier: 03007170
 Accident Date: 2003/02/19
 Accident Month: February
 Accident Time of Day: 1302
 Accident Date Stamp: 02/19/03 13:02:00
 Accident Year: 2003
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0

Number of Non-Fatal Injuries: 2
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 4
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 69. Accident 03007170 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1970/07/13	32
Vehicle 2	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1979/09/24	23

Accident Details: Accident Case ID: 02018547

Accident

Accident ID: 02018547
 Internal Accident ID: A4026
 Inventory Element: S4672
 Location: 10.384
 GIS Identifier: 02018547
 Accident Date: 2002/07/11
 Accident Month: July
 Accident Time of Day: 1559
 Accident Date Stamp: 07/11/02 15:59:00
 Accident Year: 2002

Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: At driveway or driveway-related
 Driveway Indicator: Yes, at driveway
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Thursday

Table 70. Accident 02018547 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1985/05/17	17
Vehicle 2	Southbound	Turning left	Passenger car	Motor vehicle in transport	1932/06/18	70

Accident Details: Accident Case ID: 02011438

Accident

Accident ID: 02011438
 Internal Accident ID: A104
 Inventory Element: S4672
 Location: 10.2947
 GIS Identifier: 02011438
 Accident Date: 2002/05/01
 Accident Month: May
 Accident Time of Day: 1200

Accident Date Stamp: 05/01/02 12:00:00
 Accident Year: 2002
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 71. Accident 02011438 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Slowing	Passenger car	Motor vehicle in transport	1982/04/24	20
Vehicle 2	Eastbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1952/07/04	49

Accident Details: Accident Case ID: 08018315

Accident

Accident ID: 08018315
 Internal Accident ID: A107426
 Inventory Element: S4672
 Location: 10.3461
 GIS Identifier: 08018315
 Accident Date: 2008/07/16

Accident Month: July
 Accident Time of Day: 1724
 Accident Date Stamp: 07/16/08 17:24:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 72. Accident 08018315 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1965/01/20	43
Vehicle 2	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1972/12/14	35

Accident Details: Accident Case ID: 02024352

Accident

Accident ID: 02024352
 Internal Accident ID: A751
 Inventory Element: S4672
 Location: 10.384

GIS Identifier: 02024352
 Accident Date: 2002/09/09
 Accident Month: September
 Accident Time of Day: 1537
 Accident Date Stamp: 09/09/02 15:37:00
 Accident Year: 2002
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with bicyclist
 Contributing Circumstances, Environment: Unknown
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: Yes
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 73. Accident 02024352 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Unknown	Unknown	Unknown vehicle configuration	Bicyclist		
Vehicle 2	Northbound	Movements essentially straight ahead	Motorcycle/Moped	Bicyclist	1976/08/12	26

Accident Details: Accident Case ID: 07026193

Accident

Accident ID: 07026193

Internal Accident ID: A87392

Inventory Element: S4672
 Location: 10.28525
 GIS Identifier: 07026193
 Accident Date: 2007/09/30
 Accident Month: September
 Accident Time of Day: 1315
 Accident Date Stamp: 09/30/07 13:15:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Sunday

Table 74. Accident 07026193 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1957/06/27	50
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1941/04/26	66

Accident Details: Accident Case ID: 03026318

Accident

Accident ID: 03026318
 Internal Accident ID: A14889
 Inventory Element: S4672
 Location: 10.3651
 GIS Identifier: 03026318
 Accident Date: 2003/08/25
 Accident Month: August
 Accident Time of Day: 1534
 Accident Date Stamp: 08/25/03 15:34:00
 Accident Year: 2003
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 75. Accident 03026318 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1972/07/27	31
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1983/08/16	20