

SafetyAnalyst

**Accident Summary for Route SR S0000101A_,
Milepost 11.494 to 11.568 (Segment 1617)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary 1

 1.1 Accident Case Identifier 1

 1.2 Accident Month 1

 1.3 Accident Severity Level 1 2

 1.4 Accident Time of Day 2

 1.5 Accident Type and Manner of Collision 3

 1.6 Alcohol/Drug Involvement 3

 1.7 Bicycle Indicator 4

 1.8 Contributing Circumstances, Environment 4

 1.9 Contributing Circumstances, Road 5

 1.10 Day of Week 5

 1.11 Divided Highway Flag-Side of Road 6

 1.12 Driver Age 6

 1.13 Driveway Indicator 7

 1.14 First Harmful Event 8

 1.15 Initial Direction of Travel 8

 1.16 Light Condition 9

 1.17 Number of Vehicles Involved 9

 1.18 Pedestrian Indicator 10

 1.19 Relationship to Junction 10

 1.20 Roadway Surface Condition 11

 1.21 Run-Off Road Indicator 11

 1.22 School Bus Related 12

 1.23 Tow-Away Indicator 12

 1.24 Vehicle Configuration 13

 1.25 Vehicle Maneuver/Action 13

 1.26 Vehicle Turning Movement 14

 1.27 Weather Condition 14

 1.28 Work Zone Related 15

2. Route SR S0000101A_, Milepost 11.494 to 11.568 16

3. Accident Case Details 18

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	1
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	2
Table 6. Accident Time of Day	2
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	3
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	3
Table 10. Alcohol/Drug Involvement	3
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	4
Table 12. Bicycle Indicator	4
Table 13. Bicycle Indicator (Accident Case Identifier)	4
Table 14. Contributing Circumstances, Environment	4
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	5
Table 16. Contributing Circumstances, Road	5
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	5
Table 18. Day of Week	5
Table 19. Day of Week (Accident Case Identifier)	6
Table 20. Divided Highway Flag-Side of Road	6
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	6
Table 22. Driver Age in Years	7
Table 23. Driver Age in Years (Accident Case Identifier)	7
Table 24. Driveway Indicator	7
Table 25. Driveway Indicator (Accident Case Identifier)	7
Table 26. First Harmful Event	8
Table 27. First Harmful Event (Accident Case Identifier)	8
Table 28. Initial Direction of Travel	8
Table 29. Initial Direction of Travel (Accident Case Identifier)	9
Table 30. Light Condition	9
Table 31. Light Condition (Accident Case Identifier)	9
Table 32. Number of Vehicles Involved	9
Table 33. Number of Vehicles Involved (Accident Case Identifier)	10
Table 34. Pedestrian Indicator	10
Table 35. Pedestrian Indicator (Accident Case Identifier)	10
Table 36. Relationship to Junction	10
Table 37. Relationship to Junction (Accident Case Identifier)	11
Table 38. Roadway Surface Condition	11

Table 39. Roadway Surface Condition (Accident Case Identifier)	11
Table 40. Run-Off Road Indicator	11
Table 41. Run-Off Road Indicator (Accident Case Identifier)	12
Table 42. School Bus Related	12
Table 43. School Bus Related (Accident Case Identifier)	12
Table 44. Tow-Away Indicator	12
Table 45. Tow-Away Indicator (Accident Case Identifier)	13
Table 46. Vehicle Configuration	13
Table 47. Vehicle Configuration (Accident Case Identifier)	13
Table 48. Vehicle Maneuver/Action	13
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	14
Table 50. Vehicle Turning Movement	14
Table 51. Vehicle Turning Movement (Accident Case Identifier)	14
Table 52. Weather Condition	15
Table 53. Weather Condition (Accident Case Identifier)	15
Table 54. Work Zone Related	15
Table 55. Work Zone Related (Accident Case Identifier)	15
Table 56. Route SR S0000101A_, Milepost 11.494 to 11.568 Directional Attributes	17
Table 57. Route SR S0000101A_, Milepost 11.494 to 11.568 Annual Traffic	17
Table 58. Accident 07011654 Vehicle-Level Accident Data	19
Table 59. Accident 07021547 Vehicle-Level Accident Data	20
Table 60. Accident 07009519 Vehicle-Level Accident Data	21
Table 61. Accident 06028386 Vehicle-Level Accident Data	22

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 11.494 to 11.568 (Segment 1617)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **4 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **11.494** to **11.568** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2006	06028386
2007	07011654, 07021547, 07009519

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
April	0	0	0	0	0	2	0	0	2	50	7
August	0	0	0	0	0	1	0	0	1	25	9
November	0	0	0	0	1	0	0	0	1	25	8
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
April	07011654, 07009519
August	07021547
November	06028386

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapitating Injury	0	0	0	0	0	1	0	0	1	25	N/A
Property-Damage-Only	0	0	0	0	1	2	0	0	3	75	N/A
Total Accidents	0	0	0	0	1	3	0	0	4	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapitating Injury	07009519
Property-Damage-Only	07011654, 07021547, 06028386

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1:00 pm to 1:59 pm	0	0	0	0	1	1	0	0	2	50	N/A
2:00 pm to 2:59 pm	0	0	0	0	0	1	0	0	1	25	N/A
3:00 pm to 3:59 pm	0	0	0	0	0	1	0	0	1	25	N/A
Total Accidents	0	0	0	0	1	3	0	0	4	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
1:00 pm to 1:59 pm	07009519,06028386
2:00 pm to 2:59 pm	07011654
3:00 pm to 3:59 pm	07021547

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Other multiple-vehicle collision	0	0	0	0	1	3	0	0	4	100	64
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Other multiple-vehicle collision	07011654, 07021547, 07009519, 06028386

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	0	0	0	0	1	3	0	0	4	100	97
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	07011654, 07021547, 07009519, 06028386

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	0	0	0	1	3	0	0	4	100	99
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07011654, 07021547, 07009519, 06028386

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	0	0	0	0	0	2	0	0	2	50	74
Weather conditions	0	0	0	0	1	1	0	0	2	50	14
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	07021547, 07009519
Weather conditions	07011654, 06028386

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	0	0	0	0	1	3	0	0	4	100	94
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	07011654, 07021547, 07009519, 06028386

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Monday	0	0	0	0	0	2	0	0	2	50	13
Wednesday	0	0	0	0	1	0	0	0	1	25	13
Saturday	0	0	0	0	0	1	0	0	1	25	18
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Monday	07011654, 07021547
Wednesday	06028386
Saturday	07009519

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	0	0	0	1	3	0	0	4	100	100
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07011654, 07021547, 07009519, 06028386

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	0	0	0	0	1	1	0	0	2	25	N/A
25 to 34	0	0	0	0	0	2	0	0	2	25	N/A
35 to 44	0	0	0	0	0	1	0	0	1	13	N/A
45 to 54	0	0	0	0	1	0	0	0	1	13	N/A
65 to 74	0	0	0	0	0	1	0	0	1	13	N/A
75 to 84	0	0	0	0	0	1	0	0	1	13	N/A
Total Vehicles	0	0	0	0	2	6	0	0	8	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	07011654, 06028386
25 to 34	07011654, 07021547
35 to 44	07009519
45 to 54	06028386
65 to 74	07021547
75 to 84	07009519

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	0	0	0	0	3	0	0	3	75	83
Yes, at driveway	0	0	0	0	1	0	0	0	1	25	17
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07011654, 07021547, 07009519
Yes, at driveway	06028386

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Motor vehicle in transport	0	0	0	0	2	6	0	0	8	100	N/A
Total Vehicles	0	0	0	0	2	6	0	0	8	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Motor vehicle in transport	07011654, 07011654, 07021547, 07021547, 07009519, 07009519, 06028386, 06028386

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Eastbound	0	0	0	0	2	6	0	0	8	100	N/A
Total Vehicles	0	0	0	0	2	6	0	0	8	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Eastbound	07011654, 07011654, 07021547, 07021547, 07009519, 07009519, 06028386, 06028386

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	0	0	0	0	1	3	0	0	4	100	71
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	07011654, 07021547, 07009519, 06028386

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
2 Vehicles	0	0	0	0	1	3	0	0	4	100	N/A
Total Accidents	0	0	0	0	1	3	0	0	4	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
2 Vehicles	07011654, 07021547, 07009519, 06028386

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	0	0	0	1	3	0	0	4	100	99
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07011654, 07021547, 07009519, 06028386

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	0	0	0	0	0	3	0	0	3	75	79
At driveway or driveway-related	0	0	0	0	1	0	0	0	1	25	17
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	07011654, 07021547, 07009519
At driveway or driveway-related	06028386

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	0	0	0	0	0	1	0	0	1	25	76
Wet	0	0	0	0	1	2	0	0	3	75	18
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	07009519
Wet	07011654, 07021547, 06028386

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	0	0	0	1	3	0	0	4	100	94
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07011654, 07021547, 07009519, 06028386

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	0	0	0	1	3	0	0	4	100	100
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07011654, 07021547, 07009519, 06028386

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	0	0	0	1	3	0	0	4	100	100
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07011654, 07021547, 07009519, 06028386

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	0	0	0	0	1	3	0	0	4	50	N/A
Light truck, only four tires	0	0	0	0	1	1	0	0	2	25	N/A
Sport utility vehicle	0	0	0	0	0	2	0	0	2	25	N/A
Total Vehicles	0	0	0	0	2	6	0	0	8	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	07011654, 07021547, 07009519, 06028386
Light truck, only four tires	07011654, 06028386
Sport utility vehicle	07021547, 07009519

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	0	0	0	0	0	1	0	0	1	13	N/A
Slowing	0	0	0	0	2	2	0	0	4	50	N/A
Stopped in traffic	0	0	0	0	0	3	0	0	3	38	N/A
Total Vehicles	0	0	0	0	2	6	0	0	8	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	07009519
Slowing	07011654, 07021547, 06028386, 06028386
Stopped in traffic	07011654, 07021547, 07009519

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No-turn	0	0	0	0	1	3	0	0	4	100	81
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
No-turn	07011654, 07021547, 07009519, 06028386

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	0	0	0	0	0	1	0	0	1	25	62
Cloudy	0	0	0	0	0	1	0	0	1	25	23
Rain	0	0	0	0	1	1	0	0	2	50	11
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	07009519
Cloudy	07021547
Rain	07011654, 06028386

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	0	0	0	1	3	0	0	4	100	98
Total Accidents	0	0	0	0	1	3	0	0	4	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	07011654, 07021547, 07009519, 06028386

2. Route SR S0000101A_, Milepost 11.494 to 11.568

Roadway Segment

Segment ID: 1617
Internal Segment ID: S8203
Route Number Display Value: SRS0000101A_
Site Subtype: Seg/Urb; Multilane divided
Start Location: 11.494
End Location: 11.568
GIS Identifier: 1617
Next Roadway Segment ID: S12562
Previous Roadway Segment ID: S2765
Next Intersection ID: I9554
Previous Intersection ID: I8245
Segment Length: 0.0740 miles
Roadway Class Level 1: Principal arterial-other
Roadway Class Level 2: Principal arterial-other urban
Roadway Class Level 3: Urban multi-lane divided
Number of Through Lanes - Combined: 4
Median Type Level 1: Rigid barrier system
Median Type Level 2: Divided
Median Width: 2.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 37,823 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Eastbound
Interchange Influence Area on Mainline Freeway: No
Number of Accidents: 4

Geographic Description

Identifier: G344
Route Type: State route
Route Name: S0000101A_
Major Road Name: Amherst St
County: HILLSBOROUGH
District: 5
City/Town: NASHUA
Jurisdiction: Local maintained
Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 11.494 to 11.568 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	2	12.00	Paved	Paved	10.00	0.00		
Direction 2	2	12.00	Paved	Paved	10.00	0.00		

Table 57. Route SR S0000101A_, Milepost 11.494 to 11.568 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	37,823			Growth Factor Applied	
2003	37,823			Growth Factor Applied	
2004	37,823			Growth Factor Applied	
2005	37,823			Growth Factor Applied	
2006	37,823			Growth Factor Applied	
2007	37,823			Growth Factor Applied	
2008	37,823			Growth Factor Applied	
2009	37,823			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 07011654

Accident

Accident ID: 07011654

Internal Accident ID: A77772

Inventory Element: S8203

Location: 11.5567

GIS Identifier: 07011654

Accident Date: 2007/04/30

Accident Month: April

Accident Time of Day: 1439

Accident Date Stamp: 04/30/07 14:39:00

Accident Year: 2007

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Rain

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Weather conditions

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Monday

Table 58. Accident 07011654 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Light truck, only four tires	Motor vehicle in transport	1975/10/31	31
Vehicle 2	Eastbound	Slowing	Passenger car	Motor vehicle in transport	1982/07/25	24

Accident Details: Accident Case ID: 07021547

Accident

Accident ID: 07021547

Internal Accident ID: A89157

Inventory Element: S8203

Location: 11.5567

GIS Identifier: 07021547

Accident Date: 2007/08/06

Accident Month: August

Accident Time of Day: 1500

Accident Date Stamp: 08/06/07 15:00:00

Accident Year: 2007

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Monday

Table 59. Accident 07021547 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1976/05/26	31
Vehicle 2	Eastbound	Slowing	Passenger car	Motor vehicle in transport	1938/01/27	69

Accident Details: Accident Case ID: 07009519

Accident

Accident ID: 07009519

Internal Accident ID: A76906

Inventory Element: S8203

Location: 11.5567

GIS Identifier: 07009519

Accident Date: 2007/04/07

Accident Month: April

Accident Time of Day: 1307

Accident Date Stamp: 04/07/07 13:07:00

Accident Year: 2007

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn
 Day of Week: Saturday

Table 60. Accident 07009519 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1965/08/15	41
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1930/11/10	76

Accident Details: Accident Case ID: 06028386

Accident

Accident ID: 06028386
 Internal Accident ID: A69655
 Inventory Element: S8203
 Location: 11.5567
 GIS Identifier: 06028386
 Accident Date: 2006/11/08
 Accident Month: November
 Accident Time of Day: 1340
 Accident Date Stamp: 11/08/06 13:40:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At driveway or driveway-related
 Driveway Indicator: Yes, at driveway
 Light Condition: Daylight
 Weather Condition: Rain
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Wednesday

Table 61. Accident 06028386 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Slowing	Passenger car	Motor vehicle in transport	1955/08/07	51
Vehicle 2	Eastbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1983/06/17	23