

SafetyAnalyst

**Accident Summary for Route SR S0000101A,
Milepost 13.607 to 13.682 (Segment 30324...42685)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary	1
1.1 Accident Case Identifier	1
1.2 Accident Month	1
1.3 Accident Severity Level 1	2
1.4 Accident Time of Day	3
1.5 Accident Type and Manner of Collision	4
1.6 Alcohol/Drug Involvement	5
1.7 Bicycle Indicator	5
1.8 Contributing Circumstances, Environment	6
1.9 Contributing Circumstances, Road	6
1.10 Day of Week	7
1.11 Divided Highway Flag-Side of Road	7
1.12 Driver Age	8
1.13 Driveway Indicator	9
1.14 First Harmful Event	9
1.15 Initial Direction of Travel	10
1.16 Light Condition	11
1.17 Number of Vehicles Involved	11
1.18 Pedestrian Indicator	12
1.19 Relationship to Junction	13
1.20 Roadway Surface Condition	13
1.21 Run-Off Road Indicator	14
1.22 School Bus Related	14
1.23 Tow-Away Indicator	15
1.24 Vehicle Configuration	15
1.25 Vehicle Maneuver/Action	16
1.26 Vehicle Turning Movement	17
1.27 Weather Condition	18
1.28 Work Zone Related	18
2. Route SR S0000101A_, Milepost 13.607 to 13.682	20
3. Accident Case Details	22

List of Tables

Table 1. Accident Case Identifier by Year 1
Table 2. Accident Month 2
Table 3. Accident Month (Accident Case Identifier) 2
Table 4. Accident Severity Level 1 3
Table 5. Accident Severity Level 1 (Accident Case Identifier) 3
Table 6. Accident Time of Day 3
Table 7. Accident Time of Day (Accident Case Identifier) 4
Table 8. Accident Type and Manner of Collision 4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier) 4
Table 10. Alcohol/Drug Involvement 5
Table 11. Alcohol/Drug Involvement (Accident Case Identifier) 5
Table 12. Bicycle Indicator 5
Table 13. Bicycle Indicator (Accident Case Identifier) 6
Table 14. Contributing Circumstances, Environment 6
Table 15. Contributing Circumstances, Environment (Accident Case Identifier) 6
Table 16. Contributing Circumstances, Road 6
Table 17. Contributing Circumstances, Road (Accident Case Identifier) 7
Table 18. Day of Week 7
Table 19. Day of Week (Accident Case Identifier) 7
Table 20. Divided Highway Flag-Side of Road 8
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier) 8
Table 22. Driver Age in Years 8
Table 23. Driver Age in Years (Accident Case Identifier) 9
Table 24. Driveway Indicator 9
Table 25. Driveway Indicator (Accident Case Identifier) 9
Table 26. First Harmful Event 10
Table 27. First Harmful Event (Accident Case Identifier) 10
Table 28. Initial Direction of Travel 10
Table 29. Initial Direction of Travel (Accident Case Identifier) 11
Table 30. Light Condition 11
Table 31. Light Condition (Accident Case Identifier) 11
Table 32. Number of Vehicles Involved 12
Table 33. Number of Vehicles Involved (Accident Case Identifier) 12
Table 34. Pedestrian Indicator 12
Table 35. Pedestrian Indicator (Accident Case Identifier) 12
Table 36. Relationship to Junction 13
Table 37. Relationship to Junction (Accident Case Identifier) 13
Table 38. Roadway Surface Condition 13

Table 39. Roadway Surface Condition (Accident Case Identifier)	14
Table 40. Run-Off Road Indicator	14
Table 41. Run-Off Road Indicator (Accident Case Identifier)	14
Table 42. School Bus Related	15
Table 43. School Bus Related (Accident Case Identifier)	15
Table 44. Tow-Away Indicator	15
Table 45. Tow-Away Indicator (Accident Case Identifier)	15
Table 46. Vehicle Configuration	16
Table 47. Vehicle Configuration (Accident Case Identifier)	16
Table 48. Vehicle Maneuver/Action	16
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	17
Table 50. Vehicle Turning Movement	17
Table 51. Vehicle Turning Movement (Accident Case Identifier)	17
Table 52. Weather Condition	18
Table 53. Weather Condition (Accident Case Identifier)	18
Table 54. Work Zone Related	18
Table 55. Work Zone Related (Accident Case Identifier)	19
Table 56. Route SR S0000101A_, Milepost 13.607 to 13.682 Directional Attributes	21
Table 57. Route SR S0000101A_, Milepost 13.607 to 13.682 Annual Traffic	21
Table 58. Accident 07017017 Vehicle-Level Accident Data	23
Table 59. Accident 09026249 Vehicle-Level Accident Data	24
Table 60. Accident 08028309 Vehicle-Level Accident Data	25
Table 61. Accident 06033075 Vehicle-Level Accident Data	26
Table 62. Accident 07032076 Vehicle-Level Accident Data	27
Table 63. Accident 04009259 Vehicle-Level Accident Data	28
Table 64. Accident 07028546 Vehicle-Level Accident Data	29
Table 65. Accident 04002359 Vehicle-Level Accident Data	30
Table 66. Accident 08007357 Vehicle-Level Accident Data	31
Table 67. Accident 07003462 Vehicle-Level Accident Data	32
Table 68. Accident 08016441 Vehicle-Level Accident Data	33
Table 69. Accident 02015482 Vehicle-Level Accident Data	34
Table 70. Accident 03026372 Vehicle-Level Accident Data	36
Table 71. Accident 07013460 Vehicle-Level Accident Data	37
Table 72. Accident 06024487 Vehicle-Level Accident Data	38

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 13.607 to 13.682 (Segment 30324...42685)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **15 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **13.607** to **13.682** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2002	02015482
2003	03026372
2004	04009259, 04002359
2006	06033075, 06024487
2007	07017017, 07032076, 07028546, 07003462, 07013460
2008	08028309, 08007357, 08016441
2009	09026249

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
January	0	0	1	0	0	1	0	0	2	13	10
March	0	0	0	0	0	0	1	0	1	7	8
April	0	0	1	0	0	0	0	0	1	7	7
May	0	0	0	0	0	2	0	0	2	13	9
June	1	0	0	0	0	0	0	0	1	7	9
July	0	0	0	0	0	0	1	0	1	7	8
August	0	1	0	0	0	0	0	0	1	7	8
September	0	0	0	0	1	0	0	0	1	7	8
October	0	0	0	0	0	1	0	1	2	13	8
November	0	0	0	0	0	1	1	0	2	13	8
December	0	0	0	0	1	0	0	0	1	7	9
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
January	04002359, 07003462
March	08007357
April	04009259
May	07017017, 07013460
June	02015482
July	08016441
August	03026372
September	06024487
October	09026249, 07028546
November	08028309, 07032076
December	06033075

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Severe Injury	1	0	0	0	0	0	0	0	1	7	N/A
Non-Incapacitating Injury	0	0	1	0	1	2	0	1	5	33	N/A
Possible Injury	0	0	1	0	0	0	0	0	1	7	N/A
Property-Damage-Only	0	1	0	0	1	3	3	0	8	53	N/A
Total Accidents	1	1	2	0	2	5	3	1	15	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Severe Injury	02015482
Non-Incapacitating Injury	07017017, 09026249, 07032076, 04002359, 06024487
Possible Injury	04009259
Property-Damage-Only	08028309, 06033075, 07028546, 08007357, 07003462, 08016441, 03026372, 07013460

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1:00 am to 1:59 am	0	0	0	0	0	1	0	0	1	7	N/A
7:00 am to 7:59 am	0	0	0	0	1	0	0	1	2	13	N/A
9:00 am to 9:59 am	0	0	0	0	1	0	0	0	1	7	N/A
11:00 am to 11:59 am	1	0	0	0	0	1	0	0	2	13	N/A
12:00 pm to 12:59 pm	0	0	0	0	0	0	1	0	1	7	N/A
1:00 pm to 1:59 pm	0	1	0	0	0	0	0	0	1	7	N/A
2:00 pm to 2:59 pm	0	0	0	0	0	1	0	0	1	7	N/A
3:00 pm to 3:59 pm	0	0	0	0	0	0	1	0	1	7	N/A
5:00 pm to 5:59 pm	0	0	1	0	0	0	1	0	2	13	N/A
7:00 pm to 7:59 pm	0	0	0	0	0	1	0	0	1	7	N/A
8:00 pm to 8:59 pm	0	0	0	0	0	1	0	0	1	7	N/A
9:00 pm to 9:59 pm	0	0	1	0	0	0	0	0	1	7	N/A
Total Accidents	1	1	2	0	2	5	3	1	15	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
1:00 am to 1:59 am	07017017
7:00 am to 7:59 am	09026249,06024487
9:00 am to 9:59 am	06033075
11:00 am to 11:59 am	02015482, 07013460
12:00 pm to 12:59 pm	08016441
1:00 pm to 1:59 pm	03026372
2:00 pm to 2:59 pm	07003462
3:00 pm to 3:59 pm	08007357
5:00 pm to 5:59 pm	08028309,04002359
7:00 pm to 7:59 pm	07032076
8:00 pm to 8:59 pm	07028546
9:00 pm to 9:59 pm	04009259

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with pedestrian	1	0	2	0	0	0	0	0	3	20	2
Collision with fixed object	0	0	0	0	0	1	0	0	1	7	21
Sideswipe, same direction	0	1	0	0	0	0	0	0	1	7	1
Other multiple-vehicle collision	0	0	0	0	2	4	3	1	10	67	49
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with pedestrian	04009259, 04002359, 02015482
Collision with fixed object	07017017
Sideswipe, same direction	03026372
Other multiple-vehicle collision	09026249, 08028309, 06033075, 07032076, 07028546, 08007357, 07003462, 08016441, 07013460, 06024487

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	1	1	2	0	2	4	3	1	14	93	95
Yes (alcohol and drugs)	0	0	0	0	0	1	0	0	1	7	4
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487
Yes (alcohol and drugs)	07017017

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	1	2	0	2	5	3	1	15	100	99
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07017017, 09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	1	1	0	1	5	1	1	11	73	65
Weather conditions	0	0	0	0	1	0	1	0	2	13	20
Physical obstruction(s)	0	0	1	0	0	0	0	0	1	7	4
Unknown	0	0	0	0	0	0	1	0	1	7	5
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	07017017, 09026249, 07032076, 04009259, 07028546, 08007357, 07003462, 02015482, 03026372, 07013460, 06024487
Weather conditions	08028309, 06033075
Physical obstruction(s)	04002359
Unknown	08016441

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	1	2	0	2	5	3	1	15	100	94
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	07017017, 09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Monday	1	0	0	0	0	0	0	1	2	13	14
Tuesday	0	0	0	0	1	1	0	0	2	13	14
Wednesday	0	0	0	0	0	1	0	0	1	7	15
Thursday	0	1	2	0	0	2	0	0	5	33	16
Friday	0	0	0	0	1	1	2	0	4	27	18
Saturday	0	0	0	0	0	0	1	0	1	7	13
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Monday	09026249, 02015482
Tuesday	06033075, 07032076
Wednesday	07017017
Thursday	04009259, 07028546, 04002359, 03026372, 07013460
Friday	08007357, 07003462, 08016441, 06024487
Saturday	08028309

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided

highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	1	2	0	2	5	3	1	15	100	100
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07017017, 09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	0	0	2	0	2	5	1	2	12	48	N/A
25 to 34	0	1	0	0	0	2	2	0	5	20	N/A
35 to 44	1	1	0	0	0	2	0	0	4	16	N/A
45 to 54	0	0	0	0	2	1	0	0	3	12	N/A
55 to 64	0	0	0	0	0	0	1	0	1	4	N/A
Total Vehicles	1	2	2	0	4	10	4	2	25	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	09026249, 09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 07003462, 07003462, 07013460, 06024487
25 to 34	07017017, 07017017, 08007357, 08007357, 03026372
35 to 44	07032076, 02015482, 03026372, 07013460
45 to 54	06033075, 07028546, 06024487
55 to 64	08028309

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	1	2	0	1	4	3	1	13	87	86
Yes, at driveway	0	0	0	0	1	1	0	0	2	13	14
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07017017, 09026249, 08028309, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487
Yes, at driveway	06033075, 07032076

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Pedestrian	1	0	2	0	0	0	0	0	3	11	N/A
Motor vehicle in transport	0	2	0	0	4	8	6	2	22	81	N/A
Utility pole/Light support	0	0	0	0	0	2	0	0	2	7	N/A
Total Vehicles	1	2	2	0	4	10	6	2	27	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Pedestrian	04009259, 04002359, 02015482
Motor vehicle in transport	09026249, 09026249, 08028309, 08028309, 06033075, 06033075, 07032076, 07032076, 07028546, 07028546, 08007357, 08007357, 07003462, 07003462, 08016441, 08016441, 03026372, 03026372, 07013460, 07013460, 06024487, 06024487
Utility pole/Light support	07017017, 07017017

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Northbound	1	0	0	0	1	0	0	0	2	7	N/A
Southbound	0	0	0	0	0	1	0	0	1	4	N/A
Eastbound	0	2	0	0	2	4	2	1	11	41	N/A
Westbound	0	0	2	0	1	4	0	1	8	30	N/A
Unknown	0	0	0	0	0	1	4	0	5	19	N/A
Total Vehicles	1	2	2	0	4	10	6	2	27	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Northbound	06033075, 02015482
Southbound	07028546
Eastbound	09026249, 08028309, 08028309, 06033075, 07003462, 07003462, 03026372, 03026372, 07013460, 07013460, 06024487
Westbound	07017017, 09026249, 07032076, 07032076, 04009259, 07028546, 04002359, 06024487
Unknown	07017017, 08007357, 08007357, 08016441, 08016441

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	1	1	0	0	2	2	2	1	9	60	70
Dark-lighted	0	0	2	0	0	3	1	0	6	40	14
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	09026249, 06033075, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487
Dark-lighted	07017017, 08028309, 07032076, 04009259, 07028546, 04002359

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1 Vehicle	1	0	2	0	0	0	0	0	3	20	N/A
2 Vehicles	0	0	0	0	2	5	2	0	9	60	N/A
More than 2 Vehicles	0	1	0	0	0	0	1	1	3	20	N/A
Total Accidents	1	1	2	0	2	5	3	1	15	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
1 Vehicle	04009259, 04002359, 02015482
2 Vehicles	07017017, 06033075, 07032076, 07028546, 08007357, 07003462, 08016441, 07013460, 06024487
More than 2 Vehicles	09026249, 08028309, 03026372

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	1	0	2	0	0	0	0	0	3	20	2
No	0	1	0	0	2	5	3	1	12	80	98
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	04009259, 04002359, 02015482
No	07017017, 09026249, 08028309, 06033075, 07032076, 07028546, 08007357, 07003462, 08016441, 03026372, 07013460, 06024487

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	1	1	2	0	1	4	3	1	13	87	83
At driveway or driveway-related	0	0	0	0	1	1	0	0	2	13	14
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	07017017, 09026249, 08028309, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487
At driveway or driveway-related	06033075, 07032076

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	1	1	2	0	1	4	2	1	12	80	69
Wet	0	0	0	0	1	1	1	0	3	20	15
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	07017017, 09026249, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487
Wet	08028309, 06033075, 07032076

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	0	0	0	1	0	0	1	7	23
No	1	1	2	0	2	4	3	1	14	93	77
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	07017017
No	09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	1	2	0	2	5	3	1	15	100	100
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07017017, 09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	1	2	0	2	5	3	1	15	100	100
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07017017, 09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	1	0	2	0	3	7	3	2	18	67	N/A
Light truck, only four tires	0	1	0	0	0	1	1	0	3	11	N/A
Sport utility vehicle	0	1	0	0	1	2	0	0	4	15	N/A
Unknown vehicle configuration	0	0	0	0	0	0	2	0	2	7	N/A
Total Vehicles	1	2	2	0	4	10	6	2	27	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	07017017, 09026249, 09026249, 08028309, 08028309, 06033075, 06033075, 07032076, 07032076, 04009259, 07028546, 07028546, 04002359, 08007357, 07003462, 02015482, 07013460, 06024487
Light truck, only four tires	08007357, 07003462, 03026372
Sport utility vehicle	07017017, 03026372, 07013460, 06024487
Unknown vehicle configuration	08016441, 08016441

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	1	0	2	0	2	5	1	2	13	48	N/A
Backing	0	0	0	0	0	0	1	0	1	4	N/A
Changing lanes	0	0	0	0	1	1	0	0	2	7	N/A
Turning left	0	0	0	0	1	0	0	0	1	4	N/A
Parked	0	0	0	0	0	1	2	0	3	11	N/A
Slowing	0	2	0	0	0	1	1	0	4	15	N/A
Stopped in traffic	0	0	0	0	0	1	0	0	1	4	N/A
Unknown	0	0	0	0	0	1	1	0	2	7	N/A
Total Vehicles	1	2	2	0	4	10	6	2	27	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	07017017, 09026249, 09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 07003462, 02015482, 07013460, 06024487
Backing	08007357
Changing lanes	07032076, 06024487
Turning left	06033075
Parked	07017017, 08007357, 08016441
Slowing	08028309, 07003462, 03026372, 03026372
Stopped in traffic	07013460
Unknown	07028546, 08016441

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	0	0	0	0	1	0	0	0	1	7	13
No-turn	1	1	2	0	1	5	3	1	14	93	83
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	06033075
No-turn	07017017, 09026249, 08028309, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	1	1	1	0	1	3	1	1	9	60	60
Cloudy	0	0	1	0	0	2	1	0	4	27	19
Rain	0	0	0	0	1	0	1	0	2	13	9
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	07017017, 09026249, 04009259, 07028546, 08016441, 02015482, 03026372, 07013460, 06024487
Cloudy	07032076, 04002359, 08007357, 07003462
Rain	08028309, 06033075

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	1	2	0	2	5	3	1	15	100	98
Total Accidents	1	1	2	0	2	5	3	1	15	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	07017017, 09026249, 08028309, 06033075, 07032076, 04009259, 07028546, 04002359, 08007357, 07003462, 08016441, 02015482, 03026372, 07013460, 06024487

2. Route SR S0000101A_, Milepost 13.607 to 13.682

Roadway Segment

Segment ID: 30324...42685
Internal Segment ID: S1081a
Route Number Display Value: SRS0000101A_
Site Subtype: Seg/Urb; 2-lane arterial
Start Location: 13.607
End Location: 13.682
GIS Identifier: 30324
Next Roadway Segment ID: S400a
Previous Roadway Segment ID: S7122
Next Intersection ID: I736
Previous Intersection ID: I4900
Segment Length: 0.0750 miles
Roadway Class Level 1: Principal arterial-other
Roadway Class Level 2: Principal arterial-other urban
Roadway Class Level 3: Urban two-lane
Number of Through Lanes - Combined: 2
Median Type Level 1: Undivided
Median Type Level 2: Undivided
Median Width: 0.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 22,233 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Eastbound
Interchange Influence Area on Mainline Freeway: No
Aggregated Segment IDs: S1081...S7049
Number of Accidents: 15

Geographic Description

Identifier: G344
Route Type: State route
Route Name: S0000101A_
Major Road Name: Amherst St
County: HILLSBOROUGH
District: 5
City/Town: NASHUA
Jurisdiction: Local maintained
Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 13.607 to 13.682 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	1	12.00	Paved	Paved	6.00	6.00		
Direction 2	1	12.00	Paved	Paved	6.00	6.00		

Table 57. Route SR S0000101A_, Milepost 13.607 to 13.682 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	22,233			Growth Factor Applied	
2003	22,233			Growth Factor Applied	
2004	22,233			Growth Factor Applied	
2005	22,233			Growth Factor Applied	
2006	22,233			Growth Factor Applied	
2007	22,233			Growth Factor Applied	
2008	22,233			Growth Factor Applied	
2009	22,233			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 07017017

Accident

Accident ID: 07017017

Internal Accident ID: A83562

Inventory Element: S1081a

Pre-Post Process Inventory Element: S7049

Location: 13.6771

GIS Identifier: 07017017

Accident Date: 2007/05/16

Accident Month: May

Accident Time of Day: 0111

Accident Date Stamp: 05/16/07 01:11:00

Accident Year: 2007

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Collision with fixed object

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Yes (alcohol and drugs)

Tow-Away Indicator: Unknown

Run-Off Road Indicator: Yes

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Wednesday

Table 58. Accident 07017017 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Sport utility vehicle	Utility pole/Light support	1981/08/30	25
Vehicle 2	Unknown	Parked	Passenger car	Utility pole/Light support	1981/08/30	25

Accident Details: Accident Case ID: 09026249

Accident

Accident ID: 09026249

Internal Accident ID: A135238

Inventory Element: S1081a

Pre-Post Process Inventory Element: S1081

Location: 13.6168

GIS Identifier: 09026249

Accident Date: 2009/10/26

Accident Month: October

Accident Time of Day: 0749

Accident Date Stamp: 10/26/09 07:49:00

Accident Year: 2009

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 4

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Monday

Table 59. Accident 09026249 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1986/01/07	23
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1991/09/12	18

Accident Details: Accident Case ID: 08028309

Accident

Accident ID: 08028309

Internal Accident ID: A112327

Inventory Element: S1081a

Pre-Post Process Inventory Element: S1081

Location: 13.60738

GIS Identifier: 08028309

Accident Date: 2008/11/15

Accident Month: November

Accident Time of Day: 1702

Accident Date Stamp: 11/15/08 17:02:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Rain

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Weather conditions

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday

Table 60. Accident 08028309 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Slowing	Passenger car	Motor vehicle in transport	1984/07/08	24
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1949/12/18	58

Accident Details: Accident Case ID: 06033075

Accident

Accident ID: 06033075
 Internal Accident ID: A67690
 Inventory Element: S1081a
 Pre-Post Process Inventory Element: S1081
 Location: 13.6182
 GIS Identifier: 06033075
 Accident Date: 2006/12/26
 Accident Month: December
 Accident Time of Day: 0921
 Accident Date Stamp: 12/26/06 09:21:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: At driveway or driveway-related
 Driveway Indicator: Yes, at driveway
 Light Condition: Daylight
 Weather Condition: Rain
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Tuesday

Table 61. Accident 06033075 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Turning left	Passenger car	Motor vehicle in transport	1983/08/19	23
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1953/08/12	53

Accident Details: Accident Case ID: 07032076

Accident

Accident ID: 07032076
 Internal Accident ID: A92027
 Inventory Element: S1081a
 Pre-Post Process Inventory Element: S1081
 Location: 13.6531
 GIS Identifier: 07032076
 Accident Date: 2007/11/20
 Accident Month: November
 Accident Time of Day: 1947
 Accident Date Stamp: 11/20/07 19:47:00
 Accident Year: 2007
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: At driveway or driveway-related
 Driveway Indicator: Yes, at driveway
 Light Condition: Dark-lighted
 Weather Condition: Cloudy
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown

Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 62. Accident 07032076 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1964/06/22	43
Vehicle 2	Westbound	Changing lanes	Passenger car	Motor vehicle in transport	1991/05/28	16

Accident Details: Accident Case ID: 04009259

Accident

Accident ID: 04009259
 Internal Accident ID: A16570
 Inventory Element: S1081a
 Pre-Post Process Inventory Element: S7049
 Location: 13.6775
 GIS Identifier: 04009259
 Accident Date: 2004/04/08
 Accident Month: April
 Accident Time of Day: 2104
 Accident Date Stamp: 04/08/04 21:04:00
 Accident Year: 2004
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with pedestrian

Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: Yes
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 63. Accident 04009259 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Pedestrian	1980/09/02	23
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Pedestrian	1980/09/02	23

Accident Details: Accident Case ID: 07028546

Accident

Accident ID: 07028546
 Internal Accident ID: A89111
 Inventory Element: S1081a
 Pre-Post Process Inventory Element: S1081
 Location: 13.6673
 GIS Identifier: 07028546
 Accident Date: 2007/10/25
 Accident Month: October
 Accident Time of Day: 2014
 Accident Date Stamp: 10/25/07 20:14:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted

Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 64. Accident 07028546 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1959/08/03	48
Vehicle 2	Southbound	Unknown	Passenger car	Motor vehicle in transport	1987/11/12	19

Accident Details: Accident Case ID: 04002359

Accident

Accident ID: 04002359
 Internal Accident ID: A19942
 Inventory Element: S1081a
 Pre-Post Process Inventory Element: S1081
 Location: 13.672
 GIS Identifier: 04002359
 Accident Date: 2004/01/22
 Accident Month: January
 Accident Time of Day: 1758
 Accident Date Stamp: 01/22/04 17:58:00
 Accident Year: 2004
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with pedestrian
 Contributing Circumstances, Environment: Physical obstruction(s)
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: Yes
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 65. Accident 04002359 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Pedestrian	1980/05/15	23
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Pedestrian	1980/05/15	23

Accident Details: Accident Case ID: 08007357

Accident

Accident ID: 08007357
 Internal Accident ID: A98905
 Inventory Element: S1081a
 Pre-Post Process Inventory Element: S1081
 Location: 13.6576
 GIS Identifier: 08007357
 Accident Date: 2008/03/07
 Accident Month: March
 Accident Time of Day: 1558
 Accident Date Stamp: 03/07/08 15:58:00
 Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 66. Accident 08007357 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Unknown	Backing	Passenger car	Motor vehicle in transport	1980/09/16	27
Vehicle 2	Unknown	Parked	Light truck, only four tires	Motor vehicle in transport	1980/09/16	27

Accident Details: Accident Case ID: 07003462

Accident

Accident ID: 07003462
 Internal Accident ID: A71031
 Inventory Element: S1081a
 Pre-Post Process Inventory Element: S1081
 Location: 13.6436
 GIS Identifier: 07003462
 Accident Date: 2007/01/05
 Accident Month: January

Accident Time of Day: 1430
 Accident Date Stamp: 01/05/07 14:30:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 67. Accident 07003462 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1987/11/16	19
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1988/11/13	18

Accident Details: Accident Case ID: 08016441

Accident

Accident ID: 08016441
 Internal Accident ID: A105536
 Inventory Element: S1081a
 Pre-Post Process Inventory Element: S1081
 Location: 13.6651

GIS Identifier: 08016441
 Accident Date: 2008/07/11
 Accident Month: July
 Accident Time of Day: 1211
 Accident Date Stamp: 07/11/08 12:11:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Unknown
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 68. Accident 08016441 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Unknown	Parked	Unknown vehicle configuration	Motor vehicle in transport		
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Motor vehicle in transport		

Accident Details: Accident Case ID: 02015482

Accident

Accident ID: 02015482
 Internal Accident ID: A2992

Inventory Element: S1081a
 Pre-Post Process Inventory Element: S1081
 Location: 13.6682
 GIS Identifier: 02015482
 Accident Date: 2002/06/10
 Accident Month: June
 Accident Time of Day: 1137
 Accident Date Stamp: 06/10/02 11:37:00
 Accident Year: 2002
 Accident Severity Level 1: Severe Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with pedestrian
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: Yes
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 69. Accident 02015482 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Pedestrian	1958/08/04	43
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Pedestrian	1958/08/04	43

Accident Details: Accident Case ID: 03026372

Accident

Accident ID: 03026372
Internal Accident ID: A10737
Inventory Element: S1081a
Pre-Post Process Inventory Element: S1081
Location: 13.672
GIS Identifier: 03026372
Accident Date: 2003/08/21
Accident Month: August
Accident Time of Day: 1315
Accident Date Stamp: 08/21/03 13:15:00
Accident Year: 2003
Accident Severity Level 1: Property-Damage-Only
Number of Fatalities: 0
Number of Non-Fatal Injuries: 0
Relationship to Junction: Non-junction
Driveway Indicator: No
Light Condition: Daylight
Weather Condition: Clear
Roadway Surface Condition: Dry
Accident Type and Manner of Collision: Sideswipe, same direction
Contributing Circumstances, Environment: None
Contributing Circumstances, Road: None
School Bus Related: Unknown
Work Zone Related: No
Number of Vehicles Involved: 3
Alcohol/Drug Involvement: Neither alcohol nor other drugs
Tow-Away Indicator: Unknown
Run-Off Road Indicator: No
Pedestrian Indicator: No
Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Thursday

Table 70. Accident 03026372 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1971/05/31	32
Vehicle 2	Eastbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1958/10/04	44

Accident Details: Accident Case ID: 07013460

Accident

Accident ID: 07013460

Internal Accident ID: A81739

Inventory Element: S1081a

Pre-Post Process Inventory Element: S1081

Location: 13.672

GIS Identifier: 07013460

Accident Date: 2007/05/10

Accident Month: May

Accident Time of Day: 1148

Accident Date Stamp: 05/10/07 11:48:00

Accident Year: 2007

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Thursday

Table 71. Accident 07013460 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1963/04/01	44
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1984/07/18	22

Accident Details: Accident Case ID: 06024487

Accident

Accident ID: 06024487

Internal Accident ID: A67844

Inventory Element: S1081a

Pre-Post Process Inventory Element: S1081

Location: 13.60738

GIS Identifier: 06024487

Accident Date: 2006/09/22

Accident Month: September

Accident Time of Day: 0703

Accident Date Stamp: 09/22/06 07:03:00

Accident Year: 2006

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 2

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Friday

Table 72. Accident 06024487 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1951/10/27	54
Vehicle 2	Westbound	Changing lanes	Passenger car	Motor vehicle in transport	1985/08/22	21