

SafetyAnalyst

**Accident Summary for Route SR S0000101A_,
Milepost 10.041 to 10.184 (Segment 45288)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary 1

 1.1 Accident Case Identifier 1

 1.2 Accident Month 1

 1.3 Accident Severity Level 1 2

 1.4 Accident Time of Day 3

 1.5 Accident Type and Manner of Collision 3

 1.6 Alcohol/Drug Involvement 4

 1.7 Bicycle Indicator 5

 1.8 Contributing Circumstances, Environment 5

 1.9 Contributing Circumstances, Road 6

 1.10 Day of Week 6

 1.11 Divided Highway Flag-Side of Road 7

 1.12 Driver Age 7

 1.13 Driveway Indicator 8

 1.14 First Harmful Event 9

 1.15 Initial Direction of Travel 9

 1.16 Light Condition 10

 1.17 Number of Vehicles Involved 11

 1.18 Pedestrian Indicator 11

 1.19 Relationship to Junction 12

 1.20 Roadway Surface Condition 13

 1.21 Run-Off Road Indicator 13

 1.22 School Bus Related 14

 1.23 Tow-Away Indicator 14

 1.24 Vehicle Configuration 15

 1.25 Vehicle Maneuver/Action 15

 1.26 Vehicle Turning Movement 16

 1.27 Weather Condition 17

 1.28 Work Zone Related 17

2. Route SR S0000101A_, Milepost 10.041 to 10.184 19

3. Accident Case Details 21

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	3
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	4
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	5
Table 12. Bicycle Indicator	5
Table 13. Bicycle Indicator (Accident Case Identifier)	5
Table 14. Contributing Circumstances, Environment	5
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	6
Table 16. Contributing Circumstances, Road	6
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	6
Table 18. Day of Week	6
Table 19. Day of Week (Accident Case Identifier)	7
Table 20. Divided Highway Flag-Side of Road	7
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	7
Table 22. Driver Age in Years	8
Table 23. Driver Age in Years (Accident Case Identifier)	8
Table 24. Driveway Indicator	8
Table 25. Driveway Indicator (Accident Case Identifier)	9
Table 26. First Harmful Event	9
Table 27. First Harmful Event (Accident Case Identifier)	9
Table 28. Initial Direction of Travel	10
Table 29. Initial Direction of Travel (Accident Case Identifier)	10
Table 30. Light Condition	10
Table 31. Light Condition (Accident Case Identifier)	11
Table 32. Number of Vehicles Involved	11
Table 33. Number of Vehicles Involved (Accident Case Identifier)	11
Table 34. Pedestrian Indicator	12
Table 35. Pedestrian Indicator (Accident Case Identifier)	12
Table 36. Relationship to Junction	12
Table 37. Relationship to Junction (Accident Case Identifier)	13
Table 38. Roadway Surface Condition	13

Table 39. Roadway Surface Condition (Accident Case Identifier)	13
Table 40. Run-Off Road Indicator	13
Table 41. Run-Off Road Indicator (Accident Case Identifier)	14
Table 42. School Bus Related	14
Table 43. School Bus Related (Accident Case Identifier)	14
Table 44. Tow-Away Indicator	14
Table 45. Tow-Away Indicator (Accident Case Identifier)	15
Table 46. Vehicle Configuration	15
Table 47. Vehicle Configuration (Accident Case Identifier)	15
Table 48. Vehicle Maneuver/Action	16
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	16
Table 50. Vehicle Turning Movement	16
Table 51. Vehicle Turning Movement (Accident Case Identifier)	17
Table 52. Weather Condition	17
Table 53. Weather Condition (Accident Case Identifier)	17
Table 54. Work Zone Related	18
Table 55. Work Zone Related (Accident Case Identifier)	18
Table 56. Route SR S0000101A_, Milepost 10.041 to 10.184 Directional Attributes	20
Table 57. Route SR S0000101A_, Milepost 10.041 to 10.184 Annual Traffic	20
Table 58. Accident 05029215 Vehicle-Level Accident Data	22
Table 59. Accident 06031025 Vehicle-Level Accident Data	23
Table 60. Accident 06032846 Vehicle-Level Accident Data	24
Table 61. Accident 06006262 Vehicle-Level Accident Data	25
Table 62. Accident 06001878 Vehicle-Level Accident Data	26
Table 63. Accident 06031030 Vehicle-Level Accident Data	27
Table 64. Accident 07025238 Vehicle-Level Accident Data	28
Table 65. Accident 05029462 Vehicle-Level Accident Data	29
Table 66. Accident 03026552 Vehicle-Level Accident Data	30
Table 67. Accident 09028757 Vehicle-Level Accident Data	31
Table 68. Accident 05015766 Vehicle-Level Accident Data	32
Table 69. Accident 04019580 Vehicle-Level Accident Data	33

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 10.041 to 10.184 (Segment 45288)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **12 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **10.041** to **10.184** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2003	03026552
2004	04019580
2005	05029215, 05029462, 05015766
2006	06031025, 06032846, 06006262, 06001878, 06031030
2007	07025238
2009	09028757

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
January	0	0	0	0	1	0	0	0	1	8	9
March	0	0	0	0	1	0	0	0	1	8	7
May	0	0	0	1	0	0	0	0	1	8	8
July	0	0	1	0	0	0	0	0	1	8	8
August	0	1	0	0	0	0	0	0	1	8	9
September	0	0	0	0	0	1	0	0	1	8	9
October	0	0	0	2	0	0	0	0	2	17	8
November	0	0	0	0	2	0	0	1	3	25	8
December	0	0	0	0	1	0	0	0	1	8	11
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
January	06001878
March	06006262
May	05015766
July	04019580
August	03026552
September	07025238
October	05029215, 05029462
November	06031025, 06031030, 09028757
December	06032846

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	0	1	1	3	5	0	0	0	10	83	N/A
Property-Damage-Only	0	0	0	0	0	1	0	1	2	17	N/A
Total Accidents	0	1	1	3	5	1	0	1	12	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 05029462, 03026552, 05015766, 04019580
Property-Damage-Only	07025238, 09028757

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
7:00 am to 7:59 am	0	0	0	1	1	0	0	0	2	17	N/A
10:00 am to 10:59 am	0	0	0	0	1	1	0	0	2	17	N/A
11:00 am to 11:59 am	0	0	0	1	0	0	0	0	1	8	N/A
3:00 pm to 3:59 pm	0	0	0	1	0	0	0	0	1	8	N/A
4:00 pm to 4:59 pm	0	0	0	0	0	0	0	1	1	8	N/A
5:00 pm to 5:59 pm	0	1	0	0	3	0	0	0	4	33	N/A
9:00 pm to 9:59 pm	0	0	1	0	0	0	0	0	1	8	N/A
Total Accidents	0	1	1	3	5	1	0	1	12	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
7:00 am to 7:59 am	06001878,05015766
10:00 am to 10:59 am	06006262, 07025238
11:00 am to 11:59 am	05029215
3:00 pm to 3:59 pm	05029462
4:00 pm to 4:59 pm	09028757
5:00 pm to 5:59 pm	06031025,06032846,06031030, 03026552
9:00 pm to 9:59 pm	04019580

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with bicyclist	0	0	0	1	0	0	0	0	1	8	1
Collision with pedestrian	0	0	1	0	0	0	0	0	1	8	1
Collision with fixed object	0	0	0	0	1	0	0	0	1	8	5
Overturn	0	0	0	0	0	0	0	1	1	8	1
Rear-end	0	1	0	0	0	0	0	0	1	8	16
Other multiple-vehicle collision	0	0	0	2	4	1	0	0	7	58	64
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with bicyclist	05029215
Collision with pedestrian	04019580
Collision with fixed object	06006262
Overturn	09028757
Rear-end	03026552
Other multiple-vehicle collision	06031025, 06032846, 06001878, 06031030, 07025238, 05029462, 05015766

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	0	1	1	3	5	1	0	1	12	100	97
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	0	1	0	0	0	0	1	8	1
No	0	1	1	2	5	1	0	1	11	92	99
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	05029215
No	06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	0	1	1	2	4	1	0	1	10	83	74
Weather conditions	0	0	0	1	0	0	0	0	1	8	14
Glare	0	0	0	0	1	0	0	0	1	8	1
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	05029215, 06031025, 06032846, 06006262, 06031030, 07025238, 05029462, 03026552, 09028757, 04019580
Weather conditions	05015766
Glare	06001878

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	0	1	1	3	5	1	0	1	12	100	94
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Sunday	0	0	0	1	0	0	0	1	2	17	9
Monday	0	0	0	0	1	0	0	0	1	8	13
Tuesday	0	0	1	0	1	1	0	0	3	25	13
Wednesday	0	1	0	1	3	0	0	0	5	42	13
Friday	0	0	0	1	0	0	0	0	1	8	19
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Sunday	09028757, 05015766
Monday	06032846
Tuesday	06001878, 07025238, 04019580
Wednesday	06031025, 06006262, 06031030, 05029462, 03026552
Friday	05029215

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	1	1	3	5	1	0	1	12	100	100
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	0	1	0	2	1	0	0	0	4	19	N/A
25 to 34	0	0	2	0	2	0	0	1	5	24	N/A
35 to 44	0	1	0	2	2	1	0	0	6	29	N/A
45 to 54	0	0	0	1	2	0	0	0	3	14	N/A
55 to 64	0	0	0	1	1	0	0	0	2	10	N/A
65 to 74	0	0	0	0	1	0	0	0	1	5	N/A
Total Vehicles	0	2	2	6	9	1	0	1	21	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	05029215, 06031030, 05029462, 03026552
25 to 34	06031025, 06006262, 09028757, 04019580, 04019580
35 to 44	05029215, 06001878, 06001878, 07025238, 05029462, 03026552
45 to 54	06032846, 06032846, 05015766
55 to 64	06031025, 05015766
65 to 74	06031030

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	1	1	2	5	1	0	1	11	92	83
Yes, at driveway	0	0	0	1	0	0	0	0	1	8	17
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580
Yes, at driveway	05029215

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Pedestrian	0	0	2	0	0	0	0	0	2	9	N/A
Bicyclist	0	0	0	2	0	0	0	0	2	9	N/A
Motor vehicle in transport	0	2	0	4	8	2	0	0	16	73	N/A
Other post, pole, or support	0	0	0	0	1	0	0	0	1	5	N/A
Unknown	0	0	0	0	0	0	0	1	1	5	N/A
Total Vehicles	0	2	2	6	9	2	0	1	22	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Pedestrian	04019580, 04019580
Bicyclist	05029215, 05029215
Motor vehicle in transport	06031025, 06031025, 06032846, 06032846, 06001878, 06001878, 06031030, 06031030, 07025238, 07025238, 05029462, 05029462, 03026552, 03026552, 05015766, 05015766
Other post, pole, or support	06006262
Unknown	09028757

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either

northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Southbound	0	0	1	2	0	0	0	0	3	14	N/A
Eastbound	0	0	1	2	6	0	0	0	9	41	N/A
Westbound	0	2	0	2	3	1	0	1	9	41	N/A
Unknown	0	0	0	0	0	1	0	0	1	5	N/A
Total Vehicles	0	2	2	6	9	2	0	1	22	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Southbound	05029462, 05029462, 04019580
Eastbound	06031025, 06031025, 06032846, 06032846, 06001878, 06001878, 05015766, 05015766, 04019580
Westbound	05029215, 05029215, 06006262, 06031030, 06031030, 07025238, 03026552, 03026552, 09028757
Unknown	07025238

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	0	1	0	3	1	1	0	0	6	50	71
Dawn	0	0	0	0	1	0	0	0	1	8	1
Dusk	0	0	1	0	2	0	0	0	3	25	3
Dark-lighted	0	0	0	0	1	0	0	1	2	17	20
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	05029215, 06006262, 07025238, 05029462, 03026552, 05015766
Dawn	06001878
Dusk	06032846, 06031030, 04019580
Dark-lighted	06031025, 09028757

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1 Vehicle	0	0	0	0	1	0	0	1	2	17	N/A
2 Vehicles	0	1	1	3	1	0	0	0	6	50	N/A
More than 2 Vehicles	0	0	0	0	3	1	0	0	4	33	N/A
Total Accidents	0	1	1	3	5	1	0	1	12	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
1 Vehicle	06006262, 09028757
2 Vehicles	05029215, 06031030, 05029462, 03026552, 05015766, 04019580
More than 2 Vehicles	06031025, 06032846, 06001878, 07025238

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	1	0	0	0	0	0	1	8	1
No	0	1	0	3	5	1	0	1	11	92	99
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	04019580
No	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	0	1	1	1	5	1	0	1	10	83	79
At driveway or driveway-related	0	0	0	1	0	0	0	0	1	8	17
Other	0	0	0	1	0	0	0	0	1	8	4
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 03026552, 09028757, 05015766, 04019580
At driveway or driveway-related	05029215
Other	05029462

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	0	1	1	2	4	1	0	1	10	83	76
Wet	0	0	0	1	1	0	0	0	2	17	18
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	05029215, 06031025, 06032846, 06006262, 06031030, 07025238, 05029462, 03026552, 09028757, 04019580
Wet	06001878, 05015766

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	0	0	1	0	0	0	1	8	6
No	0	1	1	3	4	1	0	1	11	92	94
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	06006262
No	05029215, 06031025, 06032846, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	1	1	3	5	1	0	1	12	100	100
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	0	1	1	3	5	1	0	1	12	100	100
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	0	1	1	3	4	0	0	0	9	41	N/A
Light truck, only four tires	0	0	0	1	4	1	0	0	6	27	N/A
Sport utility vehicle	0	0	0	1	1	0	0	0	2	9	N/A
Motorcycle/Moped	0	1	0	0	0	0	0	1	2	9	N/A
Unknown vehicle configuration	0	0	1	1	0	1	0	0	3	14	N/A
Total Vehicles	0	2	2	6	9	2	0	1	22	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	06032846, 06006262, 06001878, 06031030, 05029462, 05029462, 03026552, 05015766, 04019580
Light truck, only four tires	06031025, 06031025, 06032846, 06031030, 07025238, 05015766
Sport utility vehicle	05029215, 06001878
Motorcycle/Moped	03026552, 09028757
Unknown vehicle configuration	05029215, 07025238, 04019580

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	0	0	1	3	5	0	0	0	9	41	N/A
Overtaking/passing	0	0	0	1	0	0	0	0	1	5	N/A
Entering traffic lane	0	0	0	1	0	0	0	0	1	5	N/A
Slowing	0	2	0	0	2	0	0	0	4	18	N/A
Stopped in traffic	0	0	0	1	2	1	0	0	4	18	N/A
Unknown	0	0	1	0	0	1	0	1	3	14	N/A
Total Vehicles	0	2	2	6	9	2	0	1	22	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	05029215, 06031025, 06006262, 06001878, 06001878, 06031030, 05015766, 05015766, 04019580
Overtaking/passing	05029215
Entering traffic lane	05029462
Slowing	06031025, 06032846, 03026552, 03026552
Stopped in traffic	06032846, 06031030, 07025238, 05029462
Unknown	07025238, 09028757, 04019580

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No-turn	0	1	1	3	5	1	0	1	12	100	81
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
No-turn	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	0	1	1	1	3	1	0	1	8	67	62
Cloudy	0	0	0	1	2	0	0	0	3	25	23
Rain	0	0	0	1	0	0	0	0	1	8	11
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 04019580
Cloudy	05029215, 06031025, 06032846
Rain	05015766

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	0	1	1	3	5	1	0	1	12	100	98
Total Accidents	0	1	1	3	5	1	0	1	12	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	05029215, 06031025, 06032846, 06006262, 06001878, 06031030, 07025238, 05029462, 03026552, 09028757, 05015766, 04019580

2. Route SR S0000101A_, Milepost 10.041 to 10.184

Roadway Segment

Segment ID: 45288
Internal Segment ID: S16180
Route Number Display Value: SRS0000101A_
Site Subtype: Seg/Urb; Multilane divided
Start Location: 10.041
End Location: 10.184
GIS Identifier: 45288
Next Roadway Segment ID: S12005
Previous Roadway Segment ID: S10314
Next Intersection ID: I4370
Previous Intersection ID: I967
Segment Length: 0.1430 miles
Roadway Class Level 1: Principal arterial-other
Roadway Class Level 2: Principal arterial-other urban
Roadway Class Level 3: Urban multi-lane divided
Number of Through Lanes - Combined: 4
Median Type Level 1: Rigid barrier system
Median Type Level 2: Divided
Median Width: 2.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 40,194 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Eastbound
Interchange Influence Area on Mainline Freeway: No
Number of Accidents: 12

Geographic Description

Identifier: G344
Route Type: State route
Route Name: S0000101A_
Major Road Name: Amherst St
County: HILLSBOROUGH
District: 5
City/Town: NASHUA
Jurisdiction: Local maintained
Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 10.041 to 10.184 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	2	12.00	Paved	Paved	10.00	0.00		
Direction 2	2	12.00	Paved	Paved	10.00	0.00		

Table 57. Route SR S0000101A_, Milepost 10.041 to 10.184 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	40,194			Growth Factor Applied	
2003	40,194			Growth Factor Applied	
2004	40,194			Growth Factor Applied	
2005	40,194			Growth Factor Applied	
2006	40,194			Growth Factor Applied	
2007	40,194			Growth Factor Applied	
2008	40,194			Growth Factor Applied	
2009	40,194			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 05029215

Accident

Accident ID: 05029215

Internal Accident ID: A42483

Inventory Element: S16180

Location: 10.0977

GIS Identifier: 05029215

Accident Date: 2005/10/07

Accident Month: October

Accident Time of Day: 1151

Accident Date Stamp: 10/07/05 11:51:00

Accident Year: 2005

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: At driveway or driveway-related

Driveway Indicator: Yes, at driveway

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Collision with bicyclist

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: Yes

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Friday

Table 58. Accident 05029215 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Unknown vehicle configuration	Bicyclist	1966/05/23	39
Vehicle 2	Westbound	Overtaking/passing	Sport utility vehicle	Bicyclist	1987/08/03	18

Accident Details: Accident Case ID: 06031025

Accident

Accident ID: 06031025

Internal Accident ID: A66639

Inventory Element: S16180

Location: 10.1702

GIS Identifier: 06031025

Accident Date: 2006/11/29

Accident Month: November

Accident Time of Day: 1714

Accident Date Stamp: 11/29/06 17:14:00

Accident Year: 2006

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Cloudy

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Wednesday

Table 59. Accident 06031025 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1976/03/18	30
Vehicle 2	Eastbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1944/03/06	62

Accident Details: Accident Case ID: 06032846

Accident

Accident ID: 06032846

Internal Accident ID: A65822

Inventory Element: S16180

Location: 10.1806

GIS Identifier: 06032846

Accident Date: 2006/12/11

Accident Month: December

Accident Time of Day: 1746

Accident Date Stamp: 12/11/06 17:46:00

Accident Year: 2006

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 2

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Dusk

Weather Condition: Cloudy

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Monday

Table 60. Accident 06032846 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1956/11/21	50
Vehicle 2	Eastbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1954/09/14	52

Accident Details: Accident Case ID: 06006262

Accident

Accident ID: 06006262

Internal Accident ID: A52805

Inventory Element: S16180

Location: 10.1178

GIS Identifier: 06006262

Accident Date: 2006/03/08

Accident Month: March

Accident Time of Day: 1013

Accident Date Stamp: 03/08/06 10:13:00

Accident Year: 2006

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Collision with fixed object

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 1

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: Yes

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Wednesday

Table 61. Accident 06006262 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Passenger car	Other post, pole, or support	1978/03/06	28
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Other post, pole, or support		

Accident Details: Accident Case ID: 06001878

Accident

Accident ID: 06001878

Internal Accident ID: A46665

Inventory Element: S16180

Location: 10.1518

GIS Identifier: 06001878

Accident Date: 2006/01/17

Accident Month: January

Accident Time of Day: 0743

Accident Date Stamp: 01/17/06 07:43:00

Accident Year: 2006

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 3

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Dawn

Weather Condition: Clear

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Glare

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 62. Accident 06001878 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1963/04/05	42
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1964/06/14	41

Accident Details: Accident Case ID: 06031030

Accident

Accident ID: 06031030
 Internal Accident ID: A67311
 Inventory Element: S16180
 Location: 10.1768
 GIS Identifier: 06031030
 Accident Date: 2006/11/29
 Accident Month: November
 Accident Time of Day: 1703
 Accident Date Stamp: 11/29/06 17:03:00
 Accident Year: 2006
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dusk
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 63. Accident 06031030 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Light truck, only four tires	Motor vehicle in transport	1935/02/25	71
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1987/12/28	18

Accident Details: Accident Case ID: 07025238

Accident

Accident ID: 07025238
 Internal Accident ID: A85536
 Inventory Element: S16180
 Location: 10.1405
 GIS Identifier: 07025238
 Accident Date: 2007/09/25
 Accident Month: September
 Accident Time of Day: 1038
 Accident Date Stamp: 09/25/07 10:38:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No

Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 64. Accident 07025238 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Light truck, only four tires	Motor vehicle in transport	1968/05/16	39
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Motor vehicle in transport		

Accident Details: Accident Case ID: 05029462

Accident

Accident ID: 05029462
 Internal Accident ID: A40767
 Inventory Element: S16180
 Location: 10.1465
 GIS Identifier: 05029462
 Accident Date: 2005/10/05
 Accident Month: October
 Accident Time of Day: 1534
 Accident Date Stamp: 10/05/05 15:34:00
 Accident Year: 2005
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 2
 Relationship to Junction: Other
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None

School Bus Related: Unknown
Work Zone Related: No
Number of Vehicles Involved: 2
Alcohol/Drug Involvement: Neither alcohol nor other drugs
Tow-Away Indicator: Unknown
Run-Off Road Indicator: No
Pedestrian Indicator: No
Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Wednesday

Table 65. Accident 05029462 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1963/06/01	42
Vehicle 2	Southbound	Entering traffic lane	Passenger car	Motor vehicle in transport	1987/04/05	18

Accident Details: Accident Case ID: 03026552

Accident

Accident ID: 03026552
Internal Accident ID: A11600
Inventory Element: S16180
Location: 10.0636
GIS Identifier: 03026552
Accident Date: 2003/08/27
Accident Month: August
Accident Time of Day: 1714
Accident Date Stamp: 08/27/03 17:14:00
Accident Year: 2003
Accident Severity Level 1: Non-Incapacitating Injury
Number of Fatalities: 0
Number of Non-Fatal Injuries: 1
Relationship to Junction: Non-junction
Driveway Indicator: No
Light Condition: Daylight
Weather Condition: Clear
Roadway Surface Condition: Dry
Accident Type and Manner of Collision: Rear-end

Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 66. Accident 03026552 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Slowing	Motorcycle/Moped	Motor vehicle in transport	1965/03/02	38
Vehicle 2	Westbound	Slowing	Passenger car	Motor vehicle in transport	1983/08/02	20

Accident Details: Accident Case ID: 09028757

Accident

Accident ID: 09028757
 Internal Accident ID: A135857
 Inventory Element: S16180
 Location: 10.0598
 GIS Identifier: 09028757
 Accident Date: 2009/11/22
 Accident Month: November
 Accident Time of Day: 1647
 Accident Date Stamp: 11/22/09 16:47:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear

Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Overturn
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Sunday

Table 67. Accident 09028757 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Unknown	Motorcycle/Moped	Unknown	1979/06/27	30
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Unknown		

Accident Details: Accident Case ID: 05015766

Accident

Accident ID: 05015766
 Internal Accident ID: A36462
 Inventory Element: S16180
 Location: 10.1806
 GIS Identifier: 05015766
 Accident Date: 2005/05/22
 Accident Month: May
 Accident Time of Day: 0713
 Accident Date Stamp: 05/22/05 07:13:00
 Accident Year: 2005
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No

Light Condition: Daylight
 Weather Condition: Rain
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Sunday

Table 68. Accident 05015766 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1958/06/28	46
Vehicle 2	Eastbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1950/03/07	55

Accident Details: Accident Case ID: 04019580

Accident

Accident ID: 04019580
 Internal Accident ID: A23648
 Inventory Element: S16180
 Location: 10.1606
 GIS Identifier: 04019580
 Accident Date: 2004/07/06
 Accident Month: July
 Accident Time of Day: 2101
 Accident Date Stamp: 07/06/04 21:01:00
 Accident Year: 2004
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction
Driveway Indicator: No
Light Condition: Dusk
Weather Condition: Clear
Roadway Surface Condition: Dry
Accident Type and Manner of Collision: Collision with pedestrian
Contributing Circumstances, Environment: None
Contributing Circumstances, Road: None
School Bus Related: Unknown
Work Zone Related: No
Number of Vehicles Involved: 2
Alcohol/Drug Involvement: Neither alcohol nor other drugs
Tow-Away Indicator: Unknown
Run-Off Road Indicator: No
Pedestrian Indicator: Yes
Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Tuesday

Table 69. Accident 04019580 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Passenger car	Pedestrian	1976/10/25	27
Vehicle 2	Eastbound	Unknown	Unknown vehicle configuration	Pedestrian	1976/10/25	27