

SafetyAnalyst

**Accident Summary for Route SR S0000101A_,
Milepost 12.918 to 12.992 (Segment 52660)**

Jun 6, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the Licensee Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary 1

 1.1 Accident Case Identifier 1

 1.2 Accident Month 1

 1.3 Accident Severity Level 1 2

 1.4 Accident Time of Day 2

 1.5 Accident Type and Manner of Collision 3

 1.6 Alcohol/Drug Involvement 4

 1.7 Bicycle Indicator 4

 1.8 Contributing Circumstances, Environment 5

 1.9 Contributing Circumstances, Road 5

 1.10 Day of Week 6

 1.11 Divided Highway Flag-Side of Road 6

 1.12 Driver Age 7

 1.13 Driveway Indicator 8

 1.14 First Harmful Event 8

 1.15 Initial Direction of Travel 9

 1.16 Light Condition 9

 1.17 Number of Vehicles Involved 10

 1.18 Pedestrian Indicator 11

 1.19 Relationship to Junction 11

 1.20 Roadway Surface Condition 12

 1.21 Run-Off Road Indicator 12

 1.22 School Bus Related 13

 1.23 Tow-Away Indicator 13

 1.24 Vehicle Configuration 14

 1.25 Vehicle Maneuver/Action 14

 1.26 Vehicle Turning Movement 15

 1.27 Weather Condition 15

 1.28 Work Zone Related 16

2. Route SR S0000101A_, Milepost 12.918 to 12.992 17

3. Accident Case Details 19

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	1
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	2
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	3
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	4
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	4
Table 12. Bicycle Indicator	4
Table 13. Bicycle Indicator (Accident Case Identifier)	5
Table 14. Contributing Circumstances, Environment	5
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	5
Table 16. Contributing Circumstances, Road	5
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	6
Table 18. Day of Week	6
Table 19. Day of Week (Accident Case Identifier)	6
Table 20. Divided Highway Flag-Side of Road	7
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	7
Table 22. Driver Age in Years	7
Table 23. Driver Age in Years (Accident Case Identifier)	8
Table 24. Driveway Indicator	8
Table 25. Driveway Indicator (Accident Case Identifier)	8
Table 26. First Harmful Event	8
Table 27. First Harmful Event (Accident Case Identifier)	9
Table 28. Initial Direction of Travel	9
Table 29. Initial Direction of Travel (Accident Case Identifier)	9
Table 30. Light Condition	10
Table 31. Light Condition (Accident Case Identifier)	10
Table 32. Number of Vehicles Involved	10
Table 33. Number of Vehicles Involved (Accident Case Identifier)	10
Table 34. Pedestrian Indicator	11
Table 35. Pedestrian Indicator (Accident Case Identifier)	11
Table 36. Relationship to Junction	11
Table 37. Relationship to Junction (Accident Case Identifier)	11
Table 38. Roadway Surface Condition	12

Table 39. Roadway Surface Condition (Accident Case Identifier)	12
Table 40. Run-Off Road Indicator	12
Table 41. Run-Off Road Indicator (Accident Case Identifier)	12
Table 42. School Bus Related	13
Table 43. School Bus Related (Accident Case Identifier)	13
Table 44. Tow-Away Indicator	13
Table 45. Tow-Away Indicator (Accident Case Identifier)	13
Table 46. Vehicle Configuration	14
Table 47. Vehicle Configuration (Accident Case Identifier)	14
Table 48. Vehicle Maneuver/Action	14
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	15
Table 50. Vehicle Turning Movement	15
Table 51. Vehicle Turning Movement (Accident Case Identifier)	15
Table 52. Weather Condition	16
Table 53. Weather Condition (Accident Case Identifier)	16
Table 54. Work Zone Related	16
Table 55. Work Zone Related (Accident Case Identifier)	16
Table 56. Route SR S0000101A_, Milepost 12.918 to 12.992 Directional Attributes	18
Table 57. Route SR S0000101A_, Milepost 12.918 to 12.992 Annual Traffic	18
Table 58. Accident 03007538 Vehicle-Level Accident Data	20
Table 59. Accident 06010771 Vehicle-Level Accident Data	21
Table 60. Accident 03026611 Vehicle-Level Accident Data	22
Table 61. Accident 07018890 Vehicle-Level Accident Data	23
Table 62. Accident 07024030 Vehicle-Level Accident Data	24
Table 63. Accident 02013375 Vehicle-Level Accident Data	25
Table 64. Accident 07022082 Vehicle-Level Accident Data	26

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000101A_, Milepost 12.918 to 12.992 (Segment 52660)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **7 Total Accidents** spanning the dates **1/1/2002** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **12.918** to **12.992** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2002	02013375
2003	03007538, 03026611
2006	06010771
2007	07018890, 07024030, 07022082

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
February	0	1	0	0	0	0	0	0	1	14	8
April	0	0	0	0	0	1	0	0	1	14	7
May	1	0	0	0	1	0	0	0	2	29	9
August	0	1	0	0	0	1	0	0	2	29	8
September	0	0	0	0	0	1	0	0	1	14	8
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
February	03007538
April	07018890
May	06010771, 02013375
August	03026611, 07022082
September	07024030

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	1	2	0	0	0	0	0	0	3	43	N/A
Property-Damage-Only	0	0	0	0	1	3	0	0	4	57	N/A
Total Accidents	1	2	0	0	1	3	0	0	7	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	03007538, 03026611, 02013375
Property-Damage-Only	06010771, 07018890, 07024030, 07022082

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
6:00 am to 6:59 am	0	0	0	0	0	1	0	0	1	14	N/A
8:00 am to 8:59 am	0	1	0	0	0	0	0	0	1	14	N/A
1:00 pm to 1:59 pm	0	0	0	0	0	1	0	0	1	14	N/A
2:00 pm to 2:59 pm	1	0	0	0	0	1	0	0	2	29	N/A
5:00 pm to 5:59 pm	0	1	0	0	1	0	0	0	2	29	N/A
Total Accidents	1	2	0	0	1	3	0	0	7	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
6:00 am to 6:59 am	07018890
8:00 am to 8:59 am	03007538
1:00 pm to 1:59 pm	07022082
2:00 pm to 2:59 pm	07024030,02013375
5:00 pm to 5:59 pm	06010771,03026611

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with fixed object	0	0	0	0	0	1	0	0	1	14	21
Rear-end	1	1	0	0	0	0	0	0	2	29	10
Other multiple-vehicle collision	0	1	0	0	1	2	0	0	4	57	49
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with fixed object	07018890
Rear-end	03026611, 02013375
Other multiple-vehicle collision	03007538, 06010771, 07024030, 07022082

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	1	2	0	0	1	3	0	0	7	100	95
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	2	0	0	1	3	0	0	7	100	99
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	2	0	0	0	2	0	0	5	71	65
Weather conditions	0	0	0	0	1	0	0	0	1	14	20
Unknown	0	0	0	0	0	1	0	0	1	14	5
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	03007538, 03026611, 07024030, 02013375, 07022082
Weather conditions	06010771
Unknown	07018890

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	2	0	0	1	3	0	0	7	100	94
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Monday	0	0	0	0	0	1	0	0	1	14	14
Tuesday	0	0	0	0	1	1	0	0	2	29	14
Friday	1	1	0	0	0	0	0	0	2	29	18
Saturday	0	1	0	0	0	1	0	0	2	29	13
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Monday	07022082
Tuesday	06010771, 07024030
Friday	03007538, 02013375
Saturday	03026611, 07018890

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	2	0	0	1	3	0	0	7	100	100
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	2	1	0	0	0	2	0	0	5	38	N/A
25 to 34	0	0	0	0	1	1	0	0	2	15	N/A
35 to 44	0	0	0	0	0	1	0	0	1	8	N/A
55 to 64	0	1	0	0	1	0	0	0	2	15	N/A
75 to 84	0	2	0	0	0	0	0	0	2	15	N/A
85 and over	0	0	0	0	0	1	0	0	1	8	N/A
Total Vehicles	2	4	0	0	2	5	0	0	13	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	03026611, 07024030, 02013375, 02013375, 07022082
25 to 34	06010771, 07024030
35 to 44	07018890
55 to 64	03007538, 06010771
75 to 84	03007538, 03026611
85 and over	07022082

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	2	0	0	1	3	0	0	7	100	86
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Motor vehicle in transport	2	4	0	0	2	4	0	0	12	92	N/A
Utility pole/Light support	0	0	0	0	0	1	0	0	1	8	N/A
Total Vehicles	2	4	0	0	2	5	0	0	13	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Motor vehicle in transport	03007538, 03007538, 06010771, 06010771, 03026611, 03026611, 07024030, 07024030, 02013375, 02013375, 07022082, 07022082
Utility pole/Light support	07018890

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Eastbound	0	2	0	0	2	0	0	0	4	31	N/A
Westbound	2	2	0	0	0	5	0	0	9	69	N/A
Total Vehicles	2	4	0	0	2	5	0	0	13	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Eastbound	06010771, 06010771, 03026611, 03026611
Westbound	03007538, 03007538, 07018890, 07024030, 07024030, 02013375, 02013375, 07022082, 07022082

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	1	2	0	0	1	3	0	0	7	100	70
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident. (Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1 Vehicle	0	0	0	0	0	1	0	0	1	14	N/A
2 Vehicles	1	0	0	0	1	2	0	0	4	57	N/A
More than 2 Vehicles	0	2	0	0	0	0	0	0	2	29	N/A
Total Accidents	1	2	0	0	1	3	0	0	7	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
1 Vehicle	07018890
2 Vehicles	06010771, 07024030, 02013375, 07022082
More than 2 Vehicles	03007538, 03026611

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	2	0	0	1	3	0	0	7	100	98
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	1	2	0	0	1	3	0	0	7	100	83
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	1	1	0	0	0	3	0	0	5	71	69
Wet	0	1	0	0	1	0	0	0	2	29	15
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	03026611, 07018890, 07024030, 02013375, 07022082
Wet	03007538, 06010771

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	0	0	0	1	0	0	1	14	23
No	1	2	0	0	1	2	0	0	6	86	77
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	07018890
No	03007538, 06010771, 03026611, 07024030, 02013375, 07022082

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	2	0	0	1	3	0	0	7	100	100
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	2	0	0	1	3	0	0	7	100	100
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	2	3	0	0	2	3	0	0	10	77	N/A
Light truck, only four tires	0	1	0	0	0	0	0	0	1	8	N/A
Sport utility vehicle	0	0	0	0	0	2	0	0	2	15	N/A
Total Vehicles	2	4	0	0	2	5	0	0	13	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	03007538, 03007538, 06010771, 06010771, 03026611, 07024030, 07024030, 02013375, 02013375, 07022082
Light truck, only four tires	03026611
Sport utility vehicle	07018890, 07022082

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	1	0	0	0	0	3	0	0	4	31	N/A
Turning left	0	0	0	0	2	0	0	0	2	15	N/A
Slowing	0	4	0	0	0	2	0	0	6	46	N/A
Stopped in traffic	1	0	0	0	0	0	0	0	1	8	N/A
Total Vehicles	2	4	0	0	2	5	0	0	13	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	07018890, 07024030, 02013375, 07022082
Turning left	06010771, 06010771
Slowing	03007538, 03007538, 03026611, 03026611, 07024030, 07022082
Stopped in traffic	02013375

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	0	0	0	0	1	0	0	0	1	14	13
No-turn	1	2	0	0	0	3	0	0	6	86	83
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	06010771
No-turn	03007538, 03026611, 07018890, 07024030, 02013375, 07022082

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	1	1	0	0	0	3	0	0	5	71	60
Cloudy	0	1	0	0	0	0	0	0	1	14	19
Rain	0	0	0	0	1	0	0	0	1	14	9
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	03007538, 07018890, 07024030, 02013375, 07022082
Cloudy	03026611
Rain	06010771

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2002	2003	2004	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	2	0	0	1	3	0	0	7	100	98
Total Accidents	1	2	0	0	1	3	0	0	7	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	03007538, 06010771, 03026611, 07018890, 07024030, 02013375, 07022082

2. Route SR S0000101A_, Milepost 12.918 to 12.992

Roadway Segment

Segment ID: 52660
Internal Segment ID: S2003
Route Number Display Value: SRS0000101A_
Site Subtype: Seg/Urb; 2-lane arterial
Start Location: 12.918
End Location: 12.992
GIS Identifier: 52660
Next Roadway Segment ID: S620
Previous Roadway Segment ID: S13192
Next Intersection ID: I7078
Previous Intersection ID: I2377
Segment Length: 0.0740 miles
Roadway Class Level 1: Principal arterial-other
Roadway Class Level 2: Principal arterial-other urban
Roadway Class Level 3: Urban two-lane
Number of Through Lanes - Combined: 2
Median Type Level 1: Other divided
Median Type Level 2: Divided
Median Width: 12.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 22,011 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Eastbound
Interchange Influence Area on Mainline Freeway: No
Number of Accidents: 7

Geographic Description

Identifier: G344
Route Type: State route
Route Name: S0000101A_
Major Road Name: Amherst St
County: HILLSBOROUGH
District: 5
City/Town: NASHUA
Jurisdiction: Local maintained
Area Type: Urban

Table 56. Route SR S0000101A_, Milepost 12.918 to 12.992 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	1	12.00	Not applicable	Not applicable	0.00	0.00		
Direction 2	1	12.00	Not applicable	Not applicable	0.00	0.00		

Table 57. Route SR S0000101A_, Milepost 12.918 to 12.992 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	22,011			Growth Factor Applied	
2003	22,011			Growth Factor Applied	
2004	22,011			Growth Factor Applied	
2005	22,011			Growth Factor Applied	
2006	22,011			Growth Factor Applied	
2007	22,011			Growth Factor Applied	
2008	22,011			Growth Factor Applied	
2009	22,011			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 03007538

Accident

Accident ID: 03007538

Internal Accident ID: A6080

Inventory Element: S2003

Location: 12.9733

GIS Identifier: 03007538

Accident Date: 2003/02/21

Accident Month: February

Accident Time of Day: 0846

Accident Date Stamp: 02/21/03 08:46:00

Accident Year: 2003

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Friday

Table 58. Accident 03007538 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Slowing	Passenger car	Motor vehicle in transport	1927/06/05	75
Vehicle 2	Westbound	Slowing	Passenger car	Motor vehicle in transport	1944/11/23	58

Accident Details: Accident Case ID: 06010771

Accident

Accident ID: 06010771

Internal Accident ID: A57334

Inventory Element: S2003

Location: 12.9885

GIS Identifier: 06010771

Accident Date: 2006/05/02

Accident Month: May

Accident Time of Day: 1755

Accident Date Stamp: 05/02/06 17:55:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Rain

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Weather conditions

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Tuesday

Table 59. Accident 06010771 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1951/03/17	55
Vehicle 2	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1972/05/08	33

Accident Details: Accident Case ID: 03026611

Accident

Accident ID: 03026611
 Internal Accident ID: A13431
 Inventory Element: S2003
 Location: 12.91838
 GIS Identifier: 03026611
 Accident Date: 2003/08/30
 Accident Month: August
 Accident Time of Day: 1745
 Accident Date Stamp: 08/30/03 17:45:00
 Accident Year: 2003
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Saturday

Table 60. Accident 03026611 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Slowing	Passenger car	Motor vehicle in transport	1924/07/26	79
Vehicle 2	Eastbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1984/04/25	19

Accident Details: Accident Case ID: 07018890

Accident

Accident ID: 07018890

Internal Accident ID: A81334

Inventory Element: S2003

Location: 12.943

GIS Identifier: 07018890

Accident Date: 2007/04/21

Accident Month: April

Accident Time of Day: 0630

Accident Date Stamp: 04/21/07 06:30:00

Accident Year: 2007

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Collision with fixed object

Contributing Circumstances, Environment: Unknown

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 1

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: Yes

Pedestrian Indicator: No

Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday

Table 61. Accident 07018890 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Movements essentially straight ahead	Sport utility vehicle	Utility pole/Light support	1966/07/01	40
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Utility pole/Light support		

Accident Details: Accident Case ID: 07024030

Accident

Accident ID: 07024030
 Internal Accident ID: A87107
 Inventory Element: S2003
 Location: 12.9392
 GIS Identifier: 07024030
 Accident Date: 2007/09/04
 Accident Month: September
 Accident Time of Day: 1457
 Accident Date Stamp: 09/04/07 14:57:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
Pedestrian Indicator: No
Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Tuesday

Table 62. Accident 07024030 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Slowing	Passenger car	Motor vehicle in transport	1973/07/13	34
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1989/11/26	17

Accident Details: Accident Case ID: 02013375

Accident

Accident ID: 02013375
Internal Accident ID: A3414
Inventory Element: S2003
Location: 12.9866
GIS Identifier: 02013375
Accident Date: 2002/05/17
Accident Month: May
Accident Time of Day: 1454
Accident Date Stamp: 05/17/02 14:54:00
Accident Year: 2002
Accident Severity Level 1: Non-Incapacitating Injury
Number of Fatalities: 0
Number of Non-Fatal Injuries: 1
Relationship to Junction: Non-junction
Driveway Indicator: No
Light Condition: Daylight
Weather Condition: Clear
Roadway Surface Condition: Dry
Accident Type and Manner of Collision: Rear-end
Contributing Circumstances, Environment: None
Contributing Circumstances, Road: None
School Bus Related: Unknown
Work Zone Related: No
Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 63. Accident 02013375 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1980/04/24	22
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1982/06/23	19

Accident Details: Accident Case ID: 07022082

Accident

Accident ID: 07022082
 Internal Accident ID: A87699
 Inventory Element: S2003
 Location: 12.943
 GIS Identifier: 07022082
 Accident Date: 2007/08/27
 Accident Month: August
 Accident Time of Day: 1325
 Accident Date Stamp: 08/27/07 13:25:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown

Work Zone Related: No
Number of Vehicles Involved: 2
Alcohol/Drug Involvement: Neither alcohol nor other drugs
Tow-Away Indicator: Unknown
Run-Off Road Indicator: No
Pedestrian Indicator: No
Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Monday

Table 64. Accident 07022082 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1922/07/30	85
Vehicle 2	Westbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1989/07/05	18