

SafetyAnalyst

**Accident Summary for Route SR S0000120 __,
Milepost 22.416 (Intersection 12970)**

May 12, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary 1

 1.1 Accident Case Identifier 1

 1.2 Accident Month 1

 1.3 Accident Severity Level 1 2

 1.4 Accident Time of Day 2

 1.5 Accident Type and Manner of Collision 3

 1.6 Alcohol/Drug Involvement 4

 1.7 Bicycle Indicator 4

 1.8 Contributing Circumstances, Environment 5

 1.9 Contributing Circumstances, Road 5

 1.10 Day of Week 6

 1.11 Divided Highway Flag-Side of Road 6

 1.12 Driver Age 7

 1.13 Driveway Indicator 7

 1.14 First Harmful Event 8

 1.15 Initial Direction of Travel 8

 1.16 Light Condition 9

 1.17 Number of Vehicles Involved 10

 1.18 Pedestrian Indicator 10

 1.19 Relationship to Junction 11

 1.20 Roadway Surface Condition 11

 1.21 Run-Off Road Indicator 12

 1.22 School Bus Related 12

 1.23 Tow-Away Indicator 13

 1.24 Vehicle Configuration 13

 1.25 Vehicle Maneuver/Action 14

 1.26 Vehicle Turning Movement 14

 1.27 Weather Condition 15

 1.28 Work Zone Related 16

2. Route SR S0000120 __, Milepost 22.416 17

3. Accident Case Details 20

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	1
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	2
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	3
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	4
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	4
Table 12. Bicycle Indicator	4
Table 13. Bicycle Indicator (Accident Case Identifier)	5
Table 14. Contributing Circumstances, Environment	5
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	5
Table 16. Contributing Circumstances, Road	5
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	6
Table 18. Day of Week	6
Table 19. Day of Week (Accident Case Identifier)	6
Table 20. Divided Highway Flag-Side of Road	6
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	7
Table 22. Driver Age in Years	7
Table 23. Driver Age in Years (Accident Case Identifier)	7
Table 24. Driveway Indicator	8
Table 25. Driveway Indicator (Accident Case Identifier)	8
Table 26. First Harmful Event	8
Table 27. First Harmful Event (Accident Case Identifier)	8
Table 28. Initial Direction of Travel	9
Table 29. Initial Direction of Travel (Accident Case Identifier)	9
Table 30. Light Condition	9
Table 31. Light Condition (Accident Case Identifier)	10
Table 32. Number of Vehicles Involved	10
Table 33. Number of Vehicles Involved (Accident Case Identifier)	10
Table 34. Pedestrian Indicator	10
Table 35. Pedestrian Indicator (Accident Case Identifier)	11
Table 36. Relationship to Junction	11
Table 37. Relationship to Junction (Accident Case Identifier)	11
Table 38. Roadway Surface Condition	11

Table 39. Roadway Surface Condition (Accident Case Identifier)	12
Table 40. Run-Off Road Indicator	12
Table 41. Run-Off Road Indicator (Accident Case Identifier)	12
Table 42. School Bus Related	12
Table 43. School Bus Related (Accident Case Identifier)	13
Table 44. Tow-Away Indicator	13
Table 45. Tow-Away Indicator (Accident Case Identifier)	13
Table 46. Vehicle Configuration	13
Table 47. Vehicle Configuration (Accident Case Identifier)	14
Table 48. Vehicle Maneuver/Action	14
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	14
Table 50. Vehicle Turning Movement	15
Table 51. Vehicle Turning Movement (Accident Case Identifier)	15
Table 52. Weather Condition	15
Table 53. Weather Condition (Accident Case Identifier)	15
Table 54. Work Zone Related	16
Table 55. Work Zone Related (Accident Case Identifier)	16
Table 56. Route SR S0000120 __, Milepost 22.416 Major Road Annual Traffic	18
Table 57. Route SR S0000120 __, Milepost 22.416 Minor Road Annual Traffic	18
Table 58. Accident 06007468 Vehicle-Level Accident Data	21
Table 59. Accident 06003097 Vehicle-Level Accident Data	22
Table 60. Accident 08032031 Vehicle-Level Accident Data	23
Table 61. Accident 05006026 Vehicle-Level Accident Data	24
Table 62. Accident 09003035 Vehicle-Level Accident Data	25
Table 63. Accident 06034496 Vehicle-Level Accident Data	26
Table 64. Accident 09003005 Vehicle-Level Accident Data	27

1. Accident Summary

This is a summary of the accident data associated with the following Intersection from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000120 __, Milepost 22.416 (Intersection 12970)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **7 Total Accidents** spanning the dates **1/1/2005** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2005	05006026
2006	06007468, 06003097, 06034496
2008	08032031
2009	09003035, 09003005

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
January	1	1	0	0	2	4	57	9
March	0	1	0	0	0	1	14	7
November	0	1	0	0	0	1	14	8
December	0	0	0	1	0	1	14	9
Total Accidents	1	3	0	1	2	7	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
January	06003097, 05006026, 09003035, 09003005
March	06007468
November	06034496
December	08032031

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	0	1	0	0	0	1	14	N/A
Possible Injury	1	0	0	0	1	2	29	N/A
Property-Damage-Only	0	2	0	1	1	4	57	N/A
Total Accidents	1	3	0	1	2	7	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	06007468
Possible Injury	05006026, 09003005
Property-Damage-Only	06003097, 08032031, 09003035, 06034496

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
7:00 am to 7:59 am	0	2	0	0	0	2	29	N/A
9:00 am to 9:59 am	0	0	0	0	1	1	14	N/A
11:00 am to 11:59 am	0	0	0	0	1	1	14	N/A
2:00 pm to 2:59 pm	0	1	0	0	0	1	14	N/A
5:00 pm to 5:59 pm	1	0	0	0	0	1	14	N/A
7:00 pm to 7:59 pm	0	0	0	1	0	1	14	N/A
Total Accidents	1	3	0	1	2	7	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
7:00 am to 7:59 am	06003097,06034496
9:00 am to 9:59 am	09003035
11:00 am to 11:59 am	09003005
2:00 pm to 2:59 pm	06007468
5:00 pm to 5:59 pm	05006026
7:00 pm to 7:59 pm	08032031

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Rear-end	0	0	0	1	0	1	14	11
Angle	0	1	0	0	0	1	14	10
Other multiple-vehicle collision	1	2	0	0	2	5	71	67
Total Accidents	1	3	0	1	2	7	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Rear-end	08032031
Angle	06007468
Other multiple-vehicle collision	06003097, 05006026, 09003035, 06034496, 09003005

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	1	3	0	1	2	7	100	98
Total Accidents	1	3	0	1	2	7	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	0	1	2	7	100	98
Total Accidents	1	3	0	1	2	7	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	3	0	0	2	6	86	70
Unknown	0	0	0	1	0	1	14	6
Total Accidents	1	3	0	1	2	7	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	06007468, 06003097, 05006026, 09003035, 06034496, 09003005
Unknown	08032031

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	3	0	0	2	6	86	95
Road surface condition (wet, icy, snow, slush, etc.)	0	0	0	1	0	1	14	2
Total Accidents	1	3	0	1	2	7	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	06007468, 06003097, 05006026, 09003035, 06034496, 09003005
Road surface condition (wet, icy, snow, slush, etc.)	08032031

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Monday	0	0	0	1	0	1	14	14
Tuesday	1	1	0	0	1	3	43	16
Wednesday	0	1	0	0	0	1	14	15
Saturday	0	1	0	0	1	2	29	12
Total Accidents	1	3	0	1	2	7	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Monday	08032031
Tuesday	05006026, 09003035, 06034496
Wednesday	06007468
Saturday	06003097, 09003005

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	3	0	1	2	7	100	100
Total Accidents	1	3	0	1	2	7	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	0	3	0	0	1	4	29	N/A
25 to 34	1	1	0	1	1	4	29	N/A
35 to 44	0	0	0	0	1	1	7	N/A
45 to 54	1	2	0	1	0	4	29	N/A
55 to 64	0	0	0	0	1	1	7	N/A
Total Vehicles	2	6	0	2	4	14	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	06007468, 06003097, 06034496, 09003005
25 to 34	06007468, 08032031, 05006026, 09003035
35 to 44	09003005
45 to 54	06003097, 08032031, 05006026, 06034496
55 to 64	09003035

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	0	1	2	7	100	100
Total Accidents	1	3	0	1	2	7	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Motor vehicle in transport	2	6	0	2	4	14	100	N/A
Total Vehicles	2	6	0	2	4	14	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Motor vehicle in transport	06007468, 06007468, 06003097, 06003097, 08032031, 08032031, 05006026, 05006026, 09003035, 09003035, 06034496, 06034496, 09003005, 09003005

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due

east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Northbound	0	3	0	0	2	5	36	N/A
Southbound	2	2	0	0	2	6	43	N/A
Eastbound	0	1	0	2	0	3	21	N/A
Total Vehicles	2	6	0	2	4	14	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Northbound	06003097, 06034496, 06034496, 09003005, 09003005
Southbound	06007468, 06003097, 05006026, 05006026, 09003035, 09003035
Eastbound	06007468, 08032031, 08032031

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	0	3	0	0	2	5	71	76
Dark-lighted	1	0	0	0	0	1	14	14
Unknown	0	0	0	1	0	1	14	3
Total Accidents	1	3	0	1	2	7	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	06007468, 06003097, 09003035, 06034496, 09003005
Dark-lighted	05006026
Unknown	08032031

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident. (Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
2 Vehicles	0	3	0	1	2	6	86	N/A
More than 2 Vehicles	1	0	0	0	0	1	14	N/A
Total Accidents	1	3	0	1	2	7	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
2 Vehicles	06007468, 06003097, 08032031, 09003035, 06034496, 09003005
More than 2 Vehicles	05006026

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	0	1	2	7	100	98
Total Accidents	1	3	0	1	2	7	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
At intersection	0	2	0	1	0	3	43	76
Intersection-related	1	1	0	0	2	4	57	24
Total Accidents	1	3	0	1	2	7	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
At intersection	06007468, 06003097, 08032031
Intersection-related	05006026, 09003035, 06034496, 09003005

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	1	3	0	0	1	5	71	75
Wet	0	0	0	0	1	1	14	17
Snow	0	0	0	1	0	1	14	6
Total Accidents	1	3	0	1	2	7	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	06007468, 06003097, 05006026, 09003035, 06034496
Wet	09003005
Snow	08032031

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	0	1	2	7	100	95
Total Accidents	1	3	0	1	2	7	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	3	0	1	2	7	100	100
Total Accidents	1	3	0	1	2	7	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	3	0	1	2	7	100	100
Total Accidents	1	3	0	1	2	7	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	0	3	0	2	1	6	43	N/A
Light truck, only four tires	1	1	0	0	2	4	29	N/A
Sport utility vehicle	1	1	0	0	1	3	21	N/A
Motor home/recreational vehicle	0	1	0	0	0	1	7	N/A
Total Vehicles	2	6	0	2	4	14	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	06007468, 06007468, 06003097, 08032031, 08032031, 09003005
Light truck, only four tires	06003097, 05006026, 09003035, 09003005
Sport utility vehicle	05006026, 09003035, 06034496
Motor home/recreational vehicle	06034496

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	1	3	0	0	1	5	36	N/A
Turning right	0	1	0	2	0	3	21	N/A
Turning left	0	2	0	0	0	2	14	N/A
Slowing	1	0	0	0	3	4	29	N/A
Total Vehicles	2	6	0	2	4	14	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	06007468, 06003097, 05006026, 09003035, 06034496
Turning right	08032031, 08032031, 06034496
Turning left	06007468, 06003097
Slowing	05006026, 09003035, 09003005, 09003005

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then

this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	0	2	0	0	0	2	29	35
Right turn	0	1	0	1	0	2	29	7
No-turn	1	0	0	0	2	3	43	58
Total Accidents	1	3	0	1	2	7	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	06007468, 06003097
Right turn	08032031, 06034496
No-turn	05006026, 09003035, 09003005

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	1	2	0	1	2	6	86	63
Cloudy	0	1	0	0	0	1	14	21
Total Accidents	1	3	0	1	2	7	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	06007468, 08032031, 05006026, 09003035, 06034496, 09003005
Cloudy	06003097

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	0	1	2	7	100	99
Total Accidents	1	3	0	1	2	7	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	06007468, 06003097, 08032031, 05006026, 09003035, 06034496, 09003005

2. Route SR S0000120 __, Milepost 22.416

Intersection

Intersection ID: 12970
Internal Intersection ID: I8221
Route Number Display Value: SRS0000120 __
Site Subtype: Int/Urb; 3-leg minor-rd STOP
Location: 22.416
GIS Identifier: 12970
Major Road Direction: North-South
Minor Road Name: Evans Dr
Minor Road Location: 0.357
Intersection Type Level 1: Tee intersection
Intersection Type Level 2: Three-legs
Traffic Control Type at Intersection: Stop signs on cross street only
Growth Factor: 1.0000
Growth Factor Source: Specified
Maximum AADT: 23,400 vehicles per day
Number of Accidents: 8

Geographic Description

Identifier: G927
Route Type: State route
Route Name: S0000120 __
Major Road Name: Route 120
County: GRAFTON
District: 2
City/Town: LEBANON
Jurisdiction: State maintained
Area Type: Urban

Table 56. Route SR S0000120 __, Milepost 22.416 Major Road Annual Traffic

Year	AADT	Volume Source	Comment
2002	23,400	Growth Factor Applied	
2003	23,400	Growth Factor Applied	
2004	23,400	Growth Factor Applied	
2005	23,400	Growth Factor Applied	
2006	23,400	Growth Factor Applied	
2007	23,400	Growth Factor Applied	
2008	23,400	Growth Factor Applied	
2009	23,400	Measured	

Table 57. Route SR S0000120 __, Milepost 22.416 Minor Road Annual Traffic

Year	AADT	Volume Source	Comment
2002	1,716	Growth Factor Applied	
2003	1,716	Growth Factor Applied	
2004	1,716	Growth Factor Applied	
2005	1,716	Growth Factor Applied	
2006	1,716	Growth Factor Applied	
2007	1,716	Growth Factor Applied	
2008	1,716	Growth Factor Applied	
2009	1,716	Measured	

Intersection Leg

Leg ID: 1

Type: Major road, increasing milepost direction

Leg Location: 22.416

Direction: NB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

Intersection Leg

Leg ID: 2

Type: Major road, decreasing milepost direction

Leg Location: 22.416

Direction: SB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

Intersection Leg

Leg ID: 3

Type: Minor road, increasing milepost direction

Leg Location: 0.357

Direction: EB approach

Thru Lanes: 1

Median Type: Unknown

Left-Turn Phasing: Unknown

Turn Prohibitions: Unknown

Operation: Unknown

3. Accident Case Details

Accident Details: Accident Case ID: 06007468

Accident

Accident ID: 06007468

Internal Accident ID: A50245

Inventory Element: I8221

Location: 22.41688

GIS Identifier: 06007468

Accident Date: 2006/03/01

Accident Month: March

Accident Time of Day: 1450

Accident Date Stamp: 03/01/06 14:50:00

Accident Year: 2006

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 2

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Angle

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Wednesday

Agency Intersection Identifier: 12970

Table 58. Accident 06007468 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1988/10/27	17
Vehicle 2	Southbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1972/09/09	33

Accident Details: Accident Case ID: 06003097

Accident

Accident ID: 06003097

Internal Accident ID: A52522

Inventory Element: I8221

Location: 22.41688

GIS Identifier: 06003097

Accident Date: 2006/01/28

Accident Month: January

Accident Time of Day: 0739

Accident Date Stamp: 01/28/06 07:39:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Left turn

Day of Week: Saturday

Agency Intersection Identifier: 12970

Table 59. Accident 06003097 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Turning left	Light truck, only four tires	Motor vehicle in transport	1988/10/03	17
Vehicle 2	Southbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1958/11/20	47

Accident Details: Accident Case ID: 08032031

Accident

Accident ID: 08032031

Internal Accident ID: A115099

Inventory Element: I8221

Location: 22.41688

GIS Identifier: 08032031

Accident Date: 2008/12/22

Accident Month: December

Accident Time of Day: 1915

Accident Date Stamp: 12/22/08 19:15:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: At intersection

Driveway Indicator: No

Light Condition: Unknown

Weather Condition: Clear

Roadway Surface Condition: Snow

Accident Type and Manner of Collision: Rear-end

Contributing Circumstances, Environment: Unknown

Contributing Circumstances, Road: Road surface condition (wet, icy, snow, slush, etc.)

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: Right turn

Day of Week: Monday

Agency Intersection Identifier: 12970

Table 60. Accident 08032031 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Eastbound	Turning right	Passenger car	Motor vehicle in transport	1959/04/30	49
Vehicle 2	Eastbound	Turning right	Passenger car	Motor vehicle in transport	1983/05/02	25

Accident Details: Accident Case ID: 05006026

Accident

Accident ID: 05006026

Internal Accident ID: A30204

Inventory Element: I8221

Location: 22.379

GIS Identifier: 05006026

Accident Date: 2005/01/25

Accident Month: January

Accident Time of Day: 1720

Accident Date Stamp: 01/25/05 17:20:00

Accident Year: 2005

Accident Severity Level 1: Possible Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Intersection-related

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 4

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 61. Accident 05006026 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1972/10/23	32
Vehicle 2	Southbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1959/06/22	45

Accident Details: Accident Case ID: 09003035

Accident

Accident ID: 09003035
 Internal Accident ID: A120658
 Inventory Element: I8221
 Location: 22.4178
 GIS Identifier: 09003035
 Accident Date: 2009/01/06
 Accident Month: January
 Accident Time of Day: 0913
 Accident Date Stamp: 01/06/09 09:13:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday
 Agency Intersection Identifier: 12970

Table 62. Accident 09003035 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1951/06/17	57
Vehicle 2	Southbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1983/04/04	25

Accident Details: Accident Case ID: 06034496

Accident

Accident ID: 06034496
 Internal Accident ID: A70084
 Inventory Element: I8221
 Location: 22.422
 GIS Identifier: 06034496
 Accident Date: 2006/11/07
 Accident Month: November
 Accident Time of Day: 0704
 Accident Date Stamp: 11/07/06 07:04:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None

School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Right turn
 Day of Week: Tuesday
 Agency Intersection Identifier: 12970

Table 63. Accident 06034496 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1984/07/18	22
Vehicle 2	Northbound	Turning right	Motor home/recreational vehicle	Motor vehicle in transport	1954/03/26	52

Accident Details: Accident Case ID: 09003005

Accident

Accident ID: 09003005
 Internal Accident ID: A122462
 Inventory Element: I8221
 Location: 22.4178
 GIS Identifier: 09003005
 Accident Date: 2009/01/03
 Accident Month: January
 Accident Time of Day: 1154
 Accident Date Stamp: 01/03/09 11:54:00
 Accident Year: 2009
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Intersection-related
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday
 Agency Intersection Identifier: 12970

Table 64. Accident 09003005 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Slowing	Passenger car	Motor vehicle in transport	1988/03/11	20
Vehicle 2	Northbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1973/04/19	35