

SafetyAnalyst

**Accident Summary for Route SR S0000120,
Milepost 21.911 to 22.163 (Segment 14967)**

May 12, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary	1
1.1 Accident Case Identifier	1
1.2 Accident Month	1
1.3 Accident Severity Level 1	2
1.4 Accident Time of Day	3
1.5 Accident Type and Manner of Collision	4
1.6 Alcohol/Drug Involvement	4
1.7 Bicycle Indicator	5
1.8 Contributing Circumstances, Environment	5
1.9 Contributing Circumstances, Road	6
1.10 Day of Week	6
1.11 Divided Highway Flag-Side of Road	7
1.12 Driver Age	8
1.13 Driveway Indicator	9
1.14 First Harmful Event	9
1.15 Initial Direction of Travel	10
1.16 Light Condition	11
1.17 Number of Vehicles Involved	11
1.18 Pedestrian Indicator	12
1.19 Relationship to Junction	13
1.20 Roadway Surface Condition	13
1.21 Run-Off Road Indicator	14
1.22 School Bus Related	14
1.23 Tow-Away Indicator	15
1.24 Vehicle Configuration	15
1.25 Vehicle Maneuver/Action	16
1.26 Vehicle Turning Movement	17
1.27 Weather Condition	18
1.28 Work Zone Related	18
2. Route SR S0000120 __, Milepost 21.911 to 22.163	20
3. Accident Case Details	22

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	3
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	4
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	5
Table 12. Bicycle Indicator	5
Table 13. Bicycle Indicator (Accident Case Identifier)	5
Table 14. Contributing Circumstances, Environment	5
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	6
Table 16. Contributing Circumstances, Road	6
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	6
Table 18. Day of Week	7
Table 19. Day of Week (Accident Case Identifier)	7
Table 20. Divided Highway Flag-Side of Road	7
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	8
Table 22. Driver Age in Years	8
Table 23. Driver Age in Years (Accident Case Identifier)	8
Table 24. Driveway Indicator	9
Table 25. Driveway Indicator (Accident Case Identifier)	9
Table 26. First Harmful Event	9
Table 27. First Harmful Event (Accident Case Identifier)	10
Table 28. Initial Direction of Travel	10
Table 29. Initial Direction of Travel (Accident Case Identifier)	11
Table 30. Light Condition	11
Table 31. Light Condition (Accident Case Identifier)	11
Table 32. Number of Vehicles Involved	12
Table 33. Number of Vehicles Involved (Accident Case Identifier)	12
Table 34. Pedestrian Indicator	12
Table 35. Pedestrian Indicator (Accident Case Identifier)	12
Table 36. Relationship to Junction	13
Table 37. Relationship to Junction (Accident Case Identifier)	13
Table 38. Roadway Surface Condition	13

Table 39. Roadway Surface Condition (Accident Case Identifier)	14
Table 40. Run-Off Road Indicator	14
Table 41. Run-Off Road Indicator (Accident Case Identifier)	14
Table 42. School Bus Related	15
Table 43. School Bus Related (Accident Case Identifier)	15
Table 44. Tow-Away Indicator	15
Table 45. Tow-Away Indicator (Accident Case Identifier)	15
Table 46. Vehicle Configuration	16
Table 47. Vehicle Configuration (Accident Case Identifier)	16
Table 48. Vehicle Maneuver/Action	16
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	17
Table 50. Vehicle Turning Movement	17
Table 51. Vehicle Turning Movement (Accident Case Identifier)	18
Table 52. Weather Condition	18
Table 53. Weather Condition (Accident Case Identifier)	18
Table 54. Work Zone Related	19
Table 55. Work Zone Related (Accident Case Identifier)	19
Table 56. Route SR S0000120 __, Milepost 21.911 to 22.163 Directional Attributes	21
Table 57. Route SR S0000120 __, Milepost 21.911 to 22.163 Annual Traffic	21
Table 58. Accident 06030293 Vehicle-Level Accident Data	23
Table 59. Accident 08023422 Vehicle-Level Accident Data	24
Table 60. Accident 07023964 Vehicle-Level Accident Data	25
Table 61. Accident 09026873 Vehicle-Level Accident Data	26
Table 62. Accident 09014536 Vehicle-Level Accident Data	27
Table 63. Accident 05035859 Vehicle-Level Accident Data	28
Table 64. Accident 08011379 Vehicle-Level Accident Data	29
Table 65. Accident 06009255 Vehicle-Level Accident Data	30
Table 66. Accident 09009658 Vehicle-Level Accident Data	31
Table 67. Accident 07027475 Vehicle-Level Accident Data	32
Table 68. Accident 08001415 Vehicle-Level Accident Data	33
Table 69. Accident 05038708 Vehicle-Level Accident Data	34
Table 70. Accident 05031739 Vehicle-Level Accident Data	35
Table 71. Accident 05012185 Vehicle-Level Accident Data	36
Table 72. Accident 07016993 Vehicle-Level Accident Data	37

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000120__, Milepost 21.911 to 22.163 (Segment 14967)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **15 Total Accidents** spanning the dates **1/1/2005** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **21.911** to **22.163** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2005	05035859, 05038708, 05031739, 05012185
2006	06030293, 06009255
2007	07023964, 07027475, 07016993
2008	08023422, 08011379, 08001415
2009	09026873, 09014536, 09009658

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
January	0	0	0	1	0	1	7	8
March	1	1	0	1	1	4	27	7
June	0	0	1	0	0	1	7	9
July	0	0	0	0	1	1	7	10
August	0	0	1	1	0	2	13	9
October	1	1	1	0	0	3	20	9
November	0	0	0	0	1	1	7	8
December	2	0	0	0	0	2	13	10
Total Accidents	4	2	3	3	3	15	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
January	08001415
March	08011379, 06009255, 09009658, 05012185
June	07016993
July	09014536
August	08023422, 07023964
October	06030293, 07027475, 05031739
November	09026873
December	05035859, 05038708

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	0	0	1	0	1	2	13	N/A
Possible Injury	0	0	0	1	0	1	7	N/A
Property-Damage-Only	4	2	2	2	2	12	80	N/A
Total Accidents	4	2	3	3	3	15	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	07023964, 09014536
Possible Injury	08011379
Property-Damage-Only	06030293, 08023422, 09026873, 05035859, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
6:00 am to 6:59 am	0	1	0	0	0	1	7	N/A
8:00 am to 8:59 am	1	1	0	0	0	2	13	N/A
12:00 pm to 12:59 pm	0	0	0	1	0	1	7	N/A
1:00 pm to 1:59 pm	0	0	1	0	0	1	7	N/A
2:00 pm to 2:59 pm	0	0	0	0	1	1	7	N/A
3:00 pm to 3:59 pm	1	0	0	0	0	1	7	N/A
4:00 pm to 4:59 pm	0	0	1	1	1	3	20	N/A
6:00 pm to 6:59 pm	2	0	0	0	1	3	20	N/A
8:00 pm to 8:59 pm	0	0	1	0	0	1	7	N/A
11:00 pm to 11:59 pm	0	0	0	1	0	1	7	N/A
Total Accidents	4	2	3	3	3	15	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
6:00 am to 6:59 am	06009255
8:00 am to 8:59 am	06030293,05031739
12:00 pm to 12:59 pm	08023422
1:00 pm to 1:59 pm	07027475
2:00 pm to 2:59 pm	09026873
3:00 pm to 3:59 pm	05012185
4:00 pm to 4:59 pm	09009658,08001415,07016993
6:00 pm to 6:59 pm	09014536,05035859,05038708
8:00 pm to 8:59 pm	07023964
11:00 pm to 11:59 pm	08011379

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with animal	0	0	1	0	0	1	7	1
Collision with fixed object	0	1	1	1	0	3	20	5
Other multiple-vehicle collision	4	1	1	2	3	11	73	65
Total Accidents	4	2	3	3	3	15	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with animal	07023964
Collision with fixed object	08011379, 06009255, 07027475
Other multiple-vehicle collision	06030293, 08023422, 09026873, 09014536, 05035859, 09009658, 08001415, 05038708, 05031739, 05012185, 07016993

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	4	2	3	3	3	15	100	98
Total Accidents	4	2	3	3	3	15	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	4	2	3	3	3	15	100	99
Total Accidents	4	2	3	3	3	15	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	4	1	2	1	2	10	67	70
Weather conditions	0	0	0	1	0	1	7	14
Physical obstruction(s)	0	0	0	1	1	2	13	8
Glare	0	1	0	0	0	1	7	1
Animal(s) in roadway	0	0	1	0	0	1	7	1
Total Accidents	4	2	3	3	3	15	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	06030293, 09014536, 05035859, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993
Weather conditions	08011379
Physical obstruction(s)	08023422, 09026873
Glare	06009255
Animal(s) in roadway	07023964

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	4	2	3	3	3	15	100	95
Total Accidents	4	2	3	3	3	15	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Sunday	0	0	1	0	0	1	7	8
Monday	1	0	0	0	0	1	7	13
Tuesday	0	0	1	0	0	1	7	13
Wednesday	2	1	0	1	1	5	33	16
Thursday	1	0	1	1	0	3	20	17
Friday	0	1	0	1	0	2	13	19
Saturday	0	0	0	0	2	2	13	15
Total Accidents	4	2	3	3	3	15	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Sunday	07027475
Monday	05031739
Tuesday	07023964
Wednesday	09014536, 08011379, 06009255, 05038708, 05012185
Thursday	08023422, 05035859, 07016993
Friday	06030293, 08001415
Saturday	09026873, 09009658

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	4	2	3	3	3	15	100	100
Total Accidents	4	2	3	3	3	15	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	4	0	0	0	1	5	20	N/A
25 to 34	0	1	1	0	1	3	12	N/A
35 to 44	0	1	0	2	1	4	16	N/A
45 to 54	2	0	2	2	2	8	32	N/A
55 to 64	0	1	0	1	0	2	8	N/A
65 to 74	1	0	0	0	0	1	4	N/A
75 to 84	0	0	1	0	1	2	8	N/A
Total Vehicles	7	3	4	5	6	25	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	09026873, 05035859, 05035859, 05038708, 05012185
25 to 34	07023964, 06009255, 09009658
35 to 44	06030293, 08023422, 09014536, 08001415
45 to 54	09014536, 08011379, 09009658, 07027475, 08001415, 05031739, 05012185, 07016993
55 to 64	06030293, 08023422
65 to 74	05031739
75 to 84	09026873, 07016993

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	4	2	3	3	3	15	100	79
Total Accidents	4	2	3	3	3	15	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Animal	0	0	1	0	0	1	4	N/A
Motor vehicle in transport	8	2	2	4	6	22	85	N/A
Embankment	0	0	1	0	0	1	4	N/A
Guardrail face	0	0	0	1	0	1	4	N/A
Highway traffic sign or signpost	0	1	0	0	0	1	4	N/A
Total Vehicles	8	3	4	5	6	26	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Animal	07023964
Motor vehicle in transport	06030293, 06030293, 08023422, 08023422, 09026873, 09026873, 09014536, 09014536, 05035859, 05035859, 09009658, 09009658, 08001415, 08001415, 05038708, 05038708, 05031739, 05031739, 05012185, 05012185, 07016993, 07016993
Embankment	07027475
Guardrail face	08011379
Highway traffic sign or signpost	06009255

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Northbound	5	3	3	2	6	19	73	N/A
Southbound	2	0	1	0	0	3	12	N/A
Westbound	1	0	0	3	0	4	15	N/A
Total Vehicles	8	3	4	5	6	26	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Northbound	06030293, 06030293, 08023422, 08023422, 09026873, 09026873, 09014536, 09014536, 06009255, 09009658, 09009658, 07027475, 05038708, 05031739, 05031739, 05012185, 05012185, 07016993, 07016993
Southbound	07023964, 05035859, 05035859
Westbound	08011379, 08001415, 08001415, 05038708

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	2	2	2	2	3	11	73	75
Dusk	1	0	0	0	0	1	7	3
Dark-lighted	1	0	0	1	0	2	13	16
Dark-not lighted	0	0	1	0	0	1	7	2
Total Accidents	4	2	3	3	3	15	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	06030293, 08023422, 09026873, 09014536, 06009255, 09009658, 07027475, 08001415, 05031739, 05012185, 07016993
Dusk	05038708
Dark-lighted	05035859, 08011379
Dark-not lighted	07023964

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1 Vehicle	0	1	2	1	0	4	27	N/A
2 Vehicles	4	0	1	2	3	10	67	N/A
More than 2 Vehicles	0	1	0	0	0	1	7	N/A
Total Accidents	4	2	3	3	3	15	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
1 Vehicle	07023964, 08011379, 06009255, 07027475
2 Vehicles	08023422, 09026873, 09014536, 05035859, 09009658, 08001415, 05038708, 05031739, 05012185, 07016993
More than 2 Vehicles	06030293

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	4	2	3	3	3	15	100	98
Total Accidents	4	2	3	3	3	15	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	3	2	3	3	2	13	87	71
Other	1	0	0	0	1	2	13	8
Total Accidents	4	2	3	3	3	15	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	06030293, 08023422, 07023964, 09026873, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993
Other	09014536, 05035859

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	4	2	3	2	3	14	93	76
Ice/frost	0	0	0	1	0	1	7	1
Total Accidents	4	2	3	3	3	15	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993
Ice/frost	08011379

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	1	1	1	0	3	20	6
No	4	1	2	2	3	12	80	94
Total Accidents	4	2	3	3	3	15	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	08011379, 06009255, 07027475
No	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 09009658, 08001415, 05038708, 05031739, 05012185, 07016993

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	4	2	3	3	3	15	100	100
Total Accidents	4	2	3	3	3	15	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	4	2	3	3	3	15	100	100
Total Accidents	4	2	3	3	3	15	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	3	2	2	1	4	12	46	N/A
Light truck, only four tires	5	1	1	1	1	9	35	N/A
Sport utility vehicle	0	0	1	1	1	3	12	N/A
Other	0	0	0	1	0	1	4	N/A
Unknown vehicle configuration	0	0	0	1	0	1	4	N/A
Total Vehicles	8	3	4	5	6	26	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	06030293, 07023964, 09026873, 09014536, 05035859, 06009255, 09009658, 09009658, 08001415, 05038708, 05031739, 07016993
Light truck, only four tires	06030293, 08023422, 09026873, 05035859, 05038708, 05031739, 05012185, 05012185, 07016993
Sport utility vehicle	09014536, 08011379, 07027475
Other	08001415
Unknown vehicle configuration	08023422

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	2	2	2	2	2	10	38	N/A
Backing	1	0	0	0	0	1	4	N/A
Changing lanes	1	0	0	3	2	6	23	N/A
Making U-turn	1	0	0	0	0	1	4	N/A
Entering traffic lane	0	0	0	0	1	1	4	N/A
Slowing	2	1	0	0	1	4	15	N/A
Stopped in traffic	1	0	1	0	0	2	8	N/A
Unknown	0	0	1	0	0	1	4	N/A
Total Vehicles	8	3	4	5	6	26	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	06030293, 08023422, 07023964, 09026873, 06009255, 09009658, 08001415, 05038708, 05012185, 07016993
Backing	05035859
Changing lanes	08023422, 09026873, 08011379, 09009658, 08001415, 05012185
Making U-turn	05038708
Entering traffic lane	09014536
Slowing	06030293, 09014536, 05031739, 05031739
Stopped in traffic	05035859, 07016993
Unknown	07027475

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	1	0	0	0	0	1	7	21
No-turn	3	2	3	3	3	14	93	74
Total Accidents	4	2	3	3	3	15	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	05038708
No-turn	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05031739, 05012185, 07016993

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	4	2	3	2	1	12	80	62
Cloudy	0	0	0	0	2	2	13	24
Sleet, hail (freezing rain or drizzle)	0	0	0	1	0	1	7	0
Total Accidents	4	2	3	3	3	15	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	06030293, 08023422, 07023964, 05035859, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 05012185, 07016993
Cloudy	09026873, 09014536
Sleet, hail (freezing rain or drizzle)	08011379

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	1	0	0	0	0	1	7	2
No	3	2	3	3	3	14	93	98
Total Accidents	4	2	3	3	3	15	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
Yes	05012185
No	06030293, 08023422, 07023964, 09026873, 09014536, 05035859, 08011379, 06009255, 09009658, 07027475, 08001415, 05038708, 05031739, 07016993

2. Route SR S0000120 __, Milepost 21.911 to 22.163

Roadway Segment

Segment ID: 14967
Internal Segment ID: S11585
Route Number Display Value: SRS0000120 __
Site Subtype: Seg/Urb; Multilane undivided
Start Location: 21.911
End Location: 22.163
GIS Identifier: 14967
Next Roadway Segment ID: S10499
Previous Roadway Segment ID: S14056
Next Intersection ID: I4049
Previous Intersection ID: I390
Segment Length: 0.2520 miles
Roadway Class Level 1: Minor Collector
Roadway Class Level 2: Collector urban
Roadway Class Level 3: Urban multi-lane undivided
Number of Through Lanes - Combined: 4
Median Type Level 1: Undivided
Median Type Level 2: Undivided
Median Width: 0.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 12,050 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Northbound
Interchange Influence Area on Mainline Freeway: No
Number of Accidents: 16

Geographic Description

Identifier: G2522
Route Type: State route
Route Name: S0000120 __
Major Road Name: Route 120
County: GRAFTON
District: 2
City/Town: LEBANON
Jurisdiction: Local maintained
Area Type: Urban

Table 56. Route SR S0000120 __, Milepost 21.911 to 22.163 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	2	11.00	Not applicable	Not applicable	0.00	0.00		
Direction 2	2	11.00	Not applicable	Not applicable	0.00	0.00		

Table 57. Route SR S0000120 __, Milepost 21.911 to 22.163 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	12,050			Growth Factor Applied	
2003	12,050			Growth Factor Applied	
2004	12,050			Growth Factor Applied	
2005	12,050			Growth Factor Applied	
2006	12,050			Growth Factor Applied	
2007	12,050			Growth Factor Applied	
2008	12,050			Growth Factor Applied	
2009	12,050			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 06030293

Accident

Accident ID: 06030293

Internal Accident ID: A69492

Inventory Element: S11585

Location: 22.119

GIS Identifier: 06030293

Accident Date: 2006/10/13

Accident Month: October

Accident Time of Day: 0804

Accident Date Stamp: 10/13/06 08:04:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 4

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Friday

Table 58. Accident 06030293 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1951/04/22	55
Vehicle 2	Northbound	Slowing	Passenger car	Motor vehicle in transport	1963/10/02	43

Accident Details: Accident Case ID: 08023422

Accident

Accident ID: 08023422

Internal Accident ID: A111887

Inventory Element: S11585

Location: 22.15313

GIS Identifier: 08023422

Accident Date: 2008/08/28

Accident Month: August

Accident Time of Day: 1216

Accident Date Stamp: 08/28/08 12:16:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Physical obstruction(s)

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Thursday

Table 59. Accident 08023422 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Changing lanes	Unknown vehicle configuration	Motor vehicle in transport	1951/01/25	57
Vehicle 2	Northbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1966/02/14	42

Accident Details: Accident Case ID: 07023964

Accident

Accident ID: 07023964

Internal Accident ID: A88177

Inventory Element: S11585

Location: 22.138

GIS Identifier: 07023964

Accident Date: 2007/08/28

Accident Month: August

Accident Time of Day: 2005

Accident Date Stamp: 08/28/07 20:05:00

Accident Year: 2007

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Dark-not lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Collision with animal

Contributing Circumstances, Environment: Animal(s) in roadway

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 1

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 60. Accident 07023964 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Passenger car	Animal	1972/10/06	34
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Animal		

Accident Details: Accident Case ID: 09026873

Accident

Accident ID: 09026873
 Internal Accident ID: A137211
 Inventory Element: S11585
 Location: 22.1626
 GIS Identifier: 09026873
 Accident Date: 2009/11/07
 Accident Month: November
 Accident Time of Day: 1455
 Accident Date Stamp: 11/07/09 14:55:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Physical obstruction(s)
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No

Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Saturday

Table 61. Accident 09026873 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Changing lanes	Passenger car	Motor vehicle in transport	1992/03/11	17
Vehicle 2	Northbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1933/06/04	76

Accident Details: Accident Case ID: 09014536

Accident

Accident ID: 09014536
Internal Accident ID: A125582
Inventory Element: S11585
Location: 22.15313
GIS Identifier: 09014536
Accident Date: 2009/07/22
Accident Month: July
Accident Time of Day: 1810
Accident Date Stamp: 07/22/09 18:10:00
Accident Year: 2009
Accident Severity Level 1: Non-Incapacitating Injury
Number of Fatalities: 0
Number of Non-Fatal Injuries: 1
Relationship to Junction: Other
Driveway Indicator: No
Light Condition: Daylight
Weather Condition: Cloudy
Roadway Surface Condition: Dry
Accident Type and Manner of Collision: Other multiple-vehicle collision
Contributing Circumstances, Environment: None
Contributing Circumstances, Road: None
School Bus Related: Unknown
Work Zone Related: No
Number of Vehicles Involved: 2
Alcohol/Drug Involvement: Neither alcohol nor other drugs
Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 62. Accident 09014536 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Entering traffic lane	Sport utility vehicle	Motor vehicle in transport	1969/02/22	40
Vehicle 2	Northbound	Slowing	Passenger car	Motor vehicle in transport	1956/05/12	53

Accident Details: Accident Case ID: 05035859

Accident

Accident ID: 05035859
 Internal Accident ID: A47142
 Inventory Element: S11585
 Location: 22.15313
 GIS Identifier: 05035859
 Accident Date: 2005/12/22
 Accident Month: December
 Accident Time of Day: 1858
 Accident Date Stamp: 12/22/05 18:58:00
 Accident Year: 2005
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Other
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 63. Accident 05035859 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Backing	Light truck, only four tires	Motor vehicle in transport	1984/10/31	21
Vehicle 2	Southbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1983/08/24	22

Accident Details: Accident Case ID: 08011379

Accident

Accident ID: 08011379
 Internal Accident ID: A103025
 Inventory Element: S11585
 Location: 21.9637
 GIS Identifier: 08011379
 Accident Date: 2008/03/05
 Accident Month: March
 Accident Time of Day: 2310
 Accident Date Stamp: 03/05/08 23:10:00
 Accident Year: 2008
 Accident Severity Level 1: Possible Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Sleet, hail (freezing rain or drizzle)
 Roadway Surface Condition: Ice/frost
 Accident Type and Manner of Collision: Collision with fixed object
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown

Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: Yes
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 64. Accident 08011379 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Changing lanes	Sport utility vehicle	Guardrail face	1954/01/23	54
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Guardrail face		

Accident Details: Accident Case ID: 06009255

Accident

Accident ID: 06009255
 Internal Accident ID: A56170
 Inventory Element: S11585
 Location: 21.9392
 GIS Identifier: 06009255
 Accident Date: 2006/03/29
 Accident Month: March
 Accident Time of Day: 0652
 Accident Date Stamp: 03/29/06 06:52:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with fixed object
 Contributing Circumstances, Environment: Glare
 Contributing Circumstances, Road: None

School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: Yes
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 65. Accident 06009255 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Highway traffic sign or signpost	1975/11/22	30
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Highway traffic sign or signpost		

Accident Details: Accident Case ID: 09009658

Accident

Accident ID: 09009658
 Internal Accident ID: A125127
 Inventory Element: S11585
 Location: 22.1001
 GIS Identifier: 09009658
 Accident Date: 2009/03/21
 Accident Month: March
 Accident Time of Day: 1602
 Accident Date Stamp: 03/21/09 16:02:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Saturday

Table 66. Accident 09009658 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Changing lanes	Passenger car	Motor vehicle in transport	1956/06/03	52
Vehicle 2	Northbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1981/07/28	27

Accident Details: Accident Case ID: 07027475

Accident

Accident ID: 07027475
 Internal Accident ID: A88583
 Inventory Element: S11585
 Location: 22.0054
 GIS Identifier: 07027475
 Accident Date: 2007/10/07
 Accident Month: October
 Accident Time of Day: 1321
 Accident Date Stamp: 10/07/07 13:21:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear

Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with fixed object
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: Yes
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Sunday

Table 67. Accident 07027475 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Unknown	Sport utility vehicle	Embankment	1962/01/08	45
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Embankment		

Accident Details: Accident Case ID: 08001415

Accident

Accident ID: 08001415
 Internal Accident ID: A95505
 Inventory Element: S11585
 Location: 22.138
 GIS Identifier: 08001415
 Accident Date: 2008/01/18
 Accident Month: January
 Accident Time of Day: 1611
 Accident Date Stamp: 01/18/08 16:11:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No

Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 68. Accident 08001415 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Changing lanes	Passenger car	Motor vehicle in transport	1964/01/05	44
Vehicle 2	Westbound	Movements essentially straight ahead	Other	Motor vehicle in transport	1960/06/25	47

Accident Details: Accident Case ID: 05038708

Accident

Accident ID: 05038708
 Internal Accident ID: A46575
 Inventory Element: S11585
 Location: 21.9865
 GIS Identifier: 05038708
 Accident Date: 2005/12/28
 Accident Month: December
 Accident Time of Day: 1837
 Accident Date Stamp: 12/28/05 18:37:00
 Accident Year: 2005
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dusk
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Wednesday

Table 69. Accident 05038708 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Westbound	Making U-turn	Light truck, only four tires	Motor vehicle in transport		
Vehicle 2	Northbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1982/10/25	23

Accident Details: Accident Case ID: 05031739

Accident

Accident ID: 05031739
 Internal Accident ID: A41605
 Inventory Element: S11585
 Location: 22.1579
 GIS Identifier: 05031739
 Accident Date: 2005/10/31
 Accident Month: October
 Accident Time of Day: 0823
 Accident Date Stamp: 10/31/05 08:23:00
 Accident Year: 2005
 Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 70. Accident 05031739 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Slowing	Passenger car	Motor vehicle in transport	1938/10/09	67
Vehicle 2	Northbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1952/09/22	53

Accident Details: Accident Case ID: 05012185

Accident

Accident ID: 05012185
 Internal Accident ID: A39319
 Inventory Element: S11585
 Location: 22.1484
 GIS Identifier: 05012185
 Accident Date: 2005/03/30
 Accident Month: March
 Accident Time of Day: 1545
 Accident Date Stamp: 03/30/05 15:45:00

Accident Year: 2005
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: Yes
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 71. Accident 05012185 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Changing lanes	Light truck, only four tires	Motor vehicle in transport	1987/03/11	18
Vehicle 2	Northbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1953/11/02	51

Accident Details: Accident Case ID: 07016993

Accident

Accident ID: 07016993
 Internal Accident ID: A80897
 Inventory Element: S11585
 Location: 22.1001
 GIS Identifier: 07016993
 Accident Date: 2007/06/14
 Accident Month: June

Accident Time of Day: 1646
 Accident Date Stamp: 06/14/07 16:46:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 72. Accident 07016993 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Stopped in traffic	Light truck, only four tires	Motor vehicle in transport	1957/01/25	50
Vehicle 2	Northbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1928/04/17	79