

SafetyAnalyst

**Accident Summary for Route SR S0000120,
Milepost 25.517 to 25.686 (Segment 24594)**

May 12, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary 1

 1.1 Accident Case Identifier 1

 1.2 Accident Month 1

 1.3 Accident Severity Level 1 2

 1.4 Accident Time of Day 3

 1.5 Accident Type and Manner of Collision 3

 1.6 Alcohol/Drug Involvement 4

 1.7 Bicycle Indicator 4

 1.8 Contributing Circumstances, Environment 5

 1.9 Contributing Circumstances, Road 5

 1.10 Day of Week 6

 1.11 Divided Highway Flag-Side of Road 7

 1.12 Driver Age 7

 1.13 Driveway Indicator 8

 1.14 First Harmful Event 8

 1.15 Initial Direction of Travel 9

 1.16 Light Condition 9

 1.17 Number of Vehicles Involved 10

 1.18 Pedestrian Indicator 11

 1.19 Relationship to Junction 11

 1.20 Roadway Surface Condition 12

 1.21 Run-Off Road Indicator 12

 1.22 School Bus Related 13

 1.23 Tow-Away Indicator 13

 1.24 Vehicle Configuration 14

 1.25 Vehicle Maneuver/Action 14

 1.26 Vehicle Turning Movement 15

 1.27 Weather Condition 15

 1.28 Work Zone Related 16

2. Route SR S0000120 __, Milepost 25.517 to 25.686 17

3. Accident Case Details 19

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	3
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	3
Table 8. Accident Type and Manner of Collision	4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	4
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	4
Table 12. Bicycle Indicator	5
Table 13. Bicycle Indicator (Accident Case Identifier)	5
Table 14. Contributing Circumstances, Environment	5
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	5
Table 16. Contributing Circumstances, Road	6
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	6
Table 18. Day of Week	6
Table 19. Day of Week (Accident Case Identifier)	6
Table 20. Divided Highway Flag-Side of Road	7
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	7
Table 22. Driver Age in Years	7
Table 23. Driver Age in Years (Accident Case Identifier)	8
Table 24. Driveway Indicator	8
Table 25. Driveway Indicator (Accident Case Identifier)	8
Table 26. First Harmful Event	8
Table 27. First Harmful Event (Accident Case Identifier)	9
Table 28. Initial Direction of Travel	9
Table 29. Initial Direction of Travel (Accident Case Identifier)	9
Table 30. Light Condition	10
Table 31. Light Condition (Accident Case Identifier)	10
Table 32. Number of Vehicles Involved	10
Table 33. Number of Vehicles Involved (Accident Case Identifier)	10
Table 34. Pedestrian Indicator	11
Table 35. Pedestrian Indicator (Accident Case Identifier)	11
Table 36. Relationship to Junction	11
Table 37. Relationship to Junction (Accident Case Identifier)	11
Table 38. Roadway Surface Condition	12

Table 39. Roadway Surface Condition (Accident Case Identifier)	12
Table 40. Run-Off Road Indicator	12
Table 41. Run-Off Road Indicator (Accident Case Identifier)	12
Table 42. School Bus Related	13
Table 43. School Bus Related (Accident Case Identifier)	13
Table 44. Tow-Away Indicator	13
Table 45. Tow-Away Indicator (Accident Case Identifier)	13
Table 46. Vehicle Configuration	14
Table 47. Vehicle Configuration (Accident Case Identifier)	14
Table 48. Vehicle Maneuver/Action	14
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	15
Table 50. Vehicle Turning Movement	15
Table 51. Vehicle Turning Movement (Accident Case Identifier)	15
Table 52. Weather Condition	16
Table 53. Weather Condition (Accident Case Identifier)	16
Table 54. Work Zone Related	16
Table 55. Work Zone Related (Accident Case Identifier)	16
Table 56. Route SR S0000120__, Milepost 25.517 to 25.686 Directional Attributes	18
Table 57. Route SR S0000120__, Milepost 25.517 to 25.686 Annual Traffic	18
Table 58. Accident 06018655 Vehicle-Level Accident Data	20
Table 59. Accident 08005891 Vehicle-Level Accident Data	21
Table 60. Accident 09003066 Vehicle-Level Accident Data	22
Table 61. Accident 07022332 Vehicle-Level Accident Data	23
Table 62. Accident 07014031 Vehicle-Level Accident Data	24
Table 63. Accident 06015046 Vehicle-Level Accident Data	25
Table 64. Accident 06031251 Vehicle-Level Accident Data	26
Table 65. Accident 05004289 Vehicle-Level Accident Data	27
Table 66. Accident 09021160 Vehicle-Level Accident Data	28

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000120 __, Milepost 25.517 to 25.686 (Segment 24594)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **9 Total Accidents** spanning the dates **1/1/2005** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **25.517** to **25.686** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2005	05004289
2006	06018655, 06015046, 06031251
2007	07022332, 07014031
2008	08005891
2009	09003066, 09021160

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
January	1	0	0	1	1	3	33	10
May	0	0	1	0	0	1	11	9
June	0	1	0	0	0	1	11	9
July	0	1	0	0	0	1	11	8
August	0	0	1	0	0	1	11	8
October	0	0	0	0	1	1	11	8
December	0	1	0	0	0	1	11	9
Total Accidents	1	3	2	1	2	9	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
January	08005891, 09003066, 05004289
May	07014031
June	06015046
July	06018655
August	07022332
October	09021160
December	06031251

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	0	1	0	0	1	2	22	N/A
Property-Damage-Only	1	2	2	1	1	7	78	N/A
Total Accidents	1	3	2	1	2	9	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	09003066, 06031251
Property-Damage-Only	06018655, 08005891, 07022332, 07014031, 06015046, 05004289, 09021160

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
10:00 am to 10:59 am	0	0	1	0	0	1	11	N/A
4:00 pm to 4:59 pm	1	1	0	0	1	3	33	N/A
5:00 pm to 5:59 pm	0	2	1	1	1	5	56	N/A
Total Accidents	1	3	2	1	2	9	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
10:00 am to 10:59 am	07022332
4:00 pm to 4:59 pm	06018655,05004289, 09021160
5:00 pm to 5:59 pm	08005891,09003066, 07014031, 06015046, 06031251

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with animal	0	0	1	0	0	1	11	5
Other multiple-vehicle collision	1	3	1	1	2	8	89	49
Total Accidents	1	3	2	1	2	9	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with animal	07022332
Other multiple-vehicle collision	06018655, 08005891, 09003066, 07014031, 06015046, 06031251, 05004289, 09021160

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	1	3	2	1	2	9	100	95
Total Accidents	1	3	2	1	2	9	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	2	1	2	9	100	99
Total Accidents	1	3	2	1	2	9	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	2	1	1	2	7	78	65
Weather conditions	0	1	1	0	0	2	22	20
Total Accidents	1	3	2	1	2	9	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	08005891, 09003066, 07014031, 06015046, 06031251, 05004289, 09021160
Weather conditions	06018655, 07022332

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	1	3	2	1	2	9	100	94
Total Accidents	1	3	2	1	2	9	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Monday	0	1	1	0	0	2	22	14
Tuesday	0	1	1	0	0	2	22	14
Wednesday	0	0	0	1	0	1	11	15
Thursday	1	0	0	0	2	3	33	16
Friday	0	1	0	0	0	1	11	18
Total Accidents	1	3	2	1	2	9	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Monday	07022332, 06031251
Tuesday	07014031, 06015046
Wednesday	08005891
Thursday	09003066, 05004289, 09021160
Friday	06018655

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	3	2	1	2	9	100	100
Total Accidents	1	3	2	1	2	9	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	1	0	1	1	0	3	18	N/A
25 to 34	0	2	0	0	0	2	12	N/A
35 to 44	0	2	1	0	1	4	24	N/A
45 to 54	1	0	0	1	2	4	24	N/A
55 to 64	0	2	1	0	0	3	18	N/A
65 to 74	0	0	0	0	1	1	6	N/A
Total Vehicles	2	6	3	2	4	17	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	08005891, 07014031, 05004289
25 to 34	06018655, 06031251
35 to 44	09003066, 07022332, 06015046, 06015046
45 to 54	08005891, 09003066, 05004289, 09021160
55 to 64	06018655, 07014031, 06031251
65 to 74	09021160

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	2	1	2	9	100	86
Total Accidents	1	3	2	1	2	9	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Animal	0	0	1	0	0	1	6	N/A
Motor vehicle in transport	2	6	2	2	4	16	94	N/A
Total Vehicles	2	6	3	2	4	17	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Animal	07022332
Motor vehicle in transport	06018655, 06018655, 08005891, 08005891, 09003066, 09003066, 07014031, 07014031, 06015046, 06015046, 06031251, 06031251, 05004289, 05004289, 09021160, 09021160

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Northbound	2	6	2	2	2	14	82	N/A
Southbound	0	0	1	0	2	3	18	N/A
Total Vehicles	2	6	3	2	4	17	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Northbound	06018655, 06018655, 08005891, 08005891, 09003066, 09003066, 07014031, 07014031, 06015046, 06015046, 06031251, 06031251, 05004289, 05004289
Southbound	07022332, 09021160, 09021160

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	1	2	2	0	1	6	67	70
Dark-lighted	0	1	0	1	1	3	33	14
Total Accidents	1	3	2	1	2	9	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	06018655, 07022332, 07014031, 06015046, 05004289, 09021160
Dark-lighted	08005891, 09003066, 06031251

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1 Vehicle	0	0	1	0	0	1	11	N/A
2 Vehicles	0	2	1	0	1	4	44	N/A
More than 2 Vehicles	1	1	0	1	1	4	44	N/A
Total Accidents	1	3	2	1	2	9	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
1 Vehicle	07022332
2 Vehicles	07014031, 06015046, 06031251, 09021160
More than 2 Vehicles	06018655, 08005891, 09003066, 05004289

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	2	1	2	9	100	98
Total Accidents	1	3	2	1	2	9	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	1	3	2	1	2	9	100	83
Total Accidents	1	3	2	1	2	9	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	1	2	1	1	2	7	78	69
Wet	0	1	1	0	0	2	22	15
Total Accidents	1	3	2	1	2	9	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	08005891, 09003066, 07014031, 06015046, 06031251, 05004289, 09021160
Wet	06018655, 07022332

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	2	1	2	9	100	77
Total Accidents	1	3	2	1	2	9	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	3	2	1	2	9	100	100
Total Accidents	1	3	2	1	2	9	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	1	3	2	1	2	9	100	100
Total Accidents	1	3	2	1	2	9	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	1	3	2	1	3	10	59	N/A
Light truck, only four tires	0	2	1	0	0	3	18	N/A
Sport utility vehicle	1	1	0	1	0	3	18	N/A
Unknown vehicle configuration	0	0	0	0	1	1	6	N/A
Total Vehicles	2	6	3	2	4	17	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	06018655, 08005891, 09003066, 09003066, 07014031, 07014031, 06031251, 06031251, 05004289, 09021160
Light truck, only four tires	06018655, 07022332, 06015046
Sport utility vehicle	08005891, 06015046, 05004289
Unknown vehicle configuration	09021160

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	0	3	1	2	2	8	47	N/A
Changing lanes	0	0	0	0	1	1	6	N/A
Entering traffic lane	0	0	1	0	0	1	6	N/A
Slowing	2	2	0	0	1	5	29	N/A
Stopped in traffic	0	1	1	0	0	2	12	N/A
Total Vehicles	2	6	3	2	4	17	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	06018655, 08005891, 08005891, 09003066, 07022332, 06015046, 06031251, 09021160
Changing lanes	09021160
Entering traffic lane	07014031
Slowing	06018655, 09003066, 06015046, 05004289, 05004289
Stopped in traffic	07014031, 06031251

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No-turn	1	3	2	1	2	9	100	83
Total Accidents	1	3	2	1	2	9	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
No-turn	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	1	1	1	1	1	5	56	60
Cloudy	0	1	0	0	1	2	22	19
Rain	0	1	1	0	0	2	22	9
Total Accidents	1	3	2	1	2	9	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	08005891, 09003066, 07014031, 06015046, 05004289
Cloudy	06031251, 09021160
Rain	06018655, 07022332

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	1	3	2	1	2	9	100	98
Total Accidents	1	3	2	1	2	9	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	06018655, 08005891, 09003066, 07022332, 07014031, 06015046, 06031251, 05004289, 09021160

2. Route SR S0000120 __, Milepost 25.517 to 25.686

Roadway Segment

Segment ID: 24594
Internal Segment ID: S8814
Route Number Display Value: SRS0000120 __
Site Subtype: Seg/Urb; 2-lane arterial
Start Location: 25.517
End Location: 25.686
GIS Identifier: 24594
Next Roadway Segment ID: S4002
Previous Roadway Segment ID: S121
Next Intersection ID: I1152
Previous Intersection ID: I1839
Segment Length: 0.1690 miles
Roadway Class Level 1: Minor arterial
Roadway Class Level 2: Minor arterial urban
Roadway Class Level 3: Urban two-lane
Number of Through Lanes - Combined: 2
Median Type Level 1: Undivided
Median Type Level 2: Undivided
Median Width: 0.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 11,340 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Northbound
Interchange Influence Area on Mainline Freeway: No
Number of Accidents: 9

Geographic Description

Identifier: G111
Route Type: State route
Route Name: S0000120 __
Major Road Name: Lebanon St
County: GRAFTON
District: 2
City/Town: HANOVER
Jurisdiction: State maintained
Area Type: Urban

Table 56. Route SR S0000120 __, Milepost 25.517 to 25.686 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	1	14.00	Paved	Paved	4.00	10.00		
Direction 2	1	14.00	Paved	Paved	4.00	10.00		

Table 57. Route SR S0000120 __, Milepost 25.517 to 25.686 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	11,340			Growth Factor Applied	
2003	11,340			Growth Factor Applied	
2004	11,340			Growth Factor Applied	
2005	11,340			Growth Factor Applied	
2006	11,340			Growth Factor Applied	
2007	11,340			Growth Factor Applied	
2008	11,340			Growth Factor Applied	
2009	11,340			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 06018655

Accident

Accident ID: 06018655

Internal Accident ID: A63716

Inventory Element: S8814

Location: 25.5271

GIS Identifier: 06018655

Accident Date: 2006/07/28

Accident Month: July

Accident Time of Day: 1630

Accident Date Stamp: 07/28/06 16:30:00

Accident Year: 2006

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Rain

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: Weather conditions

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Friday

Table 58. Accident 06018655 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1949/06/04	57
Vehicle 2	Northbound	Slowing	Passenger car	Motor vehicle in transport	1971/08/22	34

Accident Details: Accident Case ID: 08005891

Accident

Accident ID: 08005891

Internal Accident ID: A96616

Inventory Element: S8814

Location: 25.5271

GIS Identifier: 08005891

Accident Date: 2008/01/16

Accident Month: January

Accident Time of Day: 1734

Accident Date Stamp: 01/16/08 17:34:00

Accident Year: 2008

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Wednesday

Table 59. Accident 08005891 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1990/03/15	17
Vehicle 2	Northbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1962/01/14	46

Accident Details: Accident Case ID: 09003066

Accident

Accident ID: 09003066

Internal Accident ID: A121784

Inventory Element: S8814

Location: 25.5366

GIS Identifier: 09003066

Accident Date: 2009/01/15

Accident Month: January

Accident Time of Day: 1718

Accident Date Stamp: 01/15/09 17:18:00

Accident Year: 2009

Accident Severity Level 1: Non-Incapacitating Injury

Number of Fatalities: 0

Number of Non-Fatal Injuries: 1

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Dark-lighted

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 3

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 60. Accident 09003066 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1965/05/10	43
Vehicle 2	Northbound	Slowing	Passenger car	Motor vehicle in transport	1957/04/24	51

Accident Details: Accident Case ID: 07022332

Accident

Accident ID: 07022332
 Internal Accident ID: A85013
 Inventory Element: S8814
 Location: 25.51763
 GIS Identifier: 07022332
 Accident Date: 2007/08/06
 Accident Month: August
 Accident Time of Day: 1007
 Accident Date Stamp: 08/06/07 10:07:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Rain
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Collision with animal
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No

Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 61. Accident 07022332 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Light truck, only four tires	Animal	1970/03/16	37
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Animal		

Accident Details: Accident Case ID: 07014031

Accident

Accident ID: 07014031
 Internal Accident ID: A80895
 Inventory Element: S8814
 Location: 25.6772
 GIS Identifier: 07014031
 Accident Date: 2007/05/15
 Accident Month: May
 Accident Time of Day: 1724
 Accident Date Stamp: 05/15/07 17:24:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown

Run-Off Road Indicator: No
Pedestrian Indicator: No
Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Tuesday

Table 62. Accident 07014031 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Entering traffic lane	Passenger car	Motor vehicle in transport	1986/06/20	20
Vehicle 2	Northbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1946/12/12	60

Accident Details: Accident Case ID: 06015046

Accident

Accident ID: 06015046
Internal Accident ID: A55315
Inventory Element: S8814
Location: 25.5366
GIS Identifier: 06015046
Accident Date: 2006/06/27
Accident Month: June
Accident Time of Day: 1717
Accident Date Stamp: 06/27/06 17:17:00
Accident Year: 2006
Accident Severity Level 1: Property-Damage-Only
Number of Fatalities: 0
Number of Non-Fatal Injuries: 0
Relationship to Junction: Non-junction
Driveway Indicator: No
Light Condition: Daylight
Weather Condition: Clear
Roadway Surface Condition: Dry
Accident Type and Manner of Collision: Other multiple-vehicle collision
Contributing Circumstances, Environment: None
Contributing Circumstances, Road: None
School Bus Related: Unknown
Work Zone Related: No
Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 63. Accident 06015046 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1966/05/24	40
Vehicle 2	Northbound	Slowing	Light truck, only four tires	Motor vehicle in transport	1970/10/18	35

Accident Details: Accident Case ID: 06031251

Accident

Accident ID: 06031251
 Internal Accident ID: A65337
 Inventory Element: S8814
 Location: 25.51763
 GIS Identifier: 06031251
 Accident Date: 2006/12/04
 Accident Month: December
 Accident Time of Day: 1725
 Accident Date Stamp: 12/04/06 17:25:00
 Accident Year: 2006
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown

Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 64. Accident 06031251 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1981/10/17	25
Vehicle 2	Northbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1948/11/18	58

Accident Details: Accident Case ID: 05004289

Accident

Accident ID: 05004289
 Internal Accident ID: A33087
 Inventory Element: S8814
 Location: 25.5366
 GIS Identifier: 05004289
 Accident Date: 2005/01/27
 Accident Month: January
 Accident Time of Day: 1608
 Accident Date Stamp: 01/27/05 16:08:00
 Accident Year: 2005
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None
School Bus Related: Unknown
Work Zone Related: No
Number of Vehicles Involved: 3
Alcohol/Drug Involvement: Neither alcohol nor other drugs
Tow-Away Indicator: Unknown
Run-Off Road Indicator: No
Pedestrian Indicator: No
Bicycle Indicator: No
Divided Highway Flag-Side of Road: Unknown
Vehicle Turning Movement: No-turn
Day of Week: Thursday

Table 65. Accident 05004289 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Slowing	Passenger car	Motor vehicle in transport	1955/12/25	49
Vehicle 2	Northbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1985/09/19	19

Accident Details: Accident Case ID: 09021160

Accident

Accident ID: 09021160
Internal Accident ID: A130027
Inventory Element: S8814
Location: 25.546
GIS Identifier: 09021160
Accident Date: 2009/10/01
Accident Month: October
Accident Time of Day: 1611
Accident Date Stamp: 10/01/09 16:11:00
Accident Year: 2009
Accident Severity Level 1: Property-Damage-Only
Number of Fatalities: 0
Number of Non-Fatal Injuries: 0
Relationship to Junction: Non-junction
Driveway Indicator: No
Light Condition: Daylight
Weather Condition: Cloudy
Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Thursday

Table 66. Accident 09021160 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Changing lanes	Passenger car	Motor vehicle in transport	1944/08/20	65
Vehicle 2	Southbound	Movements essentially straight ahead	Unknown vehicle configuration	Motor vehicle in transport	1954/12/25	54