

SafetyAnalyst

**Accident Summary for Route SR S0000120—,
Milepost 22.53 to 22.982 (Segment 2697)**

May 12, 2011

Notice

This Software Product is owned by the American Association of State Highway and Transportation Officials, Inc. ("AASHTO") and is being Licensed to your agency or employer under the terms of a Master and Supplemental agreement ("License Agreements") with AASHTO. The License Agreements contain important terms and conditions relating to the use of the Software Products which are binding on your agency or employer and you, including: limitations on AASHTO warranties; prohibitions on reverse engineering and unauthorized distribution or copying; protections of AASHTO patent, copyright, trademark and other proprietary rights; procedures for addressing defects; and termination and return of the Software Product. Violations of any of the terms of the License Agreements may result in the termination of your right to use this Software Product. Copies of the License Agreements are available from your agency or employer or from AASHTO.

By installing and/or using this Software Product, you acknowledge that you have read and understood this NOTICE and agree to comply with the terms and conditions of the License Agreements.

Table of Contents

1. Accident Summary	1
1.1 Accident Case Identifier	1
1.2 Accident Month	1
1.3 Accident Severity Level 1	2
1.4 Accident Time of Day	3
1.5 Accident Type and Manner of Collision	4
1.6 Alcohol/Drug Involvement	5
1.7 Bicycle Indicator	5
1.8 Contributing Circumstances, Environment	6
1.9 Contributing Circumstances, Road	6
1.10 Day of Week	7
1.11 Divided Highway Flag-Side of Road	7
1.12 Driver Age	8
1.13 Driveway Indicator	9
1.14 First Harmful Event	9
1.15 Initial Direction of Travel	10
1.16 Light Condition	11
1.17 Number of Vehicles Involved	11
1.18 Pedestrian Indicator	12
1.19 Relationship to Junction	13
1.20 Roadway Surface Condition	13
1.21 Run-Off Road Indicator	14
1.22 School Bus Related	14
1.23 Tow-Away Indicator	15
1.24 Vehicle Configuration	15
1.25 Vehicle Maneuver/Action	16
1.26 Vehicle Turning Movement	17
1.27 Weather Condition	18
1.28 Work Zone Related	18
2. Route SR S0000120 __, Milepost 22.53 to 22.982	20
3. Accident Case Details	22

List of Tables

Table 1. Accident Case Identifier by Year	1
Table 2. Accident Month	2
Table 3. Accident Month (Accident Case Identifier)	2
Table 4. Accident Severity Level 1	2
Table 5. Accident Severity Level 1 (Accident Case Identifier)	3
Table 6. Accident Time of Day	3
Table 7. Accident Time of Day (Accident Case Identifier)	4
Table 8. Accident Type and Manner of Collision	4
Table 9. Accident Type and Manner of Collision (Accident Case Identifier)	4
Table 10. Alcohol/Drug Involvement	5
Table 11. Alcohol/Drug Involvement (Accident Case Identifier)	5
Table 12. Bicycle Indicator	5
Table 13. Bicycle Indicator (Accident Case Identifier)	6
Table 14. Contributing Circumstances, Environment	6
Table 15. Contributing Circumstances, Environment (Accident Case Identifier)	6
Table 16. Contributing Circumstances, Road	6
Table 17. Contributing Circumstances, Road (Accident Case Identifier)	7
Table 18. Day of Week	7
Table 19. Day of Week (Accident Case Identifier)	7
Table 20. Divided Highway Flag-Side of Road	8
Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)	8
Table 22. Driver Age in Years	8
Table 23. Driver Age in Years (Accident Case Identifier)	9
Table 24. Driveway Indicator	9
Table 25. Driveway Indicator (Accident Case Identifier)	9
Table 26. First Harmful Event	10
Table 27. First Harmful Event (Accident Case Identifier)	10
Table 28. Initial Direction of Travel	10
Table 29. Initial Direction of Travel (Accident Case Identifier)	11
Table 30. Light Condition	11
Table 31. Light Condition (Accident Case Identifier)	11
Table 32. Number of Vehicles Involved	12
Table 33. Number of Vehicles Involved (Accident Case Identifier)	12
Table 34. Pedestrian Indicator	12
Table 35. Pedestrian Indicator (Accident Case Identifier)	12
Table 36. Relationship to Junction	13
Table 37. Relationship to Junction (Accident Case Identifier)	13
Table 38. Roadway Surface Condition	13

Table 39. Roadway Surface Condition (Accident Case Identifier)	14
Table 40. Run-Off Road Indicator	14
Table 41. Run-Off Road Indicator (Accident Case Identifier)	14
Table 42. School Bus Related	15
Table 43. School Bus Related (Accident Case Identifier)	15
Table 44. Tow-Away Indicator	15
Table 45. Tow-Away Indicator (Accident Case Identifier)	15
Table 46. Vehicle Configuration	16
Table 47. Vehicle Configuration (Accident Case Identifier)	16
Table 48. Vehicle Maneuver/Action	16
Table 49. Vehicle Maneuver/Action (Accident Case Identifier)	17
Table 50. Vehicle Turning Movement	17
Table 51. Vehicle Turning Movement (Accident Case Identifier)	17
Table 52. Weather Condition	18
Table 53. Weather Condition (Accident Case Identifier)	18
Table 54. Work Zone Related	19
Table 55. Work Zone Related (Accident Case Identifier)	19
Table 56. Route SR S0000120 __, Milepost 22.53 to 22.982 Directional Attributes	21
Table 57. Route SR S0000120 __, Milepost 22.53 to 22.982 Annual Traffic	21
Table 58. Accident 07032651 Vehicle-Level Accident Data	23
Table 59. Accident 09025686 Vehicle-Level Accident Data	24
Table 60. Accident 05016829 Vehicle-Level Accident Data	25
Table 61. Accident 06033692 Vehicle-Level Accident Data	26
Table 62. Accident 07011166 Vehicle-Level Accident Data	27
Table 63. Accident 08028349 Vehicle-Level Accident Data	28
Table 64. Accident 07029580 Vehicle-Level Accident Data	29
Table 65. Accident 05019838 Vehicle-Level Accident Data	30
Table 66. Accident 09018209 Vehicle-Level Accident Data	31
Table 67. Accident 08012845 Vehicle-Level Accident Data	32
Table 68. Accident 05015225 Vehicle-Level Accident Data	33
Table 69. Accident 09022866 Vehicle-Level Accident Data	34
Table 70. Accident 09007102 Vehicle-Level Accident Data	35
Table 71. Accident 07035239 Vehicle-Level Accident Data	36
Table 72. Accident 09009010 Vehicle-Level Accident Data	37

1. Accident Summary

This is a summary of the accident data associated with the following Segment from the **NH State 2009** data set, created on Apr 2, 2010 9:54 AM:

Route SR S0000120 __, Milepost 22.53 to 22.982 (Segment 2697)

The details for this site are listed in the [next](#) section.

Notes:

The summary includes **15 Total Accidents** spanning the dates **1/1/2005** to **12/31/2009**.

Dates excluded from the summary period due to major reconstruction: **option not selected when specifying the analysis period.**

The summary includes accidents that occur at the site between locations **22.53** to **22.982** inclusive.

1.1 Accident Case Identifier

Unique case numbers of the accidents for the site and analysis period.

Table 1. Accident Case Identifier by Year

Description	Accident Case Identifier
2005	05016829, 05019838, 05015225
2006	06033692
2007	07032651, 07011166, 07029580, 07035239
2008	08028349, 08012845
2009	09025686, 09018209, 09022866, 09007102, 09009010

1.2 Accident Month

The month in which the accident occurred.

Table 2. Accident Month

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
March	0	0	0	0	2	2	13	7
April	1	0	1	1	0	3	20	6
June	2	0	0	0	0	2	13	9
August	0	0	0	0	2	2	13	9
October	0	0	1	0	1	2	13	9
November	0	0	2	1	0	3	20	8
December	0	1	0	0	0	1	7	10
Total Accidents	3	1	4	2	5	15	100	100

Table 3. Accident Month (Accident Case Identifier)

Description	Accident Case Identifier
March	09007102, 09009010
April	07011166, 08012845, 05015225
June	05016829, 05019838
August	09018209, 09022866
October	09025686, 07029580
November	07032651, 08028349, 07035239
December	06033692

1.3 Accident Severity Level 1

The severity of the accident based on the most severe injury to any person involved.

Table 4. Accident Severity Level 1

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-Incapacitating Injury	0	0	0	0	1	1	7	N/A
Property-Damage-Only	3	1	4	2	4	14	93	N/A
Total Accidents	3	1	4	2	5	15	100	N/A

Table 5. Accident Severity Level 1 (Accident Case Identifier)

Description	Accident Case Identifier
Non-Incapacitating Injury	09022866
Property-Damage-Only	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09007102, 07035239, 09009010

1.4 Accident Time of Day

The time (hour and minute) at which the accident occurred.

Table 6. Accident Time of Day

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
2:00 am to 2:59 am	0	0	1	0	0	1	7	N/A
5:00 am to 5:59 am	0	0	1	0	0	1	7	N/A
7:00 am to 7:59 am	0	0	1	0	1	2	13	N/A
8:00 am to 8:59 am	1	0	0	1	0	2	13	N/A
9:00 am to 9:59 am	1	0	0	0	1	2	13	N/A
11:00 am to 11:59 am	0	0	0	1	0	1	7	N/A
2:00 pm to 2:59 pm	1	0	0	0	0	1	7	N/A
3:00 pm to 3:59 pm	0	0	0	0	1	1	7	N/A
4:00 pm to 4:59 pm	0	0	0	0	1	1	7	N/A
5:00 pm to 5:59 pm	0	0	0	0	1	1	7	N/A
7:00 pm to 7:59 pm	0	0	1	0	0	1	7	N/A
11:00 pm to 11:59 pm	0	1	0	0	0	1	7	N/A
Total Accidents	3	1	4	2	5	15	100	N/A

Table 7. Accident Time of Day (Accident Case Identifier)

Description	Accident Case Identifier
2:00 am to 2:59 am	07035239
5:00 am to 5:59 am	07011166
7:00 am to 7:59 am	07032651,09009010
8:00 am to 8:59 am	05016829,08028349
9:00 am to 9:59 am	05019838,09007102
11:00 am to 11:59 am	08012845
2:00 pm to 2:59 pm	05015225
3:00 pm to 3:59 pm	09025686
4:00 pm to 4:59 pm	09018209
5:00 pm to 5:59 pm	09022866
7:00 pm to 7:59 pm	07029580
11:00 pm to 11:59 pm	06033692

1.5 Accident Type and Manner of Collision

The type of first harmful event in a single-vehicle accident or, in a multiple-vehicle collision, manner in which two vehicles in transport initially came together without regard to the direction of force, or the type of object with which a single vehicle collided.

Table 8. Accident Type and Manner of Collision

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Collision with animal	1	1	1	0	0	3	20	1
Collision with fixed object	0	0	2	0	0	2	13	5
Rear-end	0	0	0	1	1	2	13	13
Other multiple-vehicle collision	2	0	1	1	4	8	53	65
Total Accidents	3	1	4	2	5	15	100	100

Table 9. Accident Type and Manner of Collision (Accident Case Identifier)

Description	Accident Case Identifier
Collision with animal	05016829, 06033692, 07029580
Collision with fixed object	07011166, 07035239
Rear-end	08012845, 09009010
Other multiple-vehicle collision	07032651, 09025686, 08028349, 05019838, 09018209, 05015225, 09022866, 09007102

1.6 Alcohol/Drug Involvement

The investigating police officer's assessment of whether alcohol or drug use was suspected or demonstrated to be present by test for any vehicle driver or non-motorist in the accident.

Table 10. Alcohol/Drug Involvement

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Neither alcohol nor other drugs	3	1	3	2	5	14	93	98
Yes (alcohol)	0	0	1	0	0	1	7	0
Total Accidents	3	1	4	2	5	15	100	100

Table 11. Alcohol/Drug Involvement (Accident Case Identifier)

Description	Accident Case Identifier
Neither alcohol nor other drugs	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 09009010
Yes (alcohol)	07035239

1.7 Bicycle Indicator

Indicates whether a bicycle was involved in the accident.

Table 12. Bicycle Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	3	1	4	2	5	15	100	99
Total Accidents	3	1	4	2	5	15	100	100

Table 13. Bicycle Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010

1.8 Contributing Circumstances, Environment

Apparent environmental conditions which contributed to the accident.

Table 14. Contributing Circumstances, Environment

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	2	0	2	1	4	9	60	70
Weather conditions	0	0	1	1	1	3	20	14
Animal(s) in roadway	1	1	1	0	0	3	20	1
Total Accidents	3	1	4	2	5	15	100	100

Table 15. Contributing Circumstances, Environment (Accident Case Identifier)

Description	Accident Case Identifier
None	07032651, 09025686, 08028349, 05019838, 09018209, 05015225, 09022866, 07035239, 09009010
Weather conditions	07011166, 08012845, 09007102
Animal(s) in roadway	05016829, 06033692, 07029580

1.9 Contributing Circumstances, Road

Apparent conditions of the road which contributed to the accident.

Table 16. Contributing Circumstances, Road

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
None	2	1	4	2	5	14	93	95
Unknown	1	0	0	0	0	1	7	3
Total Accidents	3	1	4	2	5	15	100	100

Table 17. Contributing Circumstances, Road (Accident Case Identifier)

Description	Accident Case Identifier
None	07032651, 09025686, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010
Unknown	05016829

1.10 Day of Week

The day of the week on which the accident occurred.

Table 18. Day of Week

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Sunday	0	0	0	0	1	1	7	8
Monday	0	0	0	1	2	3	20	13
Tuesday	1	0	1	1	1	4	27	13
Wednesday	0	0	1	0	0	1	7	16
Thursday	1	1	1	0	1	4	27	17
Friday	1	0	1	0	0	2	13	19
Total Accidents	3	1	4	2	5	15	100	100

Table 19. Day of Week (Accident Case Identifier)

Description	Accident Case Identifier
Sunday	09022866
Monday	09018209, 08012845, 09007102
Tuesday	07032651, 09025686, 08028349, 05015225
Wednesday	07029580
Thursday	06033692, 07011166, 05019838, 09009010
Friday	05016829, 07035239

1.11 Divided Highway Flag-Side of Road

Indicates the direction of travel for the side of the divided highway where the accident occurred. Mandatory for agencies that keep independent records

for the individual sides of a divided highway. Can be used for divided highway by any agency.

Table 20. Divided Highway Flag-Side of Road

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	3	1	4	2	5	15	100	100
Total Accidents	3	1	4	2	5	15	100	100

Table 21. Divided Highway Flag-Side of Road (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010

1.12 Driver Age

The value of this item is the driver age, in years, at the time of the accident. The value of this item is calculated during data set post processing.

Table 22. Driver Age in Years

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Under 25	0	0	1	0	0	1	4	N/A
25 to 34	2	1	1	1	2	7	28	N/A
35 to 44	0	0	0	1	3	4	16	N/A
45 to 54	1	0	3	2	0	6	24	N/A
55 to 64	1	0	0	0	5	6	24	N/A
75 to 84	1	0	0	0	0	1	4	N/A
Total Vehicles	5	1	5	4	10	25	100	N/A

Table 23. Driver Age in Years (Accident Case Identifier)

Description	Accident Case Identifier
Under 25	07032651
25 to 34	05016829, 06033692, 08028349, 05019838, 09007102, 07035239, 09009010
35 to 44	09025686, 09018209, 08012845, 09022866
45 to 54	07032651, 07011166, 08028349, 07029580, 08012845, 05015225
55 to 64	09025686, 05019838, 09018209, 09022866, 09007102, 09009010
75 to 84	05015225

1.13 Driveway Indicator

Indicates if the accident occurred at or near a driveway junction.

Table 24. Driveway Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	3	1	4	2	5	15	100	79
Total Accidents	3	1	4	2	5	15	100	100

Table 25. Driveway Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010

1.14 First Harmful Event

The first injury or damage-producing event that characterizes the accident type.

Table 26. First Harmful Event

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Animal	1	1	1	0	0	3	12	N/A
Motor vehicle in transport	4	0	2	4	10	20	80	N/A
Embankment	0	0	1	0	0	1	4	N/A
Other traffic barrier	0	0	1	0	0	1	4	N/A
Total Vehicles	5	1	5	4	10	25	100	N/A

Table 27. First Harmful Event (Accident Case Identifier)

Description	Accident Case Identifier
Animal	05016829, 06033692, 07029580
Motor vehicle in transport	07032651, 07032651, 09025686, 09025686, 08028349, 08028349, 05019838, 05019838, 09018209, 09018209, 08012845, 08012845, 05015225, 05015225, 09022866, 09022866, 09007102, 09007102, 09009010, 09009010
Embankment	07035239
Other traffic barrier	07011166

1.15 Initial Direction of Travel

The direction of a vehicle's normal, general travel on the roadway before the accident. Notice that this is not a compass direction but a direction consistent with the designated direction of the road. For example, the direction of a state designated north-south highway must be either northbound or southbound even though a vehicle may have been traveling due east as a result of a short segment of the highway having an east-west orientation.

Table 28. Initial Direction of Travel

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Northbound	1	0	4	4	4	13	52	N/A
Southbound	4	1	1	0	5	11	44	N/A
Eastbound	0	0	0	0	1	1	4	N/A
Total Vehicles	5	1	5	4	10	25	100	N/A

Table 29. Initial Direction of Travel (Accident Case Identifier)

Description	Accident Case Identifier
Northbound	07032651, 07032651, 05016829, 07011166, 08028349, 08028349, 07029580, 08012845, 08012845, 09022866, 09007102, 09009010, 09009010
Southbound	09025686, 09025686, 06033692, 05019838, 05019838, 09018209, 09018209, 05015225, 05015225, 09007102, 07035239
Eastbound	09022866

1.16 Light Condition

The type/level of lighting that existed at the time of the accident.

Table 30. Light Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Daylight	2	1	1	2	5	11	73	75
Dark-lighted	0	0	2	0	0	2	13	16
Dark-not lighted	0	0	1	0	0	1	7	2
Unknown	1	0	0	0	0	1	7	3
Total Accidents	3	1	4	2	5	15	100	100

Table 31. Light Condition (Accident Case Identifier)

Description	Accident Case Identifier
Daylight	07032651, 09025686, 06033692, 08028349, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 09009010
Dark-lighted	07011166, 07035239
Dark-not lighted	07029580
Unknown	05016829

1.17 Number of Vehicles Involved

The count of motor vehicles (e.g., automobiles, single-unit trucks, truck combinations that are in motion or on a roadway) involved in the accident.

(Note: Parked vehicles are not included in this vehicle count, nor are bicycles and pedestrians.)

Table 32. Number of Vehicles Involved

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
1 Vehicle	1	1	3	0	0	5	33	N/A
2 Vehicles	2	0	1	2	4	9	60	N/A
More than 2 Vehicles	0	0	0	0	1	1	7	N/A
Total Accidents	3	1	4	2	5	15	100	N/A

Table 33. Number of Vehicles Involved (Accident Case Identifier)

Description	Accident Case Identifier
1 Vehicle	05016829, 06033692, 07011166, 07029580, 07035239
2 Vehicles	07032651, 09025686, 08028349, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102
More than 2 Vehicles	09009010

1.18 Pedestrian Indicator

Indicates whether a pedestrian was involved in the accident.

Table 34. Pedestrian Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	3	1	4	2	5	15	100	98
Total Accidents	3	1	4	2	5	15	100	100

Table 35. Pedestrian Indicator (Accident Case Identifier)

Description	Accident Case Identifier
No	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010

1.19 Relationship to Junction

Identifies the type of related cross street to the accident site.

Definitions vary across states. For compatibility with the structure of SafetyAnalyst, a recoding that differs from MMUCC is recommended. Some distinctions that MMUCC tries to make in this field will instead be made in site characteristics data in SafetyAnalyst.

Table 36. Relationship to Junction

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Non-junction	3	1	4	2	5	15	100	71
Total Accidents	3	1	4	2	5	15	100	100

Table 37. Relationship to Junction (Accident Case Identifier)

Description	Accident Case Identifier
Non-junction	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010

1.20 Roadway Surface Condition

The roadway surface condition at the time and place of the accident.

Table 38. Roadway Surface Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Dry	3	1	2	1	4	11	73	76
Wet	0	0	1	1	0	2	13	18
Snow	0	0	1	0	1	2	13	4
Total Accidents	3	1	4	2	5	15	100	100

Table 39. Roadway Surface Condition (Accident Case Identifier)

Description	Accident Case Identifier
Dry	09025686, 05016829, 06033692, 08028349, 07029580, 05019838, 09018209, 05015225, 09022866, 07035239, 09009010
Wet	07032651, 08012845
Snow	07011166, 09007102

1.21 Run-Off Road Indicator

Indicates whether any vehicle involved in the accident ran off the roadway.

Table 40. Run-Off Road Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Yes	0	0	2	0	0	2	13	6
No	3	1	2	2	5	13	87	94
Total Accidents	3	1	4	2	5	15	100	100

Table 41. Run-Off Road Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Yes	07011166, 07035239
No	07032651, 09025686, 05016829, 06033692, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 09009010

1.22 School Bus Related

Indicates if a school bus or vehicle functioning as a school bus for a school-related purpose was involved in the accident. The school bus, with or without a passenger on board, must be directly involved as a contact vehicle or indirectly involved as a non-contact vehicle.

Table 42. School Bus Related

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	3	1	4	2	5	15	100	100
Total Accidents	3	1	4	2	5	15	100	100

Table 43. School Bus Related (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010

1.23 Tow-Away Indicator

Indicates whether any vehicle involved in the accident was towed away from the scene.

Table 44. Tow-Away Indicator

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Unknown	3	1	4	2	5	15	100	100
Total Accidents	3	1	4	2	5	15	100	100

Table 45. Tow-Away Indicator (Accident Case Identifier)

Description	Accident Case Identifier
Unknown	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010

1.24 Vehicle Configuration

Indicates the general configuration of the vehicle.

Table 46. Vehicle Configuration

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Passenger car	3	0	4	2	4	13	52	N/A
Light truck, only four tires	1	0	0	1	3	5	20	N/A
Sport utility vehicle	1	1	0	1	2	5	20	N/A
Other	0	0	0	0	1	1	4	N/A
Unknown vehicle configuration	0	0	1	0	0	1	4	N/A
Total Vehicles	5	1	5	4	10	25	100	N/A

Table 47. Vehicle Configuration (Accident Case Identifier)

Description	Accident Case Identifier
Passenger car	07032651, 09025686, 05016829, 07011166, 08028349, 07029580, 05019838, 05019838, 08012845, 09022866, 09007102, 07035239, 09009010
Light truck, only four tires	08012845, 05015225, 09022866, 09007102, 09009010
Sport utility vehicle	09025686, 06033692, 08028349, 09018209, 05015225
Other	09018209
Unknown vehicle configuration	07032651

1.25 Vehicle Maneuver/Action

The controlled maneuver that the vehicle was doing prior to the first event in the sequence of events for this vehicle.

Table 48. Vehicle Maneuver/Action

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Movements essentially straight ahead	5	1	4	2	4	16	64	N/A
Overtaking/passing	0	0	0	0	1	1	4	N/A
Turning left	0	0	0	0	2	2	8	N/A
Slowing	0	0	1	2	0	3	12	N/A
Stopped in traffic	0	0	0	0	3	3	12	N/A
Total Vehicles	5	1	5	4	10	25	100	N/A

Table 49. Vehicle Maneuver/Action (Accident Case Identifier)

Description	Accident Case Identifier
Movements essentially straight ahead	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 05019838, 08012845, 05015225, 05015225, 09007102, 09007102, 07035239, 09009010
Overtaking/passing	09018209
Turning left	09022866, 09022866
Slowing	07032651, 08028349, 08012845
Stopped in traffic	09025686, 09018209, 09009010

1.26 Vehicle Turning Movement

Characterization of multiple vehicle accidents where any involved vehicle was performing a turning maneuver prior to impact. Any left turn maneuver or U-turn maneuver will take precedence over any right turn maneuver. For example, if Vehicle 1 made a left turn and Vehicle 2 made a right turn, then this data item will be classified as a left turn accident. Even though the first level of this data element is labeled Left turn, the left turn category also includes U-turn accidents.

Table 50. Vehicle Turning Movement

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Left turn	0	0	0	0	1	1	7	21
No-turn	3	1	4	2	4	14	93	74
Total Accidents	3	1	4	2	5	15	100	100

Table 51. Vehicle Turning Movement (Accident Case Identifier)

Description	Accident Case Identifier
Left turn	09022866
No-turn	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09007102, 07035239, 09009010

1.27 Weather Condition

The main prevailing atmospheric conditions that existed at the time of the accident.

Table 52. Weather Condition

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
Clear	2	1	1	0	4	8	53	62
Cloudy	1	0	2	1	0	4	27	24
Rain	0	0	0	1	0	1	7	10
Snow	0	0	1	0	1	2	13	3
Total Accidents	3	1	4	2	5	15	100	100

Table 53. Weather Condition (Accident Case Identifier)

Description	Accident Case Identifier
Clear	09025686, 05016829, 06033692, 09018209, 05015225, 09022866, 07035239, 09009010
Cloudy	07032651, 08028349, 07029580, 05019838
Rain	08012845
Snow	07011166, 09007102

1.28 Work Zone Related

Indicates whether the accident occurred in or near a construction, maintenance, or utility work zone, whether workers were actually present at the time of the accident or not. Work zone related accidents include those involving vehicles slowed or stopped because of the work zone, even if the first harmful event was before the first warning sign. MMUCC has additional subfields related to this data item that are not included in this format.

Table 54. Work Zone Related

Description	2005	2006	2007	2008	2009	Total	Observed Percent	Average Percent
No	3	1	4	2	5	15	100	98
Total Accidents	3	1	4	2	5	15	100	100

Table 55. Work Zone Related (Accident Case Identifier)

Description	Accident Case Identifier
No	07032651, 09025686, 05016829, 06033692, 07011166, 08028349, 07029580, 05019838, 09018209, 08012845, 05015225, 09022866, 09007102, 07035239, 09009010

2. Route SR S0000120 __, Milepost 22.53 to 22.982

Roadway Segment

Segment ID: 2697
Internal Segment ID: S15963
Route Number Display Value: SRS0000120 __
Site Subtype: Seg/Urb; Multilane undivided
Start Location: 22.53
End Location: 22.982
GIS Identifier: 2697
Next Roadway Segment ID: S1397
Previous Roadway Segment ID: S9773
Next Intersection ID: I126
Previous Intersection ID: I1039
Segment Length: 0.4520 miles
Roadway Class Level 1: Minor arterial
Roadway Class Level 2: Minor arterial urban
Roadway Class Level 3: Urban multi-lane undivided
Number of Through Lanes - Combined: 4
Median Type Level 1: Undivided
Median Type Level 2: Undivided
Median Width: 0.00 feet
Access Control: No Access Control
Growth Factor: 1.0000
Growth Factor Source: Defaulted
Maximum AADT: 23,400 vehicles per day
Two-Way vs. One-Way Operation: Two-way road or street
Direction of Travel: Not applicable
Direction of Increasing Mileposts or Distances: Northbound
Interchange Influence Area on Mainline Freeway: No
Number of Accidents: 18

Geographic Description

Identifier: G927
Route Type: State route
Route Name: S0000120 __
Major Road Name: Route 120
County: GRAFTON
District: 2
City/Town: LEBANON
Jurisdiction: State maintained
Area Type: Urban

Table 56. Route SR S0000120 __, Milepost 22.53 to 22.982 Directional Attributes

Direction	Number of Through Lanes	Average Lane Width	Shoulder Type - Outside	Shoulder Type - Inside	Average Shoulder Width - Outside	Average Shoulder Width - Inside	Bikeway	Comment
Direction 1	2	12.00	Not applicable	Not applicable	0.00	0.00		
Direction 2	2	12.00	Not applicable	Not applicable	0.00	0.00		

Table 57. Route SR S0000120 __, Milepost 22.53 to 22.982 Annual Traffic

Year	AADT	Heavy Vehicles	Peak or Design Volume	Volume Source	Comment
2002	23,400			Growth Factor Applied	
2003	23,400			Growth Factor Applied	
2004	23,400			Growth Factor Applied	
2005	23,400			Growth Factor Applied	
2006	23,400			Growth Factor Applied	
2007	23,400			Growth Factor Applied	
2008	23,400			Growth Factor Applied	
2009	23,400			Measured	

3. Accident Case Details

Accident Details: Accident Case ID: 07032651

Accident

Accident ID: 07032651

Internal Accident ID: A93154

Inventory Element: S15963

Location: 22.9568

GIS Identifier: 07032651

Accident Date: 2007/11/13

Accident Month: November

Accident Time of Day: 0747

Accident Date Stamp: 11/13/07 07:47:00

Accident Year: 2007

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Cloudy

Roadway Surface Condition: Wet

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Tuesday

Table 58. Accident 07032651 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1984/08/23	23
Vehicle 2	Northbound	Slowing	Unknown vehicle configuration	Motor vehicle in transport	1959/03/06	48

Accident Details: Accident Case ID: 09025686

Accident

Accident ID: 09025686

Internal Accident ID: A139593

Inventory Element: S15963

Location: 22.72

GIS Identifier: 09025686

Accident Date: 2009/10/13

Accident Month: October

Accident Time of Day: 1533

Accident Date Stamp: 10/13/09 15:33:00

Accident Year: 2009

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Daylight

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision

Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn

Day of Week: Tuesday

Table 59. Accident 09025686 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1969/08/30	40
Vehicle 2	Southbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1950/12/30	58

Accident Details: Accident Case ID: 05016829

Accident

Accident ID: 05016829

Internal Accident ID: A36067

Inventory Element: S15963

Location: 22.8877

GIS Identifier: 05016829

Accident Date: 2005/06/10

Accident Month: June

Accident Time of Day: 0800

Accident Date Stamp: 06/10/05 08:00:00

Accident Year: 2005

Accident Severity Level 1: Property-Damage-Only

Number of Fatalities: 0

Number of Non-Fatal Injuries: 0

Relationship to Junction: Non-junction

Driveway Indicator: No

Light Condition: Unknown

Weather Condition: Clear

Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Collision with animal

Contributing Circumstances, Environment: Animal(s) in roadway

Contributing Circumstances, Road: Unknown

School Bus Related: Unknown

Work Zone Related: No

Number of Vehicles Involved: 1

Alcohol/Drug Involvement: Neither alcohol nor other drugs

Tow-Away Indicator: Unknown

Run-Off Road Indicator: No

Pedestrian Indicator: No

Bicycle Indicator: No

Divided Highway Flag-Side of Road: Unknown

Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 60. Accident 05016829 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Animal	1978/11/14	26
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Animal		

Accident Details: Accident Case ID: 06033692

Accident

Accident ID: 06033692
 Internal Accident ID: A70179
 Inventory Element: S15963
 Location: 22.72
 GIS Identifier: 06033692
 Accident Date: 2006/12/14
 Accident Month: December
 Accident Time of Day: 2341
 Accident Date Stamp: 12/14/06 23:41:00
 Accident Year: 2006
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with animal
 Contributing Circumstances, Environment: Animal(s) in roadway
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No

Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 61. Accident 06033692 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Sport utility vehicle	Animal	1979/08/07	27
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Animal		

Accident Details: Accident Case ID: 07011166

Accident

Accident ID: 07011166
 Internal Accident ID: A77992
 Inventory Element: S15963
 Location: 22.5325
 GIS Identifier: 07011166
 Accident Date: 2007/04/05
 Accident Month: April
 Accident Time of Day: 0525
 Accident Date Stamp: 04/05/07 05:25:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Snow
 Roadway Surface Condition: Snow
 Accident Type and Manner of Collision: Collision with fixed object
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown

Run-Off Road Indicator: Yes
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 62. Accident 07011166 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Other traffic barrier	1954/08/21	52
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Other traffic barrier		

Accident Details: Accident Case ID: 08028349

Accident

Accident ID: 08028349
 Internal Accident ID: A110812
 Inventory Element: S15963
 Location: 22.953
 GIS Identifier: 08028349
 Accident Date: 2008/11/11
 Accident Month: November
 Accident Time of Day: 0839
 Accident Date Stamp: 11/11/08 08:39:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2

Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 63. Accident 08028349 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1979/12/25	28
Vehicle 2	Northbound	Slowing	Sport utility vehicle	Motor vehicle in transport	1959/12/20	48

Accident Details: Accident Case ID: 07029580

Accident

Accident ID: 07029580
 Internal Accident ID: A90581
 Inventory Element: S15963
 Location: 22.9473
 GIS Identifier: 07029580
 Accident Date: 2007/10/24
 Accident Month: October
 Accident Time of Day: 1930
 Accident Date Stamp: 10/24/07 19:30:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-not lighted
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with animal
 Contributing Circumstances, Environment: Animal(s) in roadway
 Contributing Circumstances, Road: None
 School Bus Related: Unknown

Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Wednesday

Table 64. Accident 07029580 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Passenger car	Animal	1953/12/25	53
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Animal		

Accident Details: Accident Case ID: 05019838

Accident

Accident ID: 05019838
 Internal Accident ID: A36519
 Inventory Element: S15963
 Location: 22.9729
 GIS Identifier: 05019838
 Accident Date: 2005/06/02
 Accident Month: June
 Accident Time of Day: 0920
 Accident Date Stamp: 06/02/05 09:20:00
 Accident Year: 2005
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Cloudy
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None

Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 65. Accident 05019838 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1945/12/27	59
Vehicle 2	Southbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1971/06/02	34

Accident Details: Accident Case ID: 09018209

Accident

Accident ID: 09018209
 Internal Accident ID: A133024
 Inventory Element: S15963
 Location: 22.5969
 GIS Identifier: 09018209
 Accident Date: 2009/08/03
 Accident Month: August
 Accident Time of Day: 1649
 Accident Date Stamp: 08/03/09 16:49:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry

Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 66. Accident 09018209 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Overtaking/passing	Other	Motor vehicle in transport	1968/02/01	41
Vehicle 2	Southbound	Stopped in traffic	Sport utility vehicle	Motor vehicle in transport	1951/09/01	57

Accident Details: Accident Case ID: 08012845

Accident

Accident ID: 08012845
 Internal Accident ID: A104476
 Inventory Element: S15963
 Location: 22.6036
 GIS Identifier: 08012845
 Accident Date: 2008/04/28
 Accident Month: April
 Accident Time of Day: 1140
 Accident Date Stamp: 04/28/08 11:40:00
 Accident Year: 2008
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight

Weather Condition: Rain
 Roadway Surface Condition: Wet
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 67. Accident 08012845 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1955/01/07	53
Vehicle 2	Northbound	Slowing	Passenger car	Motor vehicle in transport	1965/02/10	43

Accident Details: Accident Case ID: 05015225

Accident

Accident ID: 05015225
 Internal Accident ID: A35990
 Inventory Element: S15963
 Location: 22.5685
 GIS Identifier: 05015225
 Accident Date: 2005/04/05
 Accident Month: April
 Accident Time of Day: 1447
 Accident Date Stamp: 04/05/05 14:47:00
 Accident Year: 2005
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction

Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Tuesday

Table 68. Accident 05015225 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Sport utility vehicle	Motor vehicle in transport	1920/08/05	84
Vehicle 2	Southbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1957/06/25	47

Accident Details: Accident Case ID: 09022866

Accident

Accident ID: 09022866
 Internal Accident ID: A130277
 Inventory Element: S15963
 Location: 22.9767
 GIS Identifier: 09022866
 Accident Date: 2009/08/30
 Accident Month: August
 Accident Time of Day: 1700
 Accident Date Stamp: 08/30/09 17:00:00
 Accident Year: 2009
 Accident Severity Level 1: Non-Incapacitating Injury
 Number of Fatalities: 0

Number of Non-Fatal Injuries: 1
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: Left turn
 Day of Week: Sunday

Table 69. Accident 09022866 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Turning left	Light truck, only four tires	Motor vehicle in transport	1971/06/21	38
Vehicle 2	Eastbound	Turning left	Passenger car	Motor vehicle in transport	1950/01/25	59

Accident Details: Accident Case ID: 09007102

Accident

Accident ID: 09007102
 Internal Accident ID: A121208
 Inventory Element: S15963
 Location: 22.72
 GIS Identifier: 09007102
 Accident Date: 2009/03/09
 Accident Month: March
 Accident Time of Day: 0956
 Accident Date Stamp: 03/09/09 09:56:00
 Accident Year: 2009

Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Snow
 Roadway Surface Condition: Snow
 Accident Type and Manner of Collision: Other multiple-vehicle collision
 Contributing Circumstances, Environment: Weather conditions
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 2
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Monday

Table 70. Accident 09007102 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Passenger car	Motor vehicle in transport	1952/04/26	56
Vehicle 2	Northbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1979/03/22	29

Accident Details: Accident Case ID: 07035239

Accident

Accident ID: 07035239
 Internal Accident ID: A93657
 Inventory Element: S15963
 Location: 22.9284
 GIS Identifier: 07035239
 Accident Date: 2007/11/30
 Accident Month: November
 Accident Time of Day: 0211

Accident Date Stamp: 11/30/07 02:11:00
 Accident Year: 2007
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Dark-lighted
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Collision with fixed object
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 1
 Alcohol/Drug Involvement: Yes (alcohol)
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: Yes
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Friday

Table 71. Accident 07035239 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Southbound	Movements essentially straight ahead	Passenger car	Embankment	1981/06/28	26
Vehicle 2	Unknown	Unknown	Unknown vehicle configuration	Embankment		

Accident Details: Accident Case ID: 09009010

Accident

Accident ID: 09009010
 Internal Accident ID: A124326
 Inventory Element: S15963
 Location: 22.8877
 GIS Identifier: 09009010
 Accident Date: 2009/03/19

Accident Month: March
 Accident Time of Day: 0747
 Accident Date Stamp: 03/19/09 07:47:00
 Accident Year: 2009
 Accident Severity Level 1: Property-Damage-Only
 Number of Fatalities: 0
 Number of Non-Fatal Injuries: 0
 Relationship to Junction: Non-junction
 Driveway Indicator: No
 Light Condition: Daylight
 Weather Condition: Clear
 Roadway Surface Condition: Dry
 Accident Type and Manner of Collision: Rear-end
 Contributing Circumstances, Environment: None
 Contributing Circumstances, Road: None
 School Bus Related: Unknown
 Work Zone Related: No
 Number of Vehicles Involved: 3
 Alcohol/Drug Involvement: Neither alcohol nor other drugs
 Tow-Away Indicator: Unknown
 Run-Off Road Indicator: No
 Pedestrian Indicator: No
 Bicycle Indicator: No
 Divided Highway Flag-Side of Road: Unknown
 Vehicle Turning Movement: No-turn
 Day of Week: Thursday

Table 72. Accident 09009010 Vehicle-Level Accident Data

Vehicle ID	Initial Direction of Travel	Vehicle Maneuver/Action	Vehicle Configuration	First Harmful Event	Driver Date of Birth	Driver Age
Vehicle 1	Northbound	Movements essentially straight ahead	Light truck, only four tires	Motor vehicle in transport	1947/03/14	62
Vehicle 2	Northbound	Stopped in traffic	Passenger car	Motor vehicle in transport	1981/07/06	27